District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised April 3, 2017

Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company Devon Energy Production Co LP (6137) Contact Stephen Richards, Devon Water Foreman Address 6488 Seven Rivers Hwy Artesia, NM 88210 Telephone No. 575-252-3717 Facility Name Billiken 7 Fed 1H Facility Type Oil Well Surface Owner Federal Mineral Owner Federal API No. 30-025-42687 LOCATION OF RELEASE Feet from the North/South Line Feet from the East/West Line Unit Letter Section Township Range County M 12 34E South East **Latitude** 32.050688 N **Longitude**-103.429337 W NATURE OF RELEASE Type of Release Volume of Release Volume Recovered Produced Water 150 barrels 100 barrels Source of Release Date and Hour of Occurrence Date and Hour of Discovery Lay Flat Line 4/20/17, 2:10 PM 4/20/17, 2:10 PM Was Immediate Notice Given? If YES, To Whom? BLM: Shelly Tucker OCD: Olivia Yu By Whom? Date and Hour Brett Fulks, EHS Professional BLM: 4/20/17, 7:35 PM OCD: 4/20/17, 7:30 PM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No **APPROVED** If a Watercourse was Impacted, Describe Fully.* N/A By Olivia Yu at 9:42 am, Nov 16, 2018 Describe Cause of Problem and Remedial Action Taken.* While transferring produced water from a frac pond to the location, the Booster pump #2 over pressured and the lay flat hose ruptured. A 2 inch hole developed and released produced water on the ground. The pump was shut down and the hose was repaired. Describe Area Affected and Cleanup Action Taken.* The spill area affected is approximately 40' x 20' running East and West beginning about 100 feet West of the Ragin Cajun 12 Fed #3H wellpad. A central location of the spill is Lat - 32.050688 N, Long - -103.429337 W and is approximately 0.85 miles Southwest from the Billiken 7 Fed #1H wellpad. An estimated 150 barrels of treated produced water was spilled, a vacuum truck was dispatched, and 100 barrels was recovered. Etech Environmental & Safety Solutions mobilized personnel to the site to conduct a site assessment and vertical/horizontal delineation of the impacted area. Remediation of the impacted soil was carried out in accordance to the NMOCD and BLM guidelines and stipulations. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Michael R. Shoemaker Approved by Environmental Specialist: Printed Name: Michael Shoemaker 11/16/2018 xx/xx/xxxx Approval Date: Expiration Date: Title: Environmental Professional E-mail Address: mike.shoemaker@dvn.com Conditions of Approval: Attached BLM approval required. Date: 08/14/18 Phone: 575-748-3371

^{*} Attach Additional Sheets If Necessary