Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1 – (575) 393-6161 Ene	ergy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240BBS OCD District II – (575) 748-1283		30-025-40816
		5. Indicate Type of Lease
811 S. First St., Artesia, NM 88210 <u>District III</u> ~ (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87 DEC 17 201 District W. (506) 476 476	2 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 874 00-V District IV ~ (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francia Dr. Santa Fa. NM		
87505		
SUNDRY NOTICES AND		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO D DIFFERENT RESERVOIR. USE "APPLICATION FO		North Hobbs (G/SA) Unit
PROPOSALS.)		8. Well Number 831
1. Type of Well: Oil Well 🛛 Gas Well	1 Dther	
2. Name of Operator		9. OGRID Number: 157984
Occidental Permian Ltd.		$10 \text{Destruction} W^{1}_{1} = 0 \text{Helps} (C/CA)$
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
2611 Plains Hwy, Denver City, TX 79323		
4. Well Location		
Unit LetterK_:1835fee	et from theSouth line and1435_	feet from theEastline
Section 13	Township 18S Range 371	
11. Ele	vation (Show whether DR, RKB, RT, GR, etc.	
3660.8	GL	
12. Check Appropri	iate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION		SEQUENT REPORT OF:
—		
—	GE PLANS	
		I JOB
OTHER: Intitial Completion	OTHER:	
		<i>"</i>
		d give pertinent dates, including estimated date
13. Describe proposed or completed oper	rations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
13. Describe proposed or completed oper	rations. (Clearly state all pertinent details, an CRULE 19.15.7.14 NMAC. For Multiple Co.	
13. Describe proposed or completed oper of starting any proposed work). SEE	rations. (Clearly state all pertinent details, an CRULE 19.15.7.14 NMAC. For Multiple Co.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 13. Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletion 1) Drill Out DV tool and Float Collar to 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletion Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 4) RIH with ESP 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletion Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 4) RIH with ESP 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 4) RIH with ESP 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 4) RIH with ESP 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 4) RIH with ESP 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. RIH with ESP Turn well to production 	rations. (Clearly state all pertinent details, an C RULE 19.15.7.14 NMAC. For Multiple Co n. 0 4371' 1338-50', 4365-68'	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. 4) RIH with ESP 	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co n.	
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. RIH with ESP Turn well to production 	rations. (Clearly state all pertinent details, an C RULE 19.15.7.14 NMAC. For Multiple Co n. 0 4371' 1338-50', 4365-68'	
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletior 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production 	Rig Release Date:	mpletrons: Attach wellbore diagram of
 Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletior Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 Acid treat with 3000 gal. RIH with ESP Turn well to production 	Rig Release Date:	mpletrons: Attach wellbore diagram of
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletior 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production 	Rig Release Date:	mpletrons: Attach wellbore diagram of
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletior 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production Spud Date:	rations. (Clearly state all pertinent details, an C RULE 19.15.7.14 NMAC. For Multiple Conn. 0.4371' 0.4371' 1338-50', 4365-68' Rig Release Date: rue and complete to the best of my knowledg	mpletions: Attach wellbore diagram of
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletior 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production 	Rig Release Date:	mpletrons: Attach wellbore diagram of
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production Spud Date: I hereby certify that the information above is t SIGNATURE	rations. (Clearly state all pertinent details, an C RULE 19.15.7.14 NMAC. For Multiple Con. 0.4371' 0.4371', 1338-50', 4365-68' Rig Release Date: rue and complete to the best of my knowledg TITLE_ Lift Specialist	mpletions: Attach wellbore diagram of
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production Spud Date: I hereby certify that the information above is t SIGNATURE Store Snead Type or print name Steve Snead	rations. (Clearly state all pertinent details, an C RULE 19.15.7.14 NMAC. For Multiple Con. 0.4371' 0.4371', 1338-50', 4365-68' Rig Release Date: rue and complete to the best of my knowledg TITLE_ Lift Specialist	mpletions: Attach wellbore diagram of
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production Spud Date: I hereby certify that the information above is t SIGNATURE	rations. (Clearly state all pertinent details, an C RULE 19.15.7.14 NMAC. For Multiple Con. 0.4371' 0.4371', 1338-50', 4365-68' Rig Release Date: rue and complete to the best of my knowledg TITLE_ Lift Specialist	mpletions: Attach wellbore diagram of
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production Spud Date: I hereby certify that the information above is t SIGNATURE Steve Snead For State Use Only Wald Wald Wald Wald Wald Wald Wald Wald	rations. (Clearly state all pertinent details, an C. RULE 19.15.7.14 NMAC. For Multiple Conn. 0.4371' 0.4371' 1338-50', 4365-68' Rig Release Date:	mpletions: Attach wellbore diagram of e and belief. DATE12/10/12 xy.com PHONE:806-592-6312 p
 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 1) Drill Out DV tool and Float Collar to 2) Perforate from 4282-90', 4326-30', 4 3) Acid treat with 3000 gal. 4) RIH with ESP 5) Turn well to production Spud Date: I hereby certify that the information above is t SIGNATURE Store Snead Type or print name Steve Snead	rations. (Clearly state all pertinent details, an C. RULE 19.15.7.14 NMAC. For Multiple Conn. 0.4371' 0.4371' 1338-50', 4365-68' Rig Release Date:	mpletions: Attach wellbore diagram of