Oil Well

Gas Well

Form 3160-5

1. Type of Well

(March 2012) 5 2013

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

MAR 1 5 2013

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No.

NMLC063458 6. If Indian, Allottee or Tribe Name

## CEIVED SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Other

7. If Unit of CA/Agreement,	Name and/or No.	
8. Well Name and No. Warren Unit 148		
9. API Well No.		

2. Name of Operator ConocoPhillips Company 3b. Phone No. (include area code) 30-025-35772 10. Field and Pool or Exploratory Area 3a. Address P. O. Box 51810 Midland TX 79710 (432)688-9174

Warren Blinebry-Tubb-Drinkard

11. County or Parish, State Location of Well (Footage, Sec., T.R., M., or Survey Description) UL M, 490' FSL & 400' FWL, Sec 25, 20S, 38E Lea

SUBMIT IN TRIPLICATE – Other instructions on page 2.

NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION -						
X Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity			
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	Other			
Final Abandonment Notice	Convert to Injection	X Plug Back	Water Disposal	·			

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

ConocoPhillips Company respectfully request to Plug back the Abo (15200) by setting a CIBP @ 7350' and spotting 35' of cmt on top of BP.

Attached is the procedure and proposed Wellbore schematic.

Surface disturbance beyond the originally approved pad must have prior

approval. Closed loop system required.

Operator to have H2S monitoring equipment on location Submit the BLM Form 3160-4 Recompletion Report within 30 days of the date

all BLM approved procedures are complete.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Rhonda Rogers	Title Staff Regulatory Technician
Signature Monde Sucus	Date 02/12/2013 APPROVE
THIS SPACE FOR FEE	DERAL OR STATE OFFICE USE SP 3 7 2013
Approved by	Title Date DATE SICE
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	or certify would Office  BUREAU OF LANGE DUTTER  BUREAU OF LANGE DUTTER  CARLSBAD FIELD UTTER  201
Title 18 II S.C. Section 1001 and Title 43 II S.C. Section 1212 make it a crime for any	y nervon knowingly and willfully to make to any department or agency of the United States any falce

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)



#### **WARREN UNIT 148**

API #30 025 35772

Location: UL M, 490' FSL & 400' FWL

Sec 25. 20S, 38E

Lea County, New Mexico

However, consolidation effort for a number of the WARREN B/T wells was done and became effective effective 11-1-12. Which rendered previous down hole commingle authorization for this well expired.

It was then deemed necessary to shut in the well and test the ABO formation by isolating it with a bridge plug set @ 6916' and testing Blinebry and Tubb horizons. This operation was done in 1/14/2013.

Based on the results of the above operations and test of the upper horizons (Blinebry/ Tubb) it was determined that Abo formation was not longer contributing production wise. Hence, becoming not economic to produce.

It is then the purpose of this proposed well work to abandon the ABO Formation completed in the interval from 7406-7518' and produce the B/T horizons.

### WELL CATEGORY, BOP CLASS AND EXCEPTIONS

Well Category One:

H2S:

0 ppm.

Well Rate:

H2S

ROE-ft.

100 ppm

n

500 ppm

0

BOPE Class One: Hydraulic BOP w/ hydril.

Well control for this well will be Class 1, Category 1: manual BOP (hydraulic BOP recommended); 1 un-tested barrier.

#### **PROCEDURE**

1. MI & RU well service unit. The following is a summary of current well configuration:

SEMU-134 (API: 30-025-3438200)			
Elev.: 3511 KB; 3522	Depth	: RKB	
	top	btm	
8-5/8", 24#, J-55 , 12 ¼" hole	surface	1757	1.02 : Cemented with 222 bbls class C cement followed by 48 bbls of class C cement + 2 % Cacl2 . Displaced with water. Circulated 50 bbls to pit.
5 1/2", 17# , L80 (8-3/4"" hole)	surface	7702	03.02: Cmt w/ 880 sks of C cement followed by tail slurry of 495 sxs of class C cement. Circulated 70 bbls/163 of cement to pit. TOC surface
5 1/2", 17# , J55 (8-3/4"" hole)			
TD: 7702			
Completion Interval: Bottom To top			<u> </u>
Perforated Interval Abo	7406	7518	05.02: Perforated @ 2 spf.
Perforated Interval Tubb	6584	6766	05.02: Perforated @ 2 spf

Perforated Interval Blinebry	6026	6192	05.02: Perforated @ 2 spf	

- 2. Unseat pump. POOH w/ rods & pump.
- 3. Pump 40 barrels of 10# brine down tubing-casing annulus. Circulate bottoms up
- **4.** ND Wellhead.NU hydril BOP. Rig down floor and tongs. RU HOT Oiler. Pump 70 bbls of hot water with 3 gallons of WRH/211, 5 gallons of M153 and 1.5 Gallons of Biocide.
- 5. RD hot oiler. RU scanning services.
- **6.** POOH w/ 2-7/8", 6.50#, J55 production tbg. (If deemed necessary production tubing can be used as WS). RD scanning services. RU tubing testers.
- **7.** PU Retrieving tool. RIH with retrieving tool on WS. Latch on to RBP. Release RBP. POOH with RBP. LD RBP.
- 8. PU & RIH with 5 1/2" CIBP and on WS. Set CIBP @ 7350 (56' above top Abo Perf).
- 9. Spot 35 ft of cement on top of CIBP. If bailer is to be used a depth tagging is required.
- 10. POOH with WS.
- **11.** RIH w/ 2-7/8" production tbg. ND BOP. NU wellhead. RIH w/ pump & rods exactly the same it was. No change in rod string design .Space out pump. Load test to 550. Hang well on.
- **12.** RDMO and clean out location before departure.
- **13.** Return well to production. Submit record of plug and cement cap depths to regulatory for filling.

# WARREN UNIT 148 API # 30-025-35772 Sec 25, T 20S, R38E, LEA County , NM

Ground Elevation: 3570 KB/RT Elevation: 3581 CASING CONFIGURATION 8 5/8", 24# , J55 , Hole Size: 12 1/4 , Set @ 1757, Cemented with 270 BBIs of class C cement 13.2 ppg circulated to Surface 5-1/2", 15.5# & 17#, L80 , Hole Size: 8 3/4", Set @ 7702, Cemented w/ 1295 sks C neat Cement. TOC @ surface **BLINEBRY Perforations** 6026-6192 @ 2 SPF 05.02 6584-6766 @ 2 SPF 05.02 **TUBB Perforations** RBP @ 6916' 01.10.2013 ( to be Removed ) 35 ft of Cement on top of CIBP. (Tag Reqired) CIBP @ 7350 (56' Above top Abo Perf) 7406-7518 @ 2 SPF 05.02 **ABO** Perforations Proposed TD:7702