Form 316Q-5 **UNITED STATES** FORM APPROVED HOBBS OCD **OCD** Hobbs (August 2007) OMB NO. 1004-0135 DEPARTMENT OF THE INTERIOR Expires: July 31, 2010 BUREAU OF LAND MANAGEMENT Lease Serial No. APR SUNDRY NOTICES AND REPORTS ON WELLS NMNM02391 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on reverse side. 1. Type of Well Well Name and No MESCALERO RIDGE UNIT 211 ☑ Oil Well ☐ Gas Well ☐ Other Name of Operator API Well No. NANCY FITZWATER Contact: LINN OPERATING INC 30-025-02391 E-Mail: nfitzwater@linnenergy.com 10. Field and Pool, or Exploratory
QUAIL RIDGE;BONE SPRING 3b. Phone No. (include area code) 3a. Address 600 TRAVIS ST., SUITE 5100 Ph: 281-840-4266 HOUSTON TX 77002 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 21 T19S R34E Mer NMP 660FNL 660FWL LEA COUNTY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION □ Acidize Deepen ☐ Production (Start/Resume) ■ Water Shut-Off ■ Notice of Intent ■ Well Integrity ☐ Alter Casing □ Fracture Treat ☐ Reclamation ■ Subsequent Report Casing Repair ■ New Construction Recomplete □ Other ☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon ☐ Convert to Injection ☐ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) LINN REQUESTS APPROVAL TO SQUEEZE BONE SPRING PERFORATIONS F/10118 T/10134 AND RECOMPLETE TO A LOWER BONE SPRING FORMATION F/10766 T/10794 W/2 SPF. COMPLETE DETAILS ATTACHED INCLUDING CURRENT WELLBORE SCHEMATIC. SEE ATTACHED FOR CONDITIONS OF APPROVAL 14. I hereby certify that the foregoing is true and correct Electronic Submission #200628 verified by the BLM Well Information System For LINN OPERATING NC, sent to the Hobbs NANCY FITZWATER Name (Printed/Typed) SUPERVISOR (Electronic Submission) 03/05/2013 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Approved By

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Title

Office

BUREAU OF LAND

MRU #21-1

LEA COUNTY, NM

30-025-02391

02/20/2013

Project Scope: Squeeze 2nd Bone Spring perfs and recomplete deeper 3rd Bone Spring

Procedure:

- 1. Test anchors prior to rigging up.
- 2. MIRU PU and record casing and tubing pressure.
- 3. Bleed pressure off of well.
- 4. NU BOP.
- 5. TOOH with pump, rods and tubing.
- 6. RU Cement Company.
- 7. RIH with cement retainer and workstring.
- 8. Set cement retainer. Set retainer @ 10,058 per matt Lake
 9. Sting out of retainer.
 1505x cluss H cement 4/16/13
- 10. Circulate cement to bottom of tubing.
- 11. Sting into retainer and continue with cement squeeze.
- 12. Sting out of retainer.
- 13. Reverse circulate to clean tubing.
- 14. POOH with tubing.
- 15. RIH with workstring and bit and drill out to 10,150.
- 16. Pressure up and hold to ensure cement squeeze integrity.
- 17. If pass, drill out to 13,079'.
- 18. POOH with workstring and bit.
- 19. RIH with bit and scraper.
- 20. POOH with workstring and bit.
- 21. Run CBL on wireline over 9150' 13079'.
- 22. Perforate on wireline 10,766' 10,794' @ 2 spf.
- 23. RIH with L-80 2 7/8" workstring and packer.
- **24. ND BOP**
- 25. NU Wellhead.
- 26. RDMO PU.
- 27. RU Tree saver.

Contact Information:

Matt Lake - Asset Engineer Cell - 713-263-4933 Office - 281-840-4088

Bob Akin - Foreman Cell - 575-390-8007

- 28. RU Frac Company, frac equipment and flow back equipment.
- 29. Conduct mini-frac.
- 30. Acidize and frac single stage in 3rd Bone Spring.
- 31. RD frac company and frac equipment.
- 32. Flow back well or swab as needed to evaluate.
- 33. Contact engineer to discuss next steps.

Contact Information:

airrent

Proposed Wellbore Schematic Well Name: Mescalero Ridge Unit 211 Date Prepared: M. Lake 20-Feb-13 Location: D-21-19S-34E 660 FNL 660 FWL Last Updated: Spud Date: 9-May-61 API#: 30-025-02391 RR Date: Spud Date to RR Date: Elevations: GROUND: Completion Start Date: KB: Completion End Date: Depths (KB): PBTD: Completion Total Days: Co-ordinates: TD 13430 Surface Casing (5/10/61): All depths KB Surf Csq Bit 17-1/2" 27 Jts (814.33') of 13-3/8", 54.5# 13-3/8" Cmt w/ 900 sx regular cmt w/ 2% Calcium Chloride Cmt circ to surf Set @839' Cmt circ to surf-Intermediate Casing (5/30/61): 183 Jts (5543.25') of 9-5/8", N-80, 40# Cmt in two stages (Stage collar at 3277') Stage 1: 1230 sx 50-50 Pox mix w/ 2% gel circulated Stage 2: 1740 sx 50-50 POZ w/ 6% Gel and 29# saturated salt per sack. Cmt circ to surf. Production Casing (9/1/61): 386 Jts (13,689.88') of 7" 32# set @ 13,709' Cmt in two stages (Stage collar at 10,215') Stage 1: 500 sx Inferno Slo Set Stage 2: 200 sx Infermo Slo Set TOC @ 9150' (CBL on 9/6/61), Length (ft) Intermediate Csq 323 jts 2 7/8" tbg 9-5/8 2 7/8" x 5 1/2" TAC Set @ 5522' 5 jts 2 7/8" tbg 2 1/2" x 2 1/4" x 24' tbg pump Cmt Circ to Surf 4' 2 7/8" perf sub 1 jt 2 7/8" tbg 1 BP Tubing Set @ ~ Rods Length (ft) 1 1/2" x 26' PR 26.00 6' 7/8" pony rod 6.00 4' 7/8" pony rod 4.00 164 7/8" rods 4100.00 233 3/4" rods Bone Spring 5825.00 10,118-10,134' (sqzd 8 1/2" k-bars 200 10,118-10,134 794) (11/12/66)O 6 sx cmt on top of sand 16 sx sand on top TOC plug @ 13079' Tbg Cut @ 13161' Perforations: 13,495 13,505' w/ 4 SPF (9/4/61) - Sqz'd w/ 25 sx Trinity Inferno Slo set (20 sx into perfs) Model D Pkr @ 13325' - Resqueezed w/ 25 sx trinity inferno slow set w/ 8% Halad-9 (9/8/61) Production Csq Morrow 13495-13498' w. 4 SPF (9/9/61) - Sqzd w/ 50 sx trinity Inferno Slo Set o 13328-13340 0 13328-13340' w/ 4 SPF (9/11/61) - 13,150 gal of 5% MSA (Acetic Acid) Set @ 13,709' and 500 lbs WAC-9 Fluid loss, 400 lbs W-9 Gel agent @ 5 BPM and max PSI of 9800 TOC @ 9150' (CBL) e 13495-13498 10,118-10,134' w/ 4 SPF (9/16/61) - Pumped 12,000 cf of N2 ahead of acid. 13498-13505 Acid frac w/ 3000 gal DS-50 (no sand). Max PSI of 6500 psi, AIP 2500 psi, AIR 1 BPM.

PBTD @ 13430'

Mescalero Ridge Unit 21-1 30-025-02391 LINN Operating Inc April 17, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by July 17, 2013.

- 1. The operator shall dump bail 35' of neat class H cement on top of the cement/sand above the CIBP. Tag required.
- 2. Operator shall place a balanced cement plug from 12860'-12630' to seal off the Morrow formation.
- 3. Operator shall place a balanced cement plug from 10925'-10715' to seal off the Wolfcamp formation.
- 4. For squeeze- pressure test must be 500 psi for 30 minutes.
- 5. A CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h and results submitted to the BLM.
- 6. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 7. Surface disturbance beyond the originally approved pad must have prior approval.
- 8. Closed loop system required.
- 9. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 10. Operator to have H2S monitoring equipment on location.

- 11. A minimum of a 5000 (5M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (5M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 12. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 041713

.