
Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resour	rces Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District W = (575) 748-1283	20 025-23643
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 535 OCD District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 2 0 2013 District IV – (505) 476-3460 MAY 2 0 2013 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	K362
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	Haunis State
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well Gas Well Other	8. Well Number 3℃
2. Name of Operator	9. OGRID Number 16696
OXY USA Inc.	10.70
3. Address of Operator P.O. Box 50250 Midland, TX 79710	10. Pool name or Wildcat
	Mescaleno San Andres
4. Well Location	1 2215
_	and 2310 feet from the east line
Section 23 Township (OS Range 32	
11. Elevation (Show whether DR, RKB, RT,	GR, etc.)
7)(7	
12. Check Appropriate Box to Indicate Nature of N	Notice Report or Other Data
12. Check Appropriate Box to indicate Nature of 1	totice, report of other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	AL WORK ALTERING CASING
	NCE DRILLING OPNS. P AND A
	CEMENT JOB 💮
DOWNHOLE COMMINGLE	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent de	etails, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1. NMAC. For Mul	etails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent de	etails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1. NMAC. For Mul	etails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion.	tiple Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Pool of the proposed completion.	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power of the second of the s	tiple Completions: Attach wellbore diagram of OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Pool of the proposed completion.	tiple Completions: Attach wellbore diagram of OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power and the description of the completion of the complete of the	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power of the description of the state	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power and the description of the completion of the complete of the	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power of the description of the state	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power of the description of the state	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power of the description of the state	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P. @ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval.	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, Power of the description of the state	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P. @ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval.	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/RBP & pkr, set d csg to surf. POOH w/RBP & pkr. at @ 4154'. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P. @ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval.	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1. NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P. @ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date:	tiple Completions: Attach wellbore diagram of OOH w/tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was
13. Describe proposed or completed operations. (Clearly 8: ite all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P. @ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm. The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date:	nowledge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1. NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P. @ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date:	nowledge and belief.
13. Describe proposed or completed operations. (Clearly 5: ite all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P. @ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my k SIGNATURE TITLE Regulatory	OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was nowledge and belief. Advisor DATE S(3(1))
13. Describe proposed or completed operations. (Clearly F. de all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P@ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my k SIGNATURE TITLE Regulatory. Type or print name Level Shows E-mail address: david st	OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was nowledge and belief. Advisor DATE S(3(1))
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P@ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my k SIGNATURE TITLE Regulatory. Type or print name Describe proposed or completed operations. (Clearly state use of my labeled and starting a	OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was nowledge and belief. Advisor DATE 5(3(3) ewart@oxy.com PHONE: 432-685-5717
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P@ different interval to test csg, isolate csg lk bottom@ 1794' w/ baRIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf@ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my k SIGNATURE TITLE Regulatory. APPROVED BY TITLE DESCRIPTION.	OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was nowledge and belief. Advisor DATE S(3(1))
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P@ different interval to test csg, isolate csg lk bottom @ 1794' w/ ba RIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf @ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my k SIGNATURE TITLE Regulatory. Type or print name Describe proposed or completed operations. (Clearly state used and proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed to the set of my least state used and set in the middle of the perforated interval.	OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was nowledge and belief. Advisor DATE 5(3(3) ewart@oxy.com PHONE: 432-685-5717
13. Describe proposed or completed operations. (Clearly state all pertinent de of starting any proposed work). SEE RULE 19.15.7.1 NMAC. For Mul proposed completion or recompletion. RUPU 4/16/13, POOH w/ rods & pump, Rel TAC, NDWH, NU BOP, P@ different interval to test csg, isolate csg lk bottom@ 1794' w/ baRIH w/ CIBP & set @ 4197', dump bail 6sx cmt, POOH. RIH & tag cm The information the field had showed the top perf@ 4247' instead set in the middle of the perforated interval. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my k SIGNATURE TITLE Regulatory. APPROVED BY TITLE DESCRIPTION.	OOH w/ tbg. RIH w/ RBP & pkr, set d csg to surf. POOH w/ RBP & pkr. at @ 4154'. RDPU. of 4158', that is why the CIBP was nowledge and belief. Advisor DATE 5(3(3) ewart@oxy.com PHONE: 432-685-5717

OXY USA Inc. - Current Harris State #3Y API No. 30-025-23643



12-1/4" hole @ 382' 8-5/8" csg @ 382' w/ 200sx-TOC-Surf-Circ

Csg Llk @ 1794'

7-7/8" hole @ 4350' 4-1/2" csg @ 4350' w/ 200sx-TOC-3420'-TS

Perfs @ 4158-4258'

4/13-CIBP @ 4197' w/ 6sx