Form 3160-5 (March 2012)

# UNITED STATES DEPARTMENT OF THE INTERIOR DUBEAU OF LAND MANAGEMENT

••••

HOBBS OCD

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

MAYC2 A. 2013

Expires: October 3

BURE	5. Lease Serial No.	5. Lease Serial No. NMLC-031741A  6. If Indian, Allottee or Tribe Name  7. If Unit of CA/Agreement, Name and/or No. NMNM-116411  8. Well Name and No. West Blinebry Drinkard Unit (WBDU) #031 (37346)					
SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.							
SUBMIT	_						
1. Type of Well  Oil Well  Gas Well  Other					8. Well Name and No		
2. Name of Operator Apache Corporation (873)				9. API Well No.			
3a. Address 303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705  3b. Phone No. (include are 432/818-1062				10. Field and Pool or Exploratory Area Eunice; B-T-D, North (22900)			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. County or Parish, State				
2528' FNL & 1250' FWL UL E Sec 9 T21S R37E				Lea County, NM			
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICAT	E NATURE OF NO	OTICE, REPORT OR OTH	IER DATA		
TYPE OF SUBMISSION			TYPE OF A	ACTION			
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Tr	eat	Production (Start/Resume) Reclamation Recomplete	Water Shut-Off Well Integrity  ✓ Other ADD PERFS		
Subsequent Report	Change Plans	Plug and A	_	emporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal			
Attach the Bond under which the w following completion of the involve testing has been completed. Final a determined that the site is ready for Apache would like to add perforation	ed operations. If the operati Abandonment Notices must final inspection.)	on results in a multipl be filed only after all	e completion or reco requirements, includ nkard formations, p	ompletion in a new intervaling reclamation, have been also been attached.	, a Form 3160-4 must be filed a completed and the operator has been detected and the operator has been detected as a complete and the operator has been detected as a coperator has a complete and the operator has been detected as a co	once	
				SEE ATTACHE CONDITIONS	OF APPROVAL		
14. I hereby certify that the foregoing is tr	ue and correct. Name (Printe	d/Typed)					
Reesa Holland Fisher		Title	Sr. Staff Reg Te	ch		-	
Signature Rosa Holla	nd Fisher	Date	05/09/2013	APPI	ROVED		
	THIS SPACE	FOR FEDERAL	OR STATE C	OFFICE USE MAY	2 2 2012		

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title Office UPLAU OF LAND MANAGEMEN CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Approved by

MUSS 1000 7/16/2013

JUL 16 2018

#### **WBDU 31 Proposed Procedure**

#### Add perforations to, and acid stimulate the Blinebry and Drinkard formations

- **Day 1:** MIRU. POOH w/ rods and pump. Install BOP. Tag for fill and POOH w/ 2-7/8" tbg. RIH w/ 4-3/4" bit on 2-7/8" ws
- Day 2: Cont. RIH. Clean well out to +/- 6800' out as necessary. POOH. RIH w/scraper to +/-6750'
- Day 3: Cont. RIH w/scraper to +/-6750', POOH.

MIRU WL. Perforation depths based on a datum elevation of 3515' (KB elevation). Openhole logs with proposed perforations will be provided for correlation

Perforate the Drinkard from 6500-02', 27-29', 48-49', 52-53', 68-69', 6604-07', 08-10', 12-16', 34-37', 54-56', 73-75', 6698-6700' w/ 4 SPF, 90 deg phasing (25 ft, 100 shots)

Perforate the Blinebry from 5783-85', 5829-31', 86-88', 5972-73', 6052-53' w/ 4 SPF, 90 deg phasing (8 ft, 32 shots)

PU RIH w/ RBP and treating pkr

Day 4: Cont. RIH w/ RBP and treating pkr

Set RBP @ +/-6750'. Set pkr @ +/-6450'. Acidize the Drinkard w/6,900 gals 15% HCl-NE-FE BXDX acid and rock salt in three equal stages @ +/-10 BPM. Release pkr. Wash out salt. Release RBP

Re-set RBP @ +/-6240', set pkr @ +/-5750'. Acidize the Blinebry w/3,000 gals 15% HCl-NE-FE BXDX acid and rock salt in three equal stages @ +/-10 BPM. Release pkr. Wash out salt. Release RBP

POOH w/ 2-7/8" ws

Day 5: Cont. POOH w/ 2-7/8" ws. RIH w/ SN, 2-7/8" production tbg. ND BOP, set TAC, NU WH


Day 6: RIH w/ 1-1/2" pump and rods. Return well to production. Place well in test

### **Apache Corporation**

WBDU #31 (Hawk A #33)








## **Apache Corporation**

WBDU #31 (Hawk A #33)





## West Blinebry Drinkard Unit 31 30-025-38196 Apache Corporation May 22, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by August 22, 2013.

- 1. Must conduct a casing integrity test before any work can be done. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h. Submit results to the BLM.
- 2. If CIT does not fail work is approved as written.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.