HOBBS OCD

	. (2.102
Submit 3 Copies To Appropriate District JUL 1 9 2013 State of New Mexico Office District 1 Energy, Minerals and Natural Resources	Form C-103 June 19, 2008
District 1 Energy, wither are and Natural Resources 1625 N. French Dr., Hobbs, NM 8\$240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 8921 0 RECEIVED CONSERVATION DIVISION	30-025-08452 5. Indicate Type of Lease
1220 South St. Francis Dr.	STATE S FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
<u> </u>	E-1356 7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Ecase Name of Control Agreement Name
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Miller W State 8. Well Number
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	9. OGRID Number
Mack Energy Corporation	013837
3. Address of Operator	10. Pool Name or Wildcat
P.O. Box 960 Artesia, NM 88210	Vacuum;Grayburg San Andres
Unit Letter 1 2030 feet from the South line and	660 feet from the East line
Section 4 Township 17S Range 34E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIALWOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	
OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
Notify OCD 24 hours prior to starting plugging operations.	
1) Set CIBP @ 4650' w/35' cmt cap.	
2) Perforate @ 2890'	
3) Squeeze 30sx (Cover base of salt). WOC and Tag. 4) Perforate @ 1790'.	
5) Squeeze 95sx (Cover top of salt and 8 5/8 shoe). WOC and Tag. 6) Perforate @ 64! 50	
7) Circulate 🌉 coment from 🍪 to surface inside and outside of 8 5/8" casing.	
7) Install P & A marker.	
Note: Circ, well with saft gel mud consisting of at least 9.5# Brine with 25 pounds of gel per barrel after the bottom plug is set.	
of get per barret are notion plug is see.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true slid complete to the best of my knowledge and belief.	
A second to the complete to the configuration.	
SIGNATURE Come W. Shenell TITLE Production Clerk	DATE6/20/13
Type or print name Jerry W. Sherrell E-mail address: jerrys@mec.com	phone: (575)748-1288
\mathcal{L}	
APPROVED BY TITLE J57, MSA	DATE 7 -22-2013
OIL CONSERVATION DIVISION - Hobbs office Must Be Notified	
24 hours prior to the beginning of Plugging Operations.	- Lander of the Control of the Contr
	JUL 2 4 2013 \
	OOL W 7 LOIO

Mack Energy Corporation Miller W State #4 30-025-08452

Before After

