Submit 1 Copy To Appropriate District Office -	State of New M			Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Na	tural Resources		vised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-025-23206	
811 S. First St., Artesia, NM 88210	OIL CONSERVATIO	N DIVISION	5. Indicate Type of Leas	
<u>District III</u> – (505) 334-6178	1220 South St. Fr.	ancis Dr.	STATE	FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM	87505	6. State Oil & Gas Lease	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ES AND REPORTS ON WELL	_S	7. Lease Name or Unit A	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA				7
DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	ATION FOR PERMIT" (FORM C-101)	FOR SUCH	North Hobbs G/SA	
1. Type of Well: Oil Well	Gas Well 🗌 Other	4/4	8. Well Number	
		V	30- 131 9. OGRID Number: 157	1004
2. Name of Operator Occidental Permian Ltd.			9. OGKID Number: 137	964 .
3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)	
HCR 1 Box 90 Denver City, TX 793	23			
4. Well Location				
	fofeet from theSouth			line
Section 20	Township 189	<u> </u>		County
	11. Elevation (Show whether D 3662' GL	R, RKB, RT, GR, etc.		
Committee of the second	3002 GL		* ************************************	A STATE OF THE PROPERTY OF THE
12 Check Ar	opropriate Box to Indicate	Nature of Notice	Report or Other Data	
•	•		•	
NOTICE OF INT			SEQUENT_REPORT	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		RING CASING
TEMPORARILY ABANDON DULL OF ALTER CARDING	CHANGE PLANS	COMMENCE DR) A 📙
	MULTIPLE COMPL	CASING/CEMEN	I JOB	
DOWNHOLE COMMINGLE				
OTHER: Coiled Tubing Cleanout	,	OTHER:		
	ted operations (Clearly state al		d give pertinent dates, inclu	uding estimated date
13. Describe proposed or comple		l pertinent details, an		
13. Describe proposed or comple	k). SEE RULE 19.15.7.14 NM/	l pertinent details, an		
13. Describe proposed or comple of starting any proposed work	k). SEE RULE 19.15.7.14 NM/	l pertinent details, an		
13. Describe proposed or comple of starting any proposed work proposed completion or recon	k). SEE RULE 19.15.7.14 NMAmpletion.	l pertinent details, an		
13. Describe proposed or comple of starting any proposed work	k). SEE RULE 19.15.7.14 NMAmpletion.	l pertinent details, an	mpletions: Attach wellbore	e diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or reconstance. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to	k). SEE RULE 19.15.7.14 NM/mpletion. with Perf Clean Tool	 pertinent details, an AC. For Multiple Co		e diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or reconstance. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with water	k). SEE RULE 19.15.7.14 NM/mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256	 pertinent details, an AC. For Multiple Co	mpletions: Attach wellbore HOBBS	e diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or record. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with water 5) Close backside and repeat performance.	k). SEE RULE 19.15.7.14 NM/mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2	 pertinent details, an AC. For Multiple Co	mpletions: Attach wellbore HOBBS	e diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or record. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat pe 6) Pump 10 bbls gel sweep to be 7) POOH with CT and RD Coil	k). SEE RULE 19.15.7.14 NM/mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface	l pertinent details, an AC. For Multiple Co No. For Multiple Co	HOBSS of HOLL	e diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or record. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to br	k). SEE RULE 19.15.7.14 NM/mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface	l pertinent details, an AC. For Multiple Co No. For Multiple Co	HOBSS of HOLL	e diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or record. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat pe 6) Pump 10 bbls gel sweep to be 7) POOH with CT and RD Coil	k). SEE RULE 19.15.7.14 NMA mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit	l pertinent details, an AC. For Multiple Co	HOBBS OF HOLL JUL 23 RECEIVE	OCD 2013
13. Describe proposed or comple of starting any proposed work proposed completion or record. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat pe 6) Pump 10 bbls gel sweep to be 7) POOH with CT and RD Coil	k). SEE RULE 19.15.7.14 NMA mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit	l pertinent details, an AC. For Multiple Co 7000 gals 15% NEFE Per Dee During this pro-	HOBBS OF THE HOLE AND ARECEIVE CEDURE WE Plan to us	OCD 2013 ED
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists. 1) Rig up Coiling Tubing Unit volume 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to be 7) POOH with CT and RD Coil 8) Return well to injection	k). SEE RULE 19.15.7.14 NMA mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit	I pertinent details, an AC. For Multiple Co 3, 000 gals 15% NEFE Per During this proclosed-loop sys	HOBBS OF THE HOLD AND ARECEIVE CEDURE WE plan to us steen with a steel tan	OCD 2013 Se the k and
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to bin 7) POOH with CT and RD Coil 8) Return well to injection	k). SEE RULE 19.15.7.14 NMA mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit	l pertinent details, an AC. For Multiple Co 7000 gals 15% NEFE Per Dee During this proclosed-loop syshaul contents to	HOBBS OF THE PROPERTY OF THE P	OCD 2013 Se the k and
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists. 1) Rig up Coiling Tubing Unit volume 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to be 7) POOH with CT and RD Coil 8) Return well to injection	k). SEE RULE 19.15.7.14 NMA mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit	I pertinent details, an AC. For Multiple Co 3, 000 gals 15% NEFE Per During this proclosed-loop sys	HOBBS OF THE PROPERTY OF THE P	OCD 2013 Se the k and
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to bin 7) POOH with CT and RD Coil 8) Return well to injection CONDITION OF APPROVAL: OPERATOR SO DISTRICT OFFICE 24 HOURS NOTICE BEF	k). SEE RULE 19.15.7.14 NMA mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS.	I pertinent details, and AC. For Multiple Co. 9000 gals 15% NEFE. During this proclosed-loop systemal contents to per OCD Rule 1	HOBBS OF THE PROPERTY OF THE P	OCD 2013 Se the k and
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to bin 7) POOH with CT and RD Coil 8) Return well to injection	k). SEE RULE 19.15.7.14 NMA mpletion. with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS.	I pertinent details, and AC. For Multiple Co. 9000 gals 15% NEFE. During this proclosed-loop systemal contents to per OCD Rule 1	HOBBS OF THE PROPERTY OF THE P	OCD 2013 Se the k and
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists of the proposed complete proposed comple	with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS. Relea	I pertinent details, and AC. For Multiple Co. One of the second of the	HOBBS OF THE HOBBS OF THE HOLD AND THE HOLD	OCD 2013 Se the k and
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to bin 7) POOH with CT and RD Coil 8) Return well to injection CONDITION OF APPROVAL: OPERATOR SO DISTRICT OFFICE 24 HOURS NOTICE BEF	with Perf Clean Tool o 4200' er across perforations 4224-4256' rf wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS. Relea	I pertinent details, and AC. For Multiple Co. One of the second of the	HOBBS OF THE PROPERTY OF THE P	OCD 2013 Se the k and
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists. 1) Rig up Coiling Tubing Unit v. 2) TIH to 4279' 3) Pull up with perf clean tool to 4) Run perf clean tool with wate 5) Close backside and repeat per 6) Pump 10 bbls gel sweep to ber 7) POOH with CT and RD Coil 8) Return well to injection CONDITION OF APPROVAL: OPERATOR SO DISTRICT OFFICE 24 HOURS NOTICE BEF	with Perf Clean Tool of 4200' or across perforations 4224-4256' or wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS. TITLE_Inject	I pertinent details, and AC. For Multiple Co. For Multipl	HOBBS of JUL 2 3 HCL JUL 2 3 RECEIVE Cedure we plan to us stem with a steel tan to the required dispose 15.17. The property of the property	e diagram of OCD 2013 Se the k and sal,
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists of the proposed complete proposed comple	with Perf Clean Tool of 4200' or across perforations 4224-4256' or wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS. TITLE_Inject	I pertinent details, and AC. For Multiple Co. For Multipl	HOBBS OF THE HOBBS OF THE HOLD AND THE HOLD	e diagram of OCD 2013 Se the k and sal,
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists of the proposed completion of the proposed c	with Perf Clean Tool of 4200' or across perforations 4224-4256' or wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS. TITLE_Inject	During this proclosed-loop syshaul contents to per OCD Rule 1 best of my knowledges on Well Analyst	HOBBS OF THE PHONE: 806-592-6	OCD 2013 Se the k and p sal,
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists of the proposed completion of the proposed c	with Perf Clean Tool of 4200' or across perforations 4224-4256' or wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS. TITLE_Inject	During this proclosed-loop syshaul contents to per OCD Rule 1 best of my knowledges on Well Analyst	HOBBS OF THE PHONE: 806-592-6	OCD 2013 Se the k and p sal,
13. Describe proposed or comple of starting any proposed work proposed completion or reconsists of the proposed completion of the proposed c	with Perf Clean Tool of 4200' or across perforations 4224-4256' or wash from 4224-4256' with 2 ring fines to the surface Tubing Unit SHALL GIVE THE OCD FORE WORK BEGINS. TITLE_Inject	During this proclosed-loop syshaul contents to per OCD Rule 1 best of my knowledges on Well Analyst	HOBBS of JUL 2 3 HCL JUL 2 3 RECEIVE Cedure we plan to us stem with a steel tan to the required dispose 15.17. The property of the property	OCD 2013 Se the k and p sal,