Office Energy Min	te of New Mexico			rm C-103
	erals and Natural Re	sources		gust 1, 2011
1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD <u>District II</u> - (575) 748-1283		Ì	WELL API NO. 30-025-37451 37480	
OIL CONSERVATION DIVISION		ISION	5. Indicate Type of Lease	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410JUL 2 5 20131220 South St. Francis Dr. Santa Fe, NM 87505		r.	STATE X FEE	
District IV = (505) 476-3460 Santa Fe, NM 87505		6. State Oil & Gas Lease No.	23	
1220 S. St. Francis Dr., Santa Fe, NM				
87505 PECFIVED SUNDRY NOTICES AND REPOR	TS ON WELLS		7. Lease Name or Unit Agreeme	nt Nama
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR T		CK TO A	7. Lease Name of Onn Agreeme	ill Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT			North Hobbs G/SA	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Oth	I Arriva		8. Well Number	
	INTECTO	2	25-741	
2. Name of Operator			9. OGRID Number: 157984	
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat Hobb	- (C/SA)
HCR 1 Box 90 Denver City, TX 79323			10. Foot hame of windcat Hobb	is (U/SA)
4. Well Location				
Unit Letter A: 360 feet from the North line and 1294 feet from the East line				
Section 25 Town			NMPM Lea	County
	now whether DR, RKB,	<u> </u>	NWI W Lea	County
3678' KB	ion memer BR, RRB,	MI, OM, CIC.)		
Day of the control is a control of the control of t			Fig. 200 and Company of March 1985 (September 1986) (September 1986) (September 1986)	***************************************
12. Check Appropriate Box	to Indicate Nature	of Notice. I	Report or Other Data	
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABA		EDIAL WORK		ASING [
TEMPORARILY ABANDON ☐ CHANGE PLANS PULL OR ALTER CASING ☐ MULTIPLE COM		ING/CEMENT	LING OPNS. PAND A	Ш
DOWNHOLE COMMINGLE	FL LI CAS	ING/CEMENT	30B	
powwwoze G	· ·			
OTHER: Coiled Tubing Cleanout ⊠	. OTH	ER:		
13. Describe proposed or completed operations. (Clearly state all pertine	nt details, and	give pertinent dates, including es	timated date
of starting any proposed work). SEE RULE 1				
proposed completion or recompletion.				
1) Rig up Coiling Tubing Unit with Perf Clean T	ool			
 Rig up Coiling Tubing Unit with Perf Clean T TIH to 4361? 	ool			
 Rig up Coiling Tubing Unit with Perf Clean T TIH to 4361' Pull up with perf clean tool to 4200' 	ool			
 2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforation 	ons 4240-4351			
 TIH to 4361' Pull up with perf clean tool to 4200' Run perf clean tool with water across perforation Close backside and repeat perf wash from 424 	ons 4240-4351' 0-4351' with 2500 gals	: 15% NEFE F	- ICL	
 TIH to 4361' Pull up with perf clean tool to 4200' Run perf clean tool with water across perforation Close backside and repeat perf wash from 424 Pump 10 bbls gel sweep to bring fines to the serior 	ons 4240-4351' 0-4351' with 2500 gals			
 TIH to 4361' Pull up with perf clean tool to 4200' Run perf clean tool with water across perforation Close backside and repeat perf wash from 424 Pump 10 bbls gel sweep to bring fines to the strength POOH with CT and RD Coil Tubing Unit 	ons 4240-4351' 0-4351' with 2500 gals			
 TIH to 4361' Pull up with perf clean tool to 4200' Run perf clean tool with water across perforation Close backside and repeat perf wash from 424 Pump 10 bbls gel sweep to bring fines to the strong POOH with CT and RD Coil Tubing Unit 	ons 4240-4351° 0-4351° with 2500 gals urface	Per	Operator	
 TIH to 4361' Pull up with perf clean tool to 4200' Run perf clean tool with water across perforation Close backside and repeat perf wash from 424 Pump 10 bbls gel sweep to bring fines to the strength POOH with CT and RD Coil Tubing Unit 	ons 4240-4351' 0-4351' with 2500 gals urface	Per uring this	Operator procedure we plan to use	e the
 TIH to 4361' Pull up with perf clean tool to 4200' Run perf clean tool with water across perforation Close backside and repeat perf wash from 424 Pump 10 bbls gel sweep to bring fines to the strength POOH with CT and RD Coil Tubing Unit 	ons 4240-4351' 0-4351' with 2500 gals urface Di	Per uring this posed-loop	Operodor procedure we plan to use system with a steel tank	and
 TIH to 4361' Pull up with perf clean tool to 4200' Run perf clean tool with water across perforation Close backside and repeat perf wash from 424 Pump 10 bbls gel sweep to bring fines to the strength POOH with CT and RD Coil Tubing Unit 	ons 4240-4351' 0-4351' with 2500 gals urface Di	Per uring this posed-loop	Operodor procedure we plan to use system with a steel tank	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforati 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the si 7) POOH with CT and RD Coil Tubing Unit 8) Return well to injection	ons 4240-4351° 0-4351° with 2500 gals urface De Cl	Per uring this posed-loop aul conten	Perador procedure we plan to use system with a steel tank to the required dispos	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforati 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the si 7) POOH with CT and RD Coil Tubing Unit 8) Return well to injection	ons 4240-4351° 0-4351° with 2500 gals urface De Cl	Per uring this posed-loop aul conten	Operodor procedure we plan to use system with a steel tank	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforati 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the si 7) POOH with CT and RD Coil Tubing Unit 8) Return well to injection Sp CONDITION OF APPROVAL: Notify OCD DISTRICT OFFICE 2 prior to STARTING THE WORKOVER.	ons 4240-4351° 0-4351° with 2500 gals urface Decliports ase Dat ha	Per uring this osed-loop aul conten er OCD Ru	Perator procedure we plan to use system with a steel tank to the required disposile 19.15.17.	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforati 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the si 7) POOH with CT and RD Coil Tubing Unit 8) Return well to injection	ons 4240-4351° 0-4351° with 2500 gals urface Decliports ase Dat ha	Per uring this osed-loop aul conten er OCD Ru	Perator procedure we plan to use system with a steel tank to the required disposile 19.15.17.	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforati 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the st 7) POOH with CT and RD Coil Tubing Unit 8) Return well to injection Sp CONDITION OF APPROVAL: Notify OCD DISTRICT OFFICE 2 prior to STARTING THE WORKOVER. I hereby certify that the information above is true and c	ons 4240-4351° 0-4351° with 2500 gals urface Di cl ase Dat ha pe	Per uring this osed-loop aul conten er OCD Ru	procedure we plan to use system with a steel tank ts to the required disposile 19.15.17.	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforati 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the st 7) POOH with CT and RD Coil Tubing Unit 8) Return well to injection Sp CONDITION OF APPROVAL: Notify OCD DISTRICT OFFICE 2 prior to STARTING THE WORKOVER. I hereby certify that the information above is true and c	ons 4240-4351° 0-4351° with 2500 gals urface Di cl ase Dat ha pe	Per uring this osed-loop aul conten er OCD Ru	Perator procedure we plan to use system with a steel tank to the required disposile 19.15.17.	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforati 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the st 7) POOH with CT and RD Coil Tubing Unit 8) Return well to injection Sp CONDITION OF APPROVAL: Notify OCD DISTRICT OFFICE 2 prior to STARTING THE WORKOVER. I hereby certify that the information above is true and c	ons 4240-4351' 0-4351' with 2500 gals urface Di cl ase Dat ha 4 HOURS per omplete to the best of n	Per uring this posed-loop aul contener OCD Runny knowledge	procedure we plan to use system with a steel tank ts to the required disposale 19.15.17. and belief. OATE 7-18-13	and
2) TIH to 4361' 3) Pull up with perf clean tool to 4200' 4) Run perf clean tool with water across perforation 5) Close backside and repeat perf wash from 424 6) Pump 10 bbls gel sweep to bring fines to the standard properties and the standard properties and the standard properties are standard properties. Sp CONDITION OF APPROVAL: Notify OCD DISTRICT OFFICE 2 prior to STARTING THE WORKOVER. I hereby certify that the information above is true and compared to the standard prior to STARTING THE WORKOVER.	ons 4240-4351' 0-4351' with 2500 gals urface Di cl ase Dat ha 4 HOURS per omplete to the best of n	Per uring this posed-loop aul contener OCD Ru ny knowledge AnalystD rhill@oxy.com	procedure we plan to use system with a steel tank ts to the required disposale 19.15.17. and belief. OATE 7-18-13	and al,

שני פיוול פיוול