Submit 1 Copy To Appropriate District State of New Mexico Office District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St. Artesia, NM 88210 OIL CONSERVATION DIVISION	Form C-103
District I – (575) 393-6161	Revised August 1/2011 WELL API NO.
District II - (575) 748-1283	30-025-26923
	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87400	STATE STATE FEE
$\frac{1018111111}{1000} = (303) 470 - 3400$	6. State Oil & Gas Lease No.
87505 RECEIVED	B-1497
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name East Vcuum GB-SA Unit Tract 2622
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 006
2. Name of Operator ConocoPhillips Company	9. OGRID Number 217817
3. Address of Operator _{P. O. Box 51810} Midland, TX 79710	10. Pool name or Wildcat
4. Well Location	Vacuum; GR-SA
Unit Letter F : 1500 feet from the North line and 2450 feet from the West line	
Section 26 Township 17S Range 35E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
<u>3906' GR</u>	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK I PLUG AND ABANDON REMEDIAL WO	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE	
OTHER: packer-on/off too	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
MIRU WSU, NDWH, NUBOP, TOOH with tubing, on/off tool and packer, stand tubing back. Inspect on/off tool and redress or	
replace packer. MI workstring and tally. TIH with scrapper and tubing to 4350'. TOOH with tubing and scrapper, lay all down. TIH	
with injection packer, on/off tool and injection tubing. Note have Duoline Tech on location while running Duoline, pressure test	
going in hole. Land packer @+/- 4346'. Note: this puts packer at 88' above top perf. RU pump truck to casing and pressure test packer to 550 psi. If test pass, get off on/off tool and circulate packer fluid to surface. Get back on on/off tool, NDBOP, NUWH, Notify	
NMOCD of impending integrity test. RU pump truck and chart recorder with 1000psi chart, pressure test casing to 550 psi of 35	
mins. Give chart to Production Specialist, RD, clean up location. Notify Projects to install injection piping to WH.	
Dufter Underground Injection Control Program Wastern and haul content to the required disposal	
11.6 C Packer shall be set within or less than 100	
	Condition of Approval: notify
	OCD Hobbs office 24 hours
Spud Date: Rig Release Date:	or of running MIT Test & Chart
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Thereby certify that are information above is the and complete to the best of my knowledge and benef.	
Hard Xana a man a second a s	
SIGNATURE And Staff Regulatory Technician DATE 10/25/2013	
Type or print name Rhonda Rogers E-mail address: rogerrs@conocophillips.com PHONE: (432)688-9174	
For State Use Only	
APPROVED BY: Maley Stown TITLE Compliance Office DATE 11/13/2013	
Conditions of Approval (if any):	

.