
## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

NOV 19 2013

p.iomp.iom.i	OIL CONSERVATION DIVISION	/
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South St. Francis Dr.	WELL API NO. 30-025-37475
DISTRICT II	HOBBS OFFE, NM 87505	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	NOV 1 5 2012	STATE FEE X
DISTRICT III	NOV 1 5 2013	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NO	OTICES AND RECEIVED WELLS	7. Lease Name or Unit Agreement Name
l	ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
	APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 29
Type of Well:     Oil Well X	Gas Well Other	8. Well No. 742
Name of Operator     Occidental Permian Ltd.		9. OGRID No. 157984
3. Address of Operator	V 70222	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	X 19323	
Unit Letter G: 1670 Feet From The North Line and 1610 Feet From The East Line		
Section 29	Township 18-S Range 38-	E NMPM Lea County
	11. Elevation (Show whether DF, RKB, RT GR, etc.) 3658' KB	
Pit or Below-grade Tank Application	or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material ,		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OF	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion CASING TEST AND CEME	NT JOB
OTHER:	OTHER:	
	perations (Clearly state all pertinent details, and give pertinent date:	s, including estimated date of starting any
13. Describe Proposed or Completed O proposed work) SEE RULE 1103		s, including estimated date of starting any
13. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent date:	s, including estimated date of starting any
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP e	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment.	s, including estimated date of starting any
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. F	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment.	s, including estimated date of starting any
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. For RU wire line & perforate cate.	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment. POOH w/bit. asing @4200-4210' (44 shots). RD wire line.	s, including estimated date of starting any completion or recompletion.
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. For RU wire line & perforate cate of the RIH w/PPI packer set @41'. brine. RD Rising Star. RU	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment. POOH w/bit. asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. For RU wire line & perforate cate of the RIH w/PPI packer set @41' brine. RD Rising Star. RU fresh water. RD pump truc	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment. POOH w/bit. asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemick. POOH w/PPI packer.	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. Fig. RU wire line & perforate cate of a RIH w/PPI packer set @41' brine. RD Rising Star. RU fresh water. RD pump tructor. RIH w/ESP equipment set of a recomplete of the set	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment. POOH w/bit. asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemick. POOH w/PPI packer.	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. Fe se	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment. POOH w/bit. asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemick. POOH w/PPI packer.	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU.  2. ND wellhead/NU BOP.  3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. Ft.  5. RU wire line & perforate cate.  6. RIH w/PPI packer set @41'. brine. RD Rising Star. RU fresh water. RD pump truct.  7. RIH w/ESP equipment set of al. RD BOP/NU wellhead.  9. RDPU & RU. Clean location.	perations (Clearly state all pertinent details, and give pertinent date.  For Multiple Completions: Attach wellbore diagram of proposed equipment.  POOH w/bit.  asing @4200-4210' (44 shots). RD wire line.  21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic k. POOH w/PPI packer.  on 124 jts of 2-7/8" tubing. Intake set @4077'  on and return well to production.	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl al mixed in 100 bbl fresh water. Flush w/100 bbl
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. For all the second of the	perations (Clearly state all pertinent details, and give pertinent date.  For Multiple Completions: Attach wellbore diagram of proposed equipment.  POOH w/bit.  asing @4200-4210' (44 shots). RD wire line.  21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic k. POOH w/PPI packer.  on 124 jts of 2-7/8" tubing. Intake set @4077'  on and return well to production.	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl al mixed in 100 bbl fresh water. Flush w/100 bbl
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU.  2. ND wellhead/NU BOP.  3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. Ft.  5. RU wire line & perforate cate.  6. RIH w/PPI packer set @41'. brine. RD Rising Star. RU fresh water. RD pump truct.  7. RIH w/ESP equipment set of al. RD BOP/NU wellhead.  9. RDPU & RU. Clean location.	perations (Clearly state all pertinent details, and give pertinent date. For Multiple Completions: Attach wellbore diagram of proposed equipment. POOH w/bit. asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic k. POOH w/PPI packer. on 124 jts of 2-7/8" tubing. Intake set @4077' on and return well to production.  RUPU 10/17/2 true and complete to the best of my knowledge and belief. I further certify	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl al mixed in 100 bbl fresh water. Flush w/100 bbl  2013 RDPU 10/23/2013 that any pit or below-grade tank has been/will be
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU.  2. ND wellhead/NU BOP.  3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. Fe set al. RIH w/PPI packer set @41'. brine. RD Rising Star. RU fresh water. RD pump tructor. RIH w/ESP equipment set al. RDPU & RU. Clean location. Thereby certify that the information above is constructed or	perations (Clearly state all pertinent details, and give pertinent date. For Multiple Completions: Attach wellbore diagram of proposed equipment. POOH w/bit. asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic k. POOH w/PPI packer. on 124 jts of 2-7/8" tubing. Intake set @4077' on and return well to production.  RUPU 10/17/2 true and complete to the best of my knowledge and belief. I further certify	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl al mixed in 100 bbl fresh water. Flush w/100 bbl  2013 RDPU 10/23/2013  that any pit or below-grade tank has been/will be e OCD-approved
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et an	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment.  POOH w/bit. asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic k. POOH w/PPI packer. on 124 jts of 2-7/8" tubing. Intake set @4077' on and return well to production.  RUPU 10/17/2 true and complete to the best of my knowledge and belief. I further certify or an (attached) alternative plan	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl al mixed in 100 bbl fresh water. Flush w/100 bbl  2013 RDPU 10/23/2013 that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE 11/13/2013
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. For State Use Only  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et al. RIH w/bit. Tag @4378'. For State Use Only  1. RIH w/bit. Tag @4378'. For State Use Only  1. RIH w/PPI packer set @41'. brine. RD Rising Star. RU fresh water. RD pump tructor. RIH w/ESP equipment set of al. RIH w/ESP eq	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment.  200H w/bit asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic k. POOH w/PPI packer on 124 jts of 2-7/8" tubing. Intake set @4077' . and and return well to production.  RUPU 10/17/2 . true and complete to the best of my knowledge and belief. I further certify plan  TITLE Administrative	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl al mixed in 100 bbl fresh water. Flush w/100 bbl  2013 RDPU 10/23/2013 that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE 11/13/2013 TELEPHONE NO. 806-592-6280
13. Describe Proposed or Completed Oproposed work) SEE RULE 1103  1. RUPU & RU. 2. ND wellhead/NU BOP. 3. POOH and lay down ESP et an	perations (Clearly state all pertinent details, and give pertinent date: . For Multiple Completions: Attach wellbore diagram of proposed equipment.  200H w/bit asing @4200-4210' (44 shots). RD wire line. 21'. RU Rising Star and pump 1200 gal of 15% PAD acid in 1 pump truck and pump scale squeeze w/100 gal of 6490 chemic k. POOH w/PPI packer on 124 jts of 2-7/8" tubing. Intake set @4077' . and and return well to production.  RUPU 10/17/2 . true and complete to the best of my knowledge and belief. I further certify plan  TITLE Administrative	s, including estimated date of starting any completion or recompletion.  stage over perfs @4195-4215'. Flush w/50 bbl al mixed in 100 bbl fresh water. Flush w/100 bbl  2013 RDPU 10/23/2013 that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE 11/13/2013

## Work Plan Report for Well: NHSAU 742-29



## **Survey Viewer**