	UNITED STATES EPARTMENT OF THE INTERIOR UPPEAU OF LAND MANAGEMENT			FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010			
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS					5. Lease Serial No. NMLC032096B		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Gas Well Other					8. Well Name and No. EAST BLINEBRY DRINKARD UNIT 016		
2. Name of Operator Contact: REESA HOLLAND FISHER APACHE CORPORATION E-Mail: Reesa Holland@apachecorp.com					9. API Well No. 30-025-06526		
3a. Address 303 VETERANS AIRPARK LANE SUITE 3000 MIDLAND, TX 79705			o. (include area cod 18-1062	e)	10. Field and Pool, or Exploratory EUNICE; B-T-D, NORTH		
4. Location of Well (Foolage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 11 T21S R37E NENE 330FNL 480FEL					LEA COUNTY COUNTY, NM		
12. CHECK APP	PROPRIATE BOX(ES) T	O INDICATE	ENATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	C Acidize	Dee	pen	Product	tion (Start/Resume)	U Water Shut-Off	
_	Alter Casing	🛛 Frac	cture Treat	🗖 Reclam	ation	Well Integrity	
Subsequent Report	Casing Repair		v Construction	🗖 Recom	plete	Other	
Final Abandonment Notice	Change Plans		g and Abandon		rarily Abandon		
	Convert to Injection	D Plug	g Back	U Water I	Disposal		
If the proposal is to deepen direction Attach the Bond under which the we following completion of the involve testing has been completed. Final A determined that the site is ready for Apache proposes to open ad treating, per the attached pro	ork will be performed or provide d operations. If the operation re (bandonment Notices shall be fil final inspection.) ditional pay in the Blinebry	e the Bond No. of esults in a multip led only after all	n file with BLM/BI te completion or rec requirements, inclu	A. Required su completion in a iding reclamatio	bsequent reports shall be new interval, a Form 316 n, have been completed,	filed within 30 days 0-4 shall be filed once and the operator has	
				SEE A CON	TTACHED FOR DITIONS OF A	PPROVAL	
14. I hereby certify that the foregoing i	Electronic Submission #			- 11 - I- I	•		
Name (Printed/Typed) REESA H	OLLAND FISHER		Title AUTHO	ORIZED REF	RESENTATIVEVE	<u>D</u>	
Signature (Electronic	Submission)		Date 01/16/2	2014	A	1 An	
	THIS SPACE FO	DR FEDERA	L OR STATE	OFFICE U	Manue To	TADA	
					REAU OF LAND MANA	GEMINT	
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or			Title	9 4	CARLSBAD (EVELD OF	FICE Date	
certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the uct operations thereon.	e subject lease	Office K	12			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe to any matter wi	rson knowingly and thin its jurisdiction	d willfully to ma	ake to any department or	agency of the United	

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

FEB 0 3 2014



AFE No: 11- 14- 0148

EBDU #016

API #: 30-025-06526 330' FNL & 480' FEL Unit A, Sec 11, Township 21S, Range 37E Lea County, New Mexico

Add Blinebry I-II Pay & Stimulate

15 January 2014

Recommended Procedure:

- 1. MIRU pulling unit. POOH w/pump & rods. Install BOP. Rel TAC. TFF. TOOH w/tbg. If necessary, clean well out to +/-6200'.
- 2. PU & RIH w/6-1/8" bit and 7" x 26# csg scraper on 2-7/8" workstring. RIH to +/-5875'. POOH.
- 3. RIH w/Pkr and 2-7/8" ws. Set pkr @ +/-5850'.
 - a. Acidize the Blinebry III-V intervals 5889'-6115' w/3000 gals 15% HCL-NE-FE BXDX acid using ball sealers to divert the acid. Flush to btm perf w/2% KCL.
 - b. Rel pkr & knock off balls. Re-set pkr @ +/-5850'.
 - c. Swab well for the rest of the day
- 4. Rel pkr & POOH.
- 5. RU wireline truck. RIH w/GR/CNL/CCL log. Correlate to the Simultaneous Radiation log run on 12/4/52. Log well from PBTD to +/-5500'. Send log to Midland office for evaluation and perf recommendations. POOH.
- 6. RIH w/7" RBP and pkr on tbg. Set plug @ +/-5875'. Pressure test plug to 1000 psi via pkr. Dump 2 sx sand on RBP. POOH.
- 7. Perf Blinebry I-II intervals from +/-5725'-5850' as per log evaluation.
- 8. RIH w/pkr on 2-7/8" ws. Set pkr @ +/-5650'.
 - a. Acidize Blinebry I-II w/3000 gals 15% HCL-NE-FE BXDX acid using ball sealers as diversion. Flush to btm perf w/2% KCL.
 - b. Rel pkr & knock off balls. POOH.
- 9. RIH w/frac pkr on 3-1/2", L-80 ws. Hydrotest tbg in hole to at least 7500 psi.
 - a. Set pkr @ +/-5625'.
 - b. Frac Blinebry I-II w/40,000# 20/40 SLC (or equivalent) resin coated sand down 3-1/2" ws @ +/-30 BPM in 25# XL gel as per frac rec. Incorporate corrosion & scale inhibitors in frac system.
 - c. Rel pkr & POOH LD 3-1/2" ws & tools.
- 10. RIH w/RH. CO sand to RBP @ +/-5875'. Rel RBP & POOH.
- 11. RIH w/2-3/8" prod tbg. Land SN @ +/-6150'. Install TAC @ +/-5600'.
- 12. RIH w/pmp and rods.
- 13. RTP Blinebry I-V and place well in test.

Created by Neevia Document Converter trial version http://www.neevia.com

East Blinebry Drinkard Unit 16 30-025-06526 Apache Corporation January 28, 2014 Conditions of Approval

Work to be completed by April 28, 2014.

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

- 1. Must conduct a casing integrity test before any perforating or fracturing can be done. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Contact the BLM if test fails.
- 2. Operator shall provide the BLM with a typical decline curve and reservoir data from each formation individually.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **2000** (**2M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 012814