					·····		
Form 3160-5 (August 2007)			_				
Form 3160-5 (August 2007) HOBDE UNITED STATES OCD Hobbs BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010		
FED SUNDRY	<ol> <li>Lease Serial No. NMLC032096B</li> </ol>	<u> </u>					
Do not use this form for proposals to drill or to re-enter an abapted well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agre	ement, Name and/or No.	
1. Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. EAST BLINEBRY	DRINKARD UNIT 033	
2. Name of Operator Contact: REESA HOLLAND FISHER APACHE CORPORATION E-Mail: Reesa.Fisher@apachecorp.com					9. API Well No. 30-025-06543	~	
3a. Address     3b. Phone No. (include area code)       303 VETERANS AIRPARK LANE SUITE 3000     Ph: 432-818-1062       MIDLAND, TX 79705     Ph: 432-818-1062					10. Field and Pool, or Exploratory EUNICE; B-T-D, NORTH		
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description,	)			11. County or Parish, and State		
Sec 12 T21S R37E SENW 1980FNL 1980FWL					LEA COUNTY COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	) INDICATE	ENATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION			TYPE O	F ACTION			
🛛 Notice of Intent	🗋 Acidize 🛛 🖾 Deepa		pen	Product	ion (Start/Resume)	□ Water Shut-Off	
	Alter Casing Fracture Treat Rec			🗖 Reclam	ation	Well Integrity	
Subsequent Report	Casing Repair	🗖 Nev	v Construction	🗖 Recomp	lete	🗖 Other	
Final Abandonment Notice	🗖 Change Plans	🗖 Plu	g and Abandon	🗖 Temporarily Abandon			
	Convert to Injection	🗖 Plu	g Back	🗖 Water I	Disposal		
13. Describe Proposed or Completed Opulf the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for final	ally or recomplete horizontally, k will be performed or provide operations. If the operation respondent Notices shall be file	give subsurface the Bond No. o sults in a multin	locations and measure n file with BLM/BIA le completion or reco	ared and true ve A. Required sub completion in a r	ertical depths of all pertin provident reports shall be new interval a Form 316	ent markers and zones. filed within 30 days 0-4 shall be filed once	
Apache intends to deepen this	s well and test the Blinebr	y pay, per the	e attached proce	dure.			
	SEE ATTA CONDITIO						
	Conditio						
14. I hereby certify that the foregoing is	true and correct.						
	Electronic Submission #2 For APACH		d by the BLM Wel TION, sent to the		System		
Committed to AFMSS for processing by JOHNNY DICKERSON on 01/28/2014 ()							
Name (Printed/Typed)         REESA HOLLAND FISHER         Title         AUTHORIZED REPRESENTATIVE							

Signature	(Electronic Submission)	Date	01/22/2014			٦
	THIS SPACE FOR FEDERA	AL OR	STATE OFFICE L	JSE	ATTROVED	
Approved By		Title			FEB 2 4 2014	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	KH	В	INFAIL OF LAND MANAGEMENT	
Title 18 U.S.C. Sectio States any false, fict	n 1001 and Title 43 U.S.C. Section 1212, make it a crime for any p itious or fraudulent statements or representations as to any matter w	erson kno vithin its j	wingly and willfully to r urisdiction.	nake to:	any department or agency of the United	

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*



AFE No: 11-14-0241

#### EBDU #033 API#: 30-025-06543 1980' FNL & 1980' FWL Unit F, Sec 12, Township 21S, Range 37E Lea County, New Mexico

Deepen & Test Blinebry 111-IV Pay

21 January 2014

#### Recommended Procedure:

- 1. MIRU pulling unit. POOH w/pump & rods. Install BOP. TOOH w/2-3/8" prod tbg.
- 2. PU & RIH w/4-3/4" bit and 5-1/2" x 15.5# csg scraper on 2-7/8" workstring to +/-5780'. POOH.
- 3. RIH w/cement retainer on 2-7/8" tbg.
  - a. Set ret @ +/-5750'.
  - b. EIR dn 2-7/8" tbg into Blinebry 1-11 perfs 5783'-5884'.
  - c. Squeeze Blinebry 1-11 w/20 sx cmt. Attempt to get 500-1000 psi squeeze pressure. Sting out of ret & POOH.
  - d. WOE-minimum of 24 hrs.
- 4. RIH w/4-3/4" bit, 3-1/2" DC's and 2-7/8" ws to 5750'.
  - a. RU reverse unit, swivel & foam unit.
  - b. Drill out cmt ret & cmt to 5900'.
  - c. Pressure test csg to 500 psi.
  - d. Drill out cmt & csg shoe 5923'-25'.
  - e. Drill new 4-3/4" OH 5925'-6100'.
  - f. Gire hole clean. POOH LD drilling equipment.
- 5. RU wireline truck.

6.


- a. RIH w/GR/CNL/CCL logging tool. Log well from TD to 5600'. Correlate log to Lane Wells radioactivity Log run on 8/29/54.
- b. Send log in to Midland office for evaluation.
- c. POOH RD wireline unit.
- RIH w/pkr on 2-7/8" ws. Set pkr @ +/-5910'. RU frac equipment.
  - a. Acidize the Blinebry III-IV OH interval 5925'-6100' w/6,000 gals 15% HCL-NE-FE acid in 3 equal stages using rock salt for diversion.
  - b. Frac the Blinebry III-IV OH interval w/60,000# 20/40 SLC (or equivalent) resin coated sand down 2-718" tbg @ +/-20 BPM in 25# XL gel as per frac rec. incorporate friction reducer & corrosion and scale inhibitors in frac system.
  - c. Rel pkr & POOH.
- 7. RU wireline truck.
  - a. RIH w/omposite bridge plug. Set CBP @ +/-5910'.
  - b. Re-perf Blinebry 1-11 intervals +/-5740'-5890' as per log evaluation.
  - c. POOH.
- 8. RIH w/pkr & 2-7/8" ws. Set pkr @ +/-5650'.RU frac equipment..
  - a. Acidize Blinebry 1-11 w/3,000 gals 15% HCL-NE-FE acid using ball sealers as diversion. Flush to btm perf w/2% KCL.
  - b. Rel pkr & knock off balls. Re-set pkr @ +/-5650'.
  - c. Frac Blinebry 1-11 w/60,000# 20/40 SLC (or equivalent) resin coated sand down 2-7/8" ws @ +/-20 BPM in 25# XL gel as per frac rec. Incorporate friction reducer & corrosion and scale inhibitors into frac system.
  - d. Rel pkr & POOH.

#### AFE No: 11-14-0241

#### EBDU #033

- 9. RIH w/4-3/4" bit on 2-7/8" ws. CO sand to CBP @ +/-5910'. DO CBP. CO to TD @ 6100'. POOH LD 2-7/8" ws.
- 10.
- RIH w/2-3/8" prod tbg. a. Land SN @ +/-5900'.
  - b. Install TAC @ +/-5650'.
  - c. RIH w/pump & new 76 rod string.
  - d. RTP Blinebry and place in test.





Created by Neevia Document Converter trial version http://www.neevia.com

# <u>Pr.oPored</u>

.

	WELL DATA SHEET Last Update:
Toce 2815	Lease Name: $\pounds/J/t'$ $tbJ!$ (Loc.I <fwr 912.="" <math="" api="" no:="" p8)="">JD \cdot O.tf - 06J-7'3 If <math>rIO''/f!(J'W' fl' 12 7!-2.I.S   fJ?E</math> County:-, L e''' ST: ///M Spud Date: <math>3;0,-1</math> Well Elev: <math>J''t71_{}</math> GL <math>II_{}</math> KB <math>I/ "O,t</math> TD Date: <math>IZ?r-f</math> Completion Date: <math>9-I_{}</math> <math>\pounds</math> TD: <math>6/0 c^{&gt;}</math> PBTD: TOC: <math>2 ff/[Ct:s)</math> <math>IOI'/i J T&gt;'' flJi'' Z/t'1 / 2fO.J';1 {CJrc}</math> Csg iz: <math>Zr;-f</math> wt: <math>J: t'''</math>, Grd: <math>fl_{}fo_{}DpthJ:,I.Jf 3'</math> Cmt: YIt'f.(</fwr>
•	Producing Formatio:       8hf! e.k 17         Perfs: From f.7:£0 .0' 'ZiL. /spf · r9.lf to /(/'1, o l-/
111 /)TI_ <b>r; m</b> ∴+ I3	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$

Created by Neevia Document Converter trial version http://www.neevia.com

## **Conditions of Approval**

### Apache Corporation East Blinebry Drinkaard Unit - 33 API 3002506543, T21S-R37E, Sec 12 February 24, 2014

- Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Surface disturbance beyond the existing pad must have prior approval.
- 5. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 6. Functional  $H_2S$  monitoring equipment shall be on location.
- 7. 2000 (2M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 8. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. During Step 4 of the recommended procedure, chart a 30 minute casing integrity test of 500psig. Document the pressure test on a one hour full rotation calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed CIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval. Include a copy of the chart in the subsequent sundry for this workover.
- 10. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 5900 or below to top of cement. The CBL may be attached to a <u>pswartz@blm.gov</u> email. The CFO BLM on call engineer may be reached at 575-706-2779.

- 11. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- 12. Submit the BLM Form 3160-4 **Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- 13. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 14. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies) before 08/24/2014 (NOI approval date + six months).
- 15. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

PRS/

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - <u>http://www.blm.gov/nm/st/en/prog/energy/oil\_and\_gas.html</u>

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.