Submit 1 Copy To Appropriate District Office	State of New	Mexico	,	Form C-10		
District 1 – (575) 393-6161	Energy, Minerals and N	latural Resources		Revised July 18, 201	3	
			WELL API NO.		1	
1625 N. French Dr., Hobbs, NM 8824 SOC District II – (575) 748-1283	OIL CONSERVATION	ON DIVISION	30-025-41037			
811 S. First St., Artesia, NM 88210			5. Indicate Type of L	ease		
<u>District III</u> $-$ (505) 334-6178	2014 1220 South St. F	rancis Dr.	STATE 7	FEE		
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NARS 4 10 6 2 District IV – (505) 476-3460	Santa Fe, NM	1 87505	6. State Oil & Gas Le	ease No	-	
1220 S. St. Francis Dr., Santa Fe, NM				/		
87505	IFD			/		
SUNDRY	ES AND REPORTS ON WEI	LLS	7. Lease Name or Un	it Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSA			North Monument G/SA	Unit (302708)		
DIFFERENT RESERVOIR. USE "APPLICA	TION FOR PERMIT" (FORM C-10	1) FOR SUCH		(Unit (302700)		
PROPOSALS.)	Gas / Well 🔲 Other		8. Well Number 385		-	
			/			
2. Name of Operator			9. OGRID Number 873			
Apache Corporation						
3. Address of Operator			10. Pool name or Wil			
303 Veterans Airpark Lane, Suite 300	0 Midland, TX 79705		Eunice Monument; G-	SA (23000)		
4. Well Location					-	
Unit Letter: 13	feet from the South	line and	feet from th	e East line		
Section 19	Township 19S	Range 37E	NMPM Co	ounty Lea	X	
	11. Elevation (Show whether	DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPO	RT OF:		
PERFORM REMEDIAL WORK		REMEDIAL WORK		TERING CASING		

NOTICE OF INTENTION TO.						
PERFORM REMEDIAL WORK	\checkmark	PLUG AND ABANDON		REMEDIAL WORK] ALTERING CASING [
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.] PANDA [
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB	J	
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM						
OTHER:				OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache would like to Sonic hammer the lower Grayburg, perforate & acidize the upper Grayburg per the attached procedure.

Spud Date:	05/06/2013	Rig Release Date:	05/11/2013	
I hereby certi	ify that the information above	e is true and complete to the best	of my knowledge and belief.	
SIGNATUR		TITLE Regulatory	y Analyst II	DATE 05/02/2014
Type or print	name Fatima Vasquez	E-mail address:	Fatima.Vasquez@apachecorp.co	om PHONE: (432) 818-1015
For State Us APPROVED		nown TITLE Dist.	Supervisor	DATE 5/7/2014
Conditions of				
				MAY 07 2014

١.

NMGSAU #385 API # 30-025-41037 Sec 19, T19S, R37E Elevation: 3693' KB, 3682' GL TD: 4,116' PBTD: 4,069' CIBP Casing Record: 8-5/8" 24# J-55@ 1,310' w/ 349 sxs 5-1/2" 17# J-55@ 4,114' w/ 637 sxs

Perfs: Grayburg: 3849-60; 3876-85; 3890-95; 3899-3903; 3922-40 w/ 2 jspf (94 holes)

Objective: Sonic hammer the lower Grayburg, perforate and acidize the upper Grayburg, RTP.

AFE: 11-14-1637

- 1. MIRU unit. Kill well as necessary. Unseat pump. POOH w/ rods and pump.
- 2. ND WH. NU BOP. Release TAC. POOH w/ tubing.
- 3. PU and RIH w/ bit, bit sub, and drill collars on 2-7/8" production tubing to PBTD @ ~4,069'.
- 4. PU and RIH w/ sonic hammer on 2-7/8" production tubing to bottom perf @ 3,940'.
- 5. MIRU acid services. Acidize down 2-7/8" J-55 tubing w/ 2,500 gals of 15% NEFE HCL w/ additives through the sonic hammer moving across perforations from 3,849'-3,940'. Drop ball and shear tool.
- 6. RU swab equipment and recover load and swab test perfs for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- 7. Kill well if necessary. POOH w/ sonic hammer and 2-7/8" tubing.
- MIRU WL. RIH w/ perforator and perforate the UPR Grayburg at 3688-94; 3705-14; 3769-81; 3793-3800; 3807-15 w/ 2 jspf 120° phasing (84 holes). TOOH w/ perf guns. Correlate to Allied Wireline Compensated Neutron Litho Density Log dated 5/9/2013. RDMO WL.
- PU and RIH w/ RBP-PKR straddle assembly with ball catcher on WS. Set RBP and ball catcher at ± 3,845. TOOH and set PKR at 3,840 and test RBP to 1000 psi. Release PKR and TOOH and set PKR above new perforations at ± 3,640'. Test backside to 500 psi.
- MIRU acid services. Acidize the Grayburg (3,688-3,815) down the tubing with 3000 gallons 15% NEFE w/ additives using 170 ball sealers to divert evenly spaced throughout the job as a max rate but do not exceed 4,000 psi surface treating pressure. Displace to bottom perf with 25 bbls of flush. Release PKR and knock balls off. TOH and set PKR at 3,640'.
- RU swab equipment and recover load and swab test perfs for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- *12.* Kill well if necessary. Release PKR and TIH to RBP and ball catcher. Latch and release RBP. TOOH w/ RBP-PKR straddle assembly.
- 13. PU and RIH w/ production tbg and rods w/ new pump as per the Monument office specification
- 14. RDMOPU. Return well to production and place into test for 10 days.



