Submit 1 Copy	To Appropriate District	State of New Mexico					Form C-103			
<u>District I</u> – (575) 393-6161		Energy, Minerals and Natural Resources						Revised July	18, 2013	
	Dr., Hobbs, NM 88240					WELL A				
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210		OIL CONSERVATION DIVISION					5-31110 ate Type of Lea			
District III - (50		1220 South St. Francis Dr.					TATE	FEE		
District IV – (50	s Rd., Aztec, NM 87410	Santa Fe, NM 87505					Oil & Gas Lea			
1220 S. St. Fran	cis Dr., Santa Fe, NM	, , , , , , , , , , , , , , , , , , ,					2			
87505		LCES AND DE		WELLS		7 1	None ou Unit			
(DO NOT USE	THIS FORM FOR PROP	TICES AND RE			BACK TO A		e Name or Unit lat State SWD	Agreement	Name	
DIFFERENT RI		CATION FOR PERMIT" (FORM C-101) FOR			R SUCH	0 117 11				
PROPOSALS.)		а П	- · · · · · · · · · · · · · · · · · · ·		HOBBS OCD	l l	number	/		
	Vell: Oil Well	Gas Well 📋	Other S	WD						
2. Name of C					MAR 3 0 201	9. OGR	ID Number			
3. Address of	eum Corporation				MAR DU-	<u>0255</u>	name or Wild			
	ourth Street, Artesia,	NM 88210					San Andres-Gl			
4. Well Loca					RECEIVED					
Unit Lett	<i>C</i> .	3300 feet fr	om the	South	line and 1	980	feet from the	East	line	
									inic	
Section	<u></u>	Towns			<u>;e 33E</u> RKB, RT, GR, etc.)	NMPM	Lea	County		
			A COUCH WILL	4,192' C			1.8	Server Server		
				.,						
	12 Check	Appropriate	Pox to Ind	licate Nat	ture of Notice, I	Report o	r Other Data			
	12. Check	Appropriate				icepoir o		L		
	NOTICE OF II	NTENTION [•]	TO:		SUBS	SEQUE	NT REPOR	RT OF:		
PERFORM F	REMEDIAL WORK 🗌	PLUG AND ABANDON			REMEDIAL WORK	EDIAL WORK 🛛 ALTERING CASING 🗌				
TEMPORAR	ILY ABANDON	CHANGE PL	ANS		COMMENCE DRILLING OPNS. P AND A					
PULL OR ALTER CASING 🛛 MULTIPLE COMPL					CASING/CEMENT	JOB				
	OP SYSTEM		N-312321-0773		OTHER	973. Tj	· · · · · · · · · · · · · · · · · · ·			
OTHER:	ribe proposed or com	Possibly repai			OTHER:	aivo port	inent dates inc	luding octim		
	rting any proposed w									
	osed completion or re				T of Muniple Con	ipietions.	rituden wende	ie ulugruin o	•	
r r -	I	- F								
Yates Petroleum Corporation plans to repair a possible leak. Attached please find a copy of the procedure and a copy of the schematic.										
Please note that verbal approval was given to Brice Letcher, a representative of Yates Petroleum Corporation, by Maxey Brown of the										
NMOCD-Hobbs office to begin the work.										
Condition of Approval: notify										
OCD Hobbs office 24 hours										
prior of running MIT Test & Chart										
	huar ar anna a									
Spud Date:			Rig R	elease Date	e:					

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jane Watter TITLE Regulatory Reporting Technician DATE March 25, 2015
Type or print name <u>Laura Watts</u> E-mail address: <u>laura@yatespetroleum.com</u> PHONE: <u>575-748-4272</u>
APPROVED BY: Maluy Blown TITLE Dist, Supervisor DATE 3/30/2015
Conditions of Approval (if any):

m

MAK 3 1 2015



105 SOUTH FOURTH STREET ARTESIA, NEW MEXICO 88210 TELEPIONE (615) 746-1471

Red Hat State SWD #1 3,300' FSL & 1,980' FEL Sec. 2-16S-33E Lea County, New Mexico API # 30-025-31110

Workover Procedure AFE005783

Executive Summary:

This SWD recently failed an MIT. Could have leak in packer, tubing or casing. Repair the well and return to SWD service.

TD:	13,250′	PBTD:	9,765'			
GR:	4,192'	KB:	4,214'			
Surface Casing: Intermediate Casing: Production Casing:		13 ¾" 54.5# at 409'. Cemented with 425 sx. Cement circulated. 8 ¾" 32# at 4,515'. Cemented with 2,100 sx. Cement circulated. 5 ¾" 17# & 20# at 13,250'. Cemented with 2,650 sx.				
Tubing S	String:	2 ‰" pla	astic coated tubing with 5 ½" nickel plated packer set at 5,774'.			

Workover Procedure:

- 1. MIRU well service unit. Flow the pressure off of the well or pump brine down the tubing to kill the well. Release packer and TOH laying down 2 %" plastic coated tubing.
- 2. Pick up 2 %" work string and TIH with RBP and packer. Set RBP at 5,780'. Pressure test casing to 1,000 psi for 30 minutes. If casing tests good then release RBP and TOH laying down work string.
- 3. If there appears to be a casing leak, isolate and squeeze the leak as necessary to restore wellbore integrity.
- 4. TIH with new 2 %" plastic coated tubing and nickel plated packer. Perform an MIT and record on chart for NMOCD. Return the SWD to service and RDMO.

Area Engineer:

Brice A. Letcher Date: 3/24/2019

CC: Master File

