Submit I Copy To Appropriate District Office District 1 (575) 393 6161 Energy Minerals and Natural Resources	Form C-103
District - (575) 393-6161	Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210	30-025-09868 5. Indicate Type of Lease
1000 Dio Brazos Dd. Aztos NM 974105-	STATE FEE A
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	B. C. Dickinson Al
1. Type of Well: Oil Well A Gas Well Other	8. Well Number 2
2. Name of Operator Resolute Natural Resources Co., LLC	9. OGRID Number 295770
3. Address of Operator 1700 Lincoln St, Ste 2800 Denver, CO 80203	10. Pool name or Wildcat Denton, Devonian
4. Well Location	
Unit Letter L : 2240 feet from the South line and 40	
Section 1 Township 15S Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3808 ' GL	
12. Check Appropriate Box to Indicate Nature of Notice. I	Report or Other Data
E DEDMITTING COMP. IN ISOTIONS	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CONVERSION RBDMS	
TEMPORARILY ABANDON CHANGE PLANS CRETURN TO TA	
PULL OR ALTER CASING MULTIPLE COMPL C CSNG	ENVIRO CHG LOC
DOWNHOLE COMMINGLE INT TO P	AMP&ANR P&AR
CLOSED-LOOP SYSTEM	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
Resolute proposes to plug and abandon the subject well as below:	
BC Dickinson A-1 #2 API 3002509868 (TDPDFFISH)	
1. Perforate 7" casing at ±6975', squeeze 35 sacks cement WOC STAL. CTOPOFFISH 2. Remove 7" casing from a minimum of 4804', and spot 35 sacks @4804 & tag, or perforate at 4804',	
 Remove 7" casing from a minimum of 4804', and spot 35 sacks squeeze and tag 35 sacks 50' below the intermediate shoe @ 4754' 	s @4804 & tag, or periorate at 4804',
3. If casing removed-spot 35 sacks at 3000' base of salt-othe	
4. If casing removed-spot 35 sacks @ 2200' top of salt-otherw	
5. If casing removed-spot 35 sacks @ 424' and tag- or circula	
If cement not circulated to surface, circulate cement from	1 60' to surface
Wellbore diagrams (current and proposed) are attached.	The Oil Conservation Division
	UST BE NOTIFIED 24 Hours
	or to the beginning of operations
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE CARRY CLASS TITLE ST Regulatory Analystate 8-20-15	
Type or print name Sherry Glass E-mail address: PHONE: 303-573-4886, 1580	
For State Use Only M Name of State Use Only R 122/2015	
APPROVED BY: 1 Conditions of Approval (if any):	

B.C DICKINSON "A-1" #2

API # 30-025-09868 2240' FSL, 400' FWL, SEC 1, T15S, R37E UNIT LWTTER "L" SPUD 10/18/52

PROPOSED



