Submit I Copy To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised July 18, 2013 District I - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 WELL API NO. District II - (575) 748-1283 30-025-21842 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 MAR 2 3 201220 South St. Francis Dr. 5. Indicate Type of Lease District III - (505) 334-6178 STATE I FEE [1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM K-5212 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Graham State 8. Well Number 1 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number 190595 Endeavor Energy Resources, LP 3. Address of Operator 10. Pool name or Wildcat North Bagley, 110 N. Marienfeld Street, Suite 200, Midland, Texas 79701 (Lower Penn) 4. Well Location Unit Letter O: 554 feet from the SOUTH line and 2086 feet from the EAST line Section 3 Township 11S Range 33E **NMPM** County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON CHANGE PLANS** PANDA **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** 17 OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of Proposed completion or recompletion. Squeeze Wolfcamp A and Bough C 10) RIH w/7" cement retainer and 2 7/8" ws and set cement retainer @ 9000'. 11) RU cement truck and squeeze Bough C per design. Sting out from cement retainer and pullup to 8700'. 12) SDFN 13) Establish injection rate on the Woplfcamp A and POOH w/ws. 14) RIH w/7" cement retainer and 2 7/8" ws and set cement retainer @ 8700'. 15) RU cement truck and squeeze Wolfcamp A per design. Sting out from cement retainer and POOH w/ws. 16) RU swivel. RIH w/6" bit, 4 drill collars and 2 7/8" ws. Drill to top of plug and test squeeze to 200 psi for 5 minutes. Report results to Midland Office/Engineering. 17) TOOH w/ 2 7/8" ws, 4 drill collars and 6" bit. Mill over Packer 18) RIH w/6" OD and 4.25" ID milling shoe, x-over, jars, 4 drilling collars, x-over and 2 7/8" ws. Tag top of plug @ 10,000'and mill over packer. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE LEGULATORY HNALYST DATE 3-23-2016 **SIGNATURE** E-mail address: Douth Cooronune, Colone: 490-DOUTH Type or print name For State Use Only DATE APPROVED BY: Conditions of Approval (if any):