

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

APR 03 2017

RECEIVED

CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-11481
5. Indicate Type of Lease STATE X FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 8910115870
7. Lease Name or Unit Agreement Name Langlie Jal
8. Well Number 32
9. OGRID Number 17213
10. Pool name or Wildcat Langlie- Mattix

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: **Oil Well X** Gas Well ☐ Other

2. Name of Operator
Penroc Oil Corporation

3. Address of Operator
PO BOX 2769, Hobbs, New Mexico 88241-2769 USA

4. Well Location

Unit Letter **C** **600** feet from the **NORTH** line and **1920** feet from the **WEST** line

Section **06** Township **25S** Range **37E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK X PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Below is a step list of work to be performed:

- 1) Clean location and test anchors.
- 2) MIRU
- 3) POOH with pump, parted rods, and tbq.
- 4) RIH w/perforating guns, add perfs 3230'-3236', 3254'-3258', 3342'-3350'. POOH w/perf guns.
- 5) RIH w/ hydrotested tbq w/ pkr/rbp.
- 6) Acidize perfs from 3164-3350' w/2500 gals 15% HCL. Release pkr/rbp, come up hole to acidize perfs 3032'- 3118' w/680 gals 15% HCL.
- 7) POOH w/ pkr/rbp and tbq.
- 8) RIH w/ tbq, rods, and pump.
- 9) Clean location and RTP

C.O.A. SUBMIT CURRENT
W.B.D. SHOWING ALL PERFORATIONS.
MAB

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.Y. Merchant TITLE

PRESIDENT

DATE 3/28/2017

Type or print name M.Y. Merchant

E-mail address: mymerch@penrocoil.com

PHONE: 575-492-1236

For State Use Only

APPROVED BY: Mary Brown TITLE

AO/II

DATE 4/3/2017

Conditions of Approval (if any):