Submit I Copy To Appropriate District State of New Mexico	Form C-103
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 BBS OCD Minerals and Natural Resources	Revised July 18, 2013
	WELL API NO.
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 OIL CONSERVATION DIVISION 2018 1220 South St. Francis Dr.	30-023-41330
District III - (505) 334-6178 JUL 2 3 2018 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NRECEIVED 87505	o. State on the Gas Boase No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name ENCORE M STATE
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well Gas Well Other	8. Well Number 012
2. Name of Operator BREITBURN OPERATING LP	9. OGRID Number 370080
3. Address of Operator	10. Pool name or Wildcat 4 2228
1111 BAGBY STREET, SUITE 1600 HOUSTON, TEXAS 77002	WILDGAT GLORIETA
4. Well Location	
Unit Letter_K : 2264 feet from the SOUTH line and 1702	
Section 20 Township 22 S Range 37 F	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
5507 GD	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI	LLING OPNS.□ P AND A □
PULL OR ALTER CASING	ΓJOB □
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER:	<u> </u>
	d -i
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19 15 7 14 NMAC. For Multiple Con	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	npletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.	npletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.	npletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed:	npletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump	npletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP	npletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing	INDICATIONS: Attach wellbore diagram of MIT WELL-ROPE DIRECTAM SUBSEQUENT C-103.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement	npletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid	INDICATION OF Approval: notify
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing	Inpletions: Attach wellbore diagram of MIT WELLBORE DIAGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing	INDICATION OF Approval: notify
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head	Inpletions: Attach wellbore diagram of MIT WELLBORE DIAGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head	Inpletions: Attach wellbore diagram of MIT WELLBORE DIAGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT	MIT WELL-BORE DIAGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT	Inpletions: Attach wellbore diagram of MIT WELLBORE DIAGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT	MIT WELL-BORE DIAGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT	MIT WELL-ROPE DINGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT Spud Date: 1/29/2014 Rig Release Date: 2//	MIT WELL-ROPE DINGRAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT Spud Date: 1/29/2014 Rig Release Date: 2//	EMIT WELL-ROPE DIRECTAM SUBSEQUENT C-103. Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Conproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT Spud Date: 1/29/2014 Rig Release Date: 2// Thereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLE Sr. Production Forema	Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart DATE
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Conproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT Spud Date: 1/29/2014 Rig Release Date: 2// Thereby certify that the information above is true and complete to the best of my knowledge.	Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart DATE
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Conproposed completion or recompletion. Breitburn Operating proposes to TA this well, The following procedure is proposed: 1. MIRUPU, POOH and LD Rods and Pump 2. NDWH NU BOP 3. POOH w/Tubing 4. Make bit & scraper run 5. RIH w/CIBP on Tubing and set CIBP at 5079' cap with 25' cement 6. Circulate wellbore w/ clean 2% KCL and Packer fluid 7. POOH and LD Tubing 8. ND BOP and Flange up well head 9. Fill casing with packer fluid and notify NMOCD and run 500# MIT Spud Date: 1/29/2014 Rig Release Date: 2// CIPP Rig Release Date: 2// CIPP START	Condition of Approval: notify OCD Hobbs office 24 hours or of running MIT Test & Chart DATE