Office	State of New Mexico	Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-26114	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease	
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505 OCD TICES AND REPORTS ON HELS	5380 SS	
87505 SLINDRY NOT	TICES AND REPORTS ON WELS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPO	DOALS TO DOLL OF TO DEEDEN OF BLUG BACK ON A	CTATE (IDD)	
	ICATION FOR PERMIT" (FORM C-101) NOR SUCH	·	
PROPOSALS.)  1. Type of Well: Oil Well X	Gas Well Other	8. Well Number	
	Gas Well Other RECEIVED	003	
2. Name of Operator		9. OGKID Number	
CIMAREX ENERGY CO. OF CO. 3. Address of Operator	DLURADO	162683 10. Pool name or Wildcat	
600 N. MARIENFELD, SUITE 6	00. MIDLAND. TEXAS 79701	E. LUSK WOLFCAMP	
4. Well Location			
	660 feet from the NORTH line and 660	feet from the EAST line	
Section 16			
. Section 10	Township 19S Range 32E 11. Elevation (Show whether DR, RKB, RT, GR, etc.		
	3,653' - GR		
	7,000		
12 Check	Appropriate Box to Indicate Nature of Notice,	Report or Other Data	
12. Check	Appropriate Box to indicate Nature of Notice,	Report of Other Data	
NOTICE OF IN	NTENTION TO:	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X 🗨 REMEDIAL WOF	RK	
TEMPORARILY ABANDON		ILLING OPNS.□ P AND A	
PULL OR ALTER CASING	│ MULTIPLE COMPL     │ CASING/CEMEN	T JOB	
DOWNHOLE COMMINGLE			
OTHER:	□ OTHER:		
	pleted operations. (Clearly state all pertinent details, an	ed give partinent dates, including activitied date	
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagrams	
of starting any proposed w proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.	mpletions: Attach wellbore diagram of	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500'; PU	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C	mpletions: Attach wellbore diagram of the street of the st	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312'	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.).	mpletions: Attach wellbore diagram of the street of the st	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312' 3) PUMP 25 SXS. CMT. @ 5,685'	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.).	mpletions: Attach wellbore diagram of the street of the st	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312'- 3) PUMP 25 SXS. CMT. @ 5,685'- 4) CUT X PULL 5-1/2" CSG. @ +/	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.). /-4,000'.	mpletions: Attach wellbore diagram of the street of the st	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312'. 3) PUMP 25 SXS. CMT. @ 5,685'. 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117'.	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.).  /-4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC	mpletions: Attach wellbore diagram of the street of the st	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500'; PL 2) PUMP 25 SXS. CMT. @ 7,312'- 3) PUMP 25 SXS. CMT. @ 5,685'- 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117'- 6) PUMP 45 SXS. CMT. @ 2,433'-	York). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.).  -4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG.	mpletions: Attach wellbore diagram of the second se	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500'; PL 2) PUMP 25 SXS. CMT. @ 7,312': 3) PUMP 25 SXS. CMT. @ 5,685': 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117': 6) PUMP 45 SXS. CMT. @ 2,433': 7) PUMP 45 SXS. CMT. @ 1,532': 8) PUMP 40 SXS. CMT. @ 505'-4	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG.	mpletions: Attach wellbore diagram of the street of the st	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312'. 3) PUMP 25 SXS. CMT. @ 5,685'. 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117'. 6) PUMP 45 SXS. CMT. @ 2,433'. 7) PUMP 45 SXS. CMT. @ 1,532'. 8) PUMP 40 SXS. CMT. @ 505'-4 9) MIX X CIRC. TO SURF. 20 SX	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ SXS. CMT. PLUG.  JMP 25 SXS. CMT. @ SXS. CMT. PLUG.  JMP 26 SXS. CMT. @ SXS. CMT. PLUG.  JMP 26 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. CMT. @ SXS. CMT. PLUG.  JMP 26 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. CMT. @ SXS. CMT. PLUG.  JMP 26 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. CMT. @ SXS. CMT. PLUG.  JMP 26 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. CMT. @ SXS. CMT. PLUG.  JMP 26 SXS. CMT. @ SXS. CMT. PLUG.  JMP 27 SXS. C	See Attach wellbore diagram of See Attached  X TAG CMT. PLUG.	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312'. 3) PUMP 25 SXS. CMT. @ 5,685'. 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117'. 6) PUMP 45 SXS. CMT. @ 2,433'. 7) PUMP 45 SXS. CMT. @ 1,532'. 8) PUMP 40 SXS. CMT. @ 505'-4 9) MIX X CIRC. TO SURF. 20 SX	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 53-5/8" CSG.SHOE); WOC X-4,000'.  JMP 25 SXS. CMT. @ 53-6/8" CSG.SHOE); WOC X-74,000'.  JMP 26 SXS. CMT. @ 63-3'.  JMP 27 SXS. CMT. @ 63'-3'.  JMP 27 SXS. CMT. @ 63'-3'.  JMP 27 SXS. CMT. @ 63'-3'.  JMP 28 SXS. CMT. @ 63'-3'.  JMP 29 SXS. CMT. @ 63'-3'.  JMP 26 SXS. CMT. @ 63'-3'.  JMP 27 SXS. CMT. @ 63'-3'.  JMP 26 SXS. CMT. @ 63'-3'.  JMP 27 SXS. CMT. @ 63'-3'.	Attach wellbore diagram of See Attach wellbore diagram of See Attached See Attached X TAG CMT. PLUG.	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10) DIG OUT X CUT OFF WELLH	Cork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG.  8e Low Grown	ATTAC CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  A REAL COMMENTATION OF A PROPERTY OF A PROPERTY OF A PROPERTY OF A REAL COMMENTATION OF	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH DURING THIS PROCEDURE WE	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG.  Below Gelower	ATTAC CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  A REAL COMMENTATION OF A PROPERTY OF A PROPERTY OF A PROPERTY OF A REAL COMMENTATION OF	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10) DIG OUT X CUT OFF WELLH	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG.  Below Gelower	ATTAC CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  A REAL COMMENTATION OF A PROPERTY OF A PROPERTY OF A PROPERTY OF A REAL COMMENTATION OF	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH DURING THIS PROCEDURE WE	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG.  Below Gelower	ATTAC CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  A REAL COMMENTATION OF A PROPERTY OF A PROPERTY OF A PROPERTY OF A REAL COMMENTATION OF	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505".4 9) MIX X CIRC. TO SURF. 20 SX 10) DIG OUT X CUT OFF WELLH DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 10,500' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 10,5	ATTAC CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  A REAL COMMENTATION OF A PROPERTY OF A PROPERTY OF A PROPERTY OF A REAL COMMENTATION OF	
of starting any proposed w proposed completion or re 1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505".4 9) MIX X CIRC. TO SURF. 20 SX 10) DIG OUT X CUT OFF WELLH DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 10,500' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 10,5	ATTAC CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  A REAL COMMENTATION OF A PROPERTY OF A PROPERTY OF A PROPERTY OF A REAL COMMENTATION OF	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH  DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER  Spud Date:	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 10,500' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 10,5	See Attach wellbore diagrams (See Attach wellbore diagrams)  SIRC WELL W/ PXA FLUID.  OF APPOVAL  S. X INSTALL DRY HOLE MARKER.  A STEEL TANK AND HAUL CONTENTS	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH  DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER  Spud Date:	Cork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Co-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 20-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG. Be Low Colored PLAN TO USE THE CLOSED-LOOP SYSTEM W/ ACCORD RULE 19.15.17.  Rig Release Date:	A STEEL TANK AND HAUL CONTENTS	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH. DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER Spud Date:	Tork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Cocomplete Cocomple	A STEEL TANK AND HAUL CONTENTS  ge and belief.	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH  DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER  Spud Date:	Cork). SEE RULE 19.15.7.14 NMAC. For Multiple Cocompletion.  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); Co-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 20-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG. Be Low Colored PLAN TO USE THE CLOSED-LOOP SYSTEM W/ ACCORD RULE 19.15.17.  Rig Release Date:	A STEEL TANK AND HAUL CONTENTS	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH  DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER  Spud Date:  I hereby certify that the information	TITLE: AGENT  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG. Below Grown EPLAN TO USE THE CLOSED-LOOP SYSTEM W/ ACCORD RULE 19.15.17.  Rig Release Date:	See Attach wellbore diagram of See Attach wellbore diagram of See Attach of Approval  X TAG CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  MRR LPC AREA  A STEEL TANK AND HAUL CONTENTS  The see and belief.  DATE: 06/10/19	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312' 3) PUMP 25 SXS. CMT. @ 5,685' 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117' 6) PUMP 45 SXS. CMT. @ 2,433' 7) PUMP 45 SXS. CMT. @ 1,532' 8) PUMP 40 SXS. CMT. @ 505'-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH  DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER  Spud Date:  I hereby certify that the information  SIGNATURE  Type or print name: DAVID A. EY	TITLE: AGENT  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.). /-4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG. Below Ground CPLAN TO USE THE CLOSED-LOOP SYSTEM W/ ACCORD RULE 19.15.17.  Rig Release Date:	See Attach wellbore diagram of See Attach wellbore diagram of See Attach of Approval  X TAG CMT. PLUG.  S. X INSTALL DRY HOLE MARKER.  MRR LPC AREA  A STEEL TANK AND HAUL CONTENTS  The see and belief.  DATE: 06/10/19	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500"; PU 2) PUMP 25 SXS. CMT. @ 7,312". 3) PUMP 25 SXS. CMT. @ 5,685". 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117". 6) PUMP 45 SXS. CMT. @ 2,433". 7) PUMP 45 SXS. CMT. @ 1,532". 8) PUMP 40 SXS. CMT. @ 505"-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH  DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER  Spud Date:  I hereby certify that the information	JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.). /4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG. Be Low Gound EPLAN TO USE THE CLOSED-LOOP SYSTEM W/ ACCORD RULE 19.15.17.  Rig Release Date:  TITLE: AGENT  CLER  E-mail address: deyler@milagro.	A STEEL TANK AND HAUL CONTENTS  DATE: 06/10/19  PHONE: 432.687.3033	
of starting any proposed we proposed completion or re  1) SET 5-1/2" CIBP @ 10,500'; PU 2) PUMP 25 SXS. CMT. @ 7,312' 3) PUMP 25 SXS. CMT. @ 5,685' 4) CUT X PULL 5-1/2" CSG. @ +/ 5) PUMP 40 SXS. CMT. @ 4,117' 6) PUMP 45 SXS. CMT. @ 2,433' 7) PUMP 45 SXS. CMT. @ 1,532' 8) PUMP 40 SXS. CMT. @ 505'-4 9) MIX X CIRC. TO SURF. 20 SX 10)DIG OUT X CUT OFF WELLH  DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER  Spud Date:  I hereby certify that the information  SIGNATURE  Type or print name: DAVID A. EY	TITLE: AGENT  JMP 25 SXS. CMT. @ 10,500'-10,300' (T/WCMP.); C-7,142' (T/BNSG.)5,535' (T/DLWR.)4,000'3,950' (5-1/2" CSG.CUT, 8-5/8" CSG.SHOE); WOC 2-2,313' (B/SALT); WOC X TAG CMT. PLUG1,422' (T/SALT); WOC X TAG CMT. PLUG. 05' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. S. CMT. @ 63'-3'. HEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSG. Below Grown EPLAN TO USE THE CLOSED-LOOP SYSTEM W/ ACCORD RULE 19.15.17.  Rig Release Date:	A STEEL TANK AND HAUL CONTENTS  DATE: 06/10/19  PHONE: 432.687.3033	



rstock

TOC @ 4115'

90 sx Cmt Plut 11,400'-600'

100 sx Cmt Plug 12,383'-583'

Cimarex Energy Co. of Colorado State DR #3

API 30-025-26114

660' FNL & 660' FEL, Sec 16, T19S R32E

Lea County, NM

GL: 3629" KB: 3654' (25')

30-025-26/14

13-3/8" 48#, H40, STC csg @ 455' 400 sxs; Circl'd Cmt

8-5/5" 32# K55 STC csg @ 4,047' 3100 sxs; Circl'd Cmt

**Tubing Detail** State DR #3

Ran 11/10

KB Correction

Quantity	Description	Length	Setting Depth
337	2-7/8" 6.5# N-80	10480.00	10505.00
1	5-1/2" TAC	2.80	10507.80
9	2-7/8" 6.5# N-80	311.29	10819.09
1	2-7/8" SN	1.10	10820.19
1	2-7/8" Perf Sub	4.08	10824.27
1	2-7/8" BPMA	30.45	10854.72
			10854.72

## **Rod Detail**

Quantity	Description	Length	Setting Depth
1	1"-1/4" PR	26.00	16.00
11	Pony Rods	4.00	20.00
99	1" Norris Rods	2475.00	2495.00
102	7/8" Norris Rods	2550.00	5045.00
109	3/4" Norris Rods		
16	1" Norris Rods		
1	Release Tool		
1	2-1/2" x 1-1/4" x 24' RHBM		

Wolfcamp Perfs:

10,530'-38', 10,608'-14' & 10,634'-54' (7/85)

10,732'-54' & 10,762'-74' (6/82)


10,721'-728' (1/79)

5-1/2" 23/26/29#, N80/S95 LTC csg @ 11,100' 1,720 sxs; TOC @ 4,115

PBTD:

TD: 12,971'

M. Ketter 2/27/2013



## **GENERAL CONDITIONS OF APPROVAL:**

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.