Submit I Copy To Appropriate District Office	State of New !		Form C-103 Revised July 18, 2013
<u>District I</u> - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and N	aturat Resources	WELL API NO.
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	ON DIVISION	30-025-01425
District III - (505) 334-6178	1220 South St. F		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM	87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-2229
SUNDRY NOT	TICES AND REPORTS ON WEL		7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR JICATION FOR PERMIT" (FORM C-101		State F TG
PROPOSALS.)	·	, 	8. Well Number
1. Type of Well: Oil Well 2. Name of Operator	Gas Well Other	iss ocu	9. OGRID Number
Co	onocoPhillips Company		217817
3. Address of Operator	FEI ox 2197 Houston TX 77252	B I I SASA	10. Pool name or Wildcat
4. Well Location	7X 2197 HOUSTON 1X 7/252	CFIVED	Vacuum Grayburg San Andres
Unit Letter E:	2310 feet from the North		660feet from theWest line
Section 36	Township 17-S	Range 33-E	NMPM County Lea
	11. Elevation (Show whether I		
· · · · · · · · · · · · · · · · · · ·	41:	28' RT	
12 Chark	Annroprieto Poy to Indicate	Noture of Notice	Panart or Other Date
	Appropriate Box to Indicate) ~ w.	
	NTENTION TO:		SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON		REMEDIAL WOR	RK ☐ ALTERING CASING ☐ ☐
PULL OR ALTER CASING	- -	CASING/CEMEN	
DOWNHOLE COMMINGLE			_
CLOSED-LOOP SYSTEM)	OTUED.	
OTHER: 13. Describe proposed or com	pleted operations. (Clearly state a	OTHER:	nd give pertinent dates, including estimated date
of starting any proposed v	vork). SEE RULE 19.15.7.14 NM		empletions: Attach wellbore diagram of
proposed completion or re	ecompletion.		
MIRU	I. ND WH, NU BOP. POOH Prod	Equipment	
Set CI	BP @ 4368'. Circ hole w/ MLF.	Pressure test casing.	
	'0sx cmt @ 4368' – 3726'. WOC- 25sx cmt @ 2700' – 2580'. WOC-		Co Sec
	25sx cmt @ 2700 - 2580 . WOC- 25sx cmt @ 1700' - 1500'. WOC-		Onding Att.
Perf &	2 Sqz 40 sx 1483'-1363' Tag	J	HONS CACHE
	z Sqz 25sx cmt @ 60' – 3' I. Fill wellbore. Verify cmt @ surf	face in all annuli	OFAn
Cut of	If WH & anchors, Install DH mark	er	POPOVA
			Conditions of Approval
			•
A closed-loop system	will be used for all fluids from this	wellbore and disposed	of required by OCD Rule 19.15.17
<u> </u>			
Spud Date:	Rig Release	Date:	
		L	
I hereby certify that the information	n above is true and complete to th	e hest of my knowled	ge and helief
	_		
SIGNATURE	TITLE_Ag	ent – Basic Energy S	ervices DATE 2/12/20
· · · ——	omero E-mail address:		PHONE:432-563-3355
For State Use Only	1 4 ~	•	
APPROVED BY:	y forther TITLE (- 0	H DATE 3-5-70
Conditions of Approval (if any):	<i>-</i>		

WELLBORE SKETCH ConocoPhilips Company -- Permian Basin Business Unit

KB @	4129'					Date: 1/15/2020
DF @	4129'	Subarea :	Buckeye	Waet		
		Lease & Well No		State F	rg 4	
		Legal Descriptio		Sec 36 F -	T 17 S - R- 33 E	SW NW
8el	1 13	County:	LEA	<u> </u>		New Mexico
	111	Field :	Vacuum			TOW IDOXICO
		Date Spudded :	Vadami	3/9/1955		
3	Surface	API Number :	30025014			
	8-5/8", 24#/ft to 1505'	ra i namos :	00020014			
	Cmt'd w/ 400 SX		——		Operator Num	ther
ົ1⊗	TOC - Circ'd to surface				Lease ID:	
					Field Number:	•
					r icia realitaci.	•
 						
	Production					
	322					
	5-1/2", 24#/ft to 4584'					
	Cmt'd w/ 250 SX					
▧	TOC - 1505' by TS					
33						
33	Mi Mi					
₩						
	i i i i i i i i i i i i i i i i i i i					
※						
500	<u> </u>					
=	- Grayburg Perfd					
=	= 4468' - 4539'					
888						
	San Andres					
	Open Hole_ 4584' - 4679'					
	M.					
7 ,	7 ,					
4						
9	[2]					
3/1	21					
74	5))					
	<i>(</i> 9)					
	TD @ 4679',					
	, 14					

WELLBORE SKETCH ConocoPhillips Company – Permian Basin Business Unit

RKB @ 4129	<u> </u>
DF @ 4129' GL @ 4119'	_
	-
*	P/S 25 ax 60'-3'
	P/S 40 ex 1483'-1383' Teg Surface
	8-5/8", 24#/ft to 1505'
	Cmt'd w/ 400 SX
	TOC - Circ'd to surface 25 sx 1700'-1500' Teg
	Production
	5-1/2", 24#/ft to 4584' Cmt'd w/ 250 SX
	TOC - 1505' by TS
	· · · · · · · · · · · · · · · · · · ·
	25 ex 2700'-2580' Tag
	20 8X 8100 -2000 14g
	70 ex 4368'-3728' Tag
XXX	CIBP 4368'
	0
	Grayburg Perfd 4468' - 4539'
	_
	San Andres Open Hole_ 4584' - 4679'
56 56	
ା ପାଁ	
	ļ
(4)	TD @ 4679'.

				Date: 1/15/2020
Subarea :	Buckeye 1	West		
Lease & Well No	o. :	State F TG 4		
Legal Description	n:	Sec 36 E - T 17 S - R- 33	E	SW NW
County:	LEA	Stat	B:	New Mexico
Field :	Vacuum			
Date Spudded:		3/9/1955		
API Number :	300250142	25		
	Operator Number: Lease ID: Field Number:			

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify **NMOCD District Office I** (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least 1/4" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION