Submit I Copy To Appropriate District Office	State of New Me	xico	Form C-103			
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-025-03051			
811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	f t l'a T			
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		CD STATE S FEE			
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	(505) ADD 9 9 9 9	6. State Oil & Gas Lease No.			
87505		APR 2 2 202				
SUNDRY NOT	ICES AND REPORTS ON WELLS	Dan	7. Lease Name or Unit Agreement Name			
DIFFERENT RESERVOIR. USE "APPLI	SALS TO DRILL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FORM C-101) FO	RSUCIOEIVE	Vacuum Abo Unit Tr 13			
PROPOSALS.)	Gas Well Other - INJECTI		8. Well Number 014			
1. Type of Well: Oil Well	9. OGRID Number					
2. Name of Operator ConocoPhillips Company			217817			
3. Address of Operator			10. Pool name or Wildcat			
PO Box 2197 Houston TX 77252			Vacuum; (Abo Reef)			
4. Well Location						
Unit LetterH:_	1650feet from theNorth_	line and6	60feet from theEastline			
Section 4	Township 18-S Ran	· Y	NMPM County Lea			
	11. Elevation (Show whether DR,	,				
	3935'	GR				
12 Charle	A	······································	n Od. D.			
12. Check	Appropriate Box to Indicate Na	ature of Notice,	Report or Other Data			
NOTICE OF IN	ITENTION TO:	SUBS	SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING						
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII				
PULL OR ALTER CASING DOWN IN COMMINC COMMING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗆			
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM						
OTHER:		OTHER:	п			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
		. For Multiple Con	npletions: Attach wellbore diagram of			
proposed completion or rec	ompletion.					
MIRU.	ND WH, NU BOP. POOH Prod Equ	uipment				
a contract of contract						
	5 sx @ 6700'-6600'					
Spot 25	Spot 25 sx @ 5439'-5319'					
Spot 25sx cmt @ 4779'-4659'. WOC-Tag						
Spot 50sx cmt @ 4373'-3960' Spot 40sx cmt @ 3278'-2938'. WOC-Tag						
Perf/Sqz 40sx cmt @ 1653'-1533'. WOC-Tag						
Perf/Sqz 110sx cmt @ 358'-3'.						
POOH. Fill wellbore. Verify cmt @ surface in all annuli						
Cut off	WH & anchors. Install DH marker		Conditions of Approval			
A closed-loop system	will be used for all fluids from this wel	lbore and disposed o	f required by OCD Rule 19.15.17			
Spud Date:	Rig Release Da	te:				
I hereby certify that the information	above is true and complete to the be	et of my knowledge	and belief			
Thereby certify that the information		st of my knowledge	, and benefit.			
SIGNATURE	TITLEAgent	– Basic Energy Sei	rvicesDATE4/20/20			
Type or print name Greg Bry	ant E-mail address:		PHONE:432-563-3355			
For State Use Only			Λ			
APPROVED BY: Now 3	orther TITLE (\mathcal{O}_{-}	A DATE \$ 4/24/20			
Conditions of Approval (if ary):	·					

WELLBORE SKETCH ConocoPhillips Company -- Lower 48 - Mid-Continent BU

byn a 10	140			De	ite <u>3/26/2020</u>
DF @ 39	346' 346'				
GL @ 39	35'		Subarea	Buckeye	
			Lease & Well No. :		13-14W
1	1		Legal Description :	Section 4H_ T-18S_R - 35E_165	
		13-3/8" 48# H-40 @ 308'	County:	Loa State: Ne	w Mexico
		175 sxs circ, TOC at surface	Field : Date Spudded :	Vacuum (Abo Reef) 6/23/1961	
			API Number : 30-025-		
			Status:		· · · · · · · · · · · · · · · · · · ·
1111	1111				
1111					
1111		0.50*3/# 1.55 @ 3105			
		8-5/8° 24# J-55 @ 3105° 1250 sxs. TOC @ Surface			
		1250 535, 100 @ 301800			
-					
1111					
1111	1111				
1111					
	1111				
'111'					
111					
111					
111					
111					
. []					
111					
		5 4 M 4 5 5 M 4 6 M 7 4 M			
111		5-1/2" 15.5# ,F55 @ 9100" 960 5xs, TOC @ 3100"			
		800 Std, 100 @ 3100			
	회				
11	- 11				
11					
 	ii =≉AboF	Reef Perfs - 8,774' - 8960'			
		en perfs to 8860"			
	==				
**	**				
22	20 20				
==	**				
**	20				
	22				
= =	23				
**					
**					
**	••				
# 2	E =				
==	*=				
**	==				
••	62				
22	62				
₽-	4 11/31	/1968			
) -	Sque	ezed			
	8874	- 0 100 0			
	177				
]]					
- 11	DOTE) - 9 056'			
 	TD -	7 - 5030 B100			
1.1	1 1,0.5				

WELLBORE SKETCH ConocoPhillips Company -- Lower 48 - Mid-Continent BU

RKB @ 3946' DF @ 3935' GL @ 3935' 13-3/8" 48# H-40 @ 308" 175 sxs circ, TOC at surface P&S 110sz cmt @ 358'-3" 8-5/8" 24# J-55 @ 3105' 1250 sxs, TOC @ Surface P&8 40sx.cmt @ 1853;-1533' - Tag Spot 40sx cmt @ 3278'-2938' - Tag ³5-1/2" 15.5# J-55 @ 9100' §960 axs, TOC @ 3100' Spot 50sx cmt @ 4373'-3960' Spot 25sx cmt @ 4779'-4659' - Tag Spot 25sx cmt @ 5439'-5319' Spot 26sx cmt @ 6700'-6600' Spot 25sx cmt @ 8674'-8574' Set CIBP @ 8674" 25 20 20 20 == Abo Reef Perfs - 8,774' - 8960' == ** Open perfs to 8860' == == 22 11/31/1968 Squeezed 8874' - 8960' PBTD - 9056' TD - 9100,

Subarea :	Buckeye
Lease & Well No.	Vacuum Abo Unit No. 13-14W
Legal Description	Section 4H_ T-18S_ R - 35E 1650 FNL 660 FEL
County.	Lea State : New Mexico
Field :	Vacuum (Abo Reef)
Date Spudded :	6/23/1961
API Number: 30-02	5-03051
Status	

Date 3/26/2020

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
 - 11. Class 'C' cement will be used above 7500 feet.
 - 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION