

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

HOBBS OFFICE O. O. O.
 NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

Nov 21 8 27 AM '66

6a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator Sunray DX Oil Company	8. Farm or Lease Name Nancy Watson
3. Address of Operator P. O. Box 1416, Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER X 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 8S RANGE 34E N.M.P.M.	10. Field and Pool, or Wildcat CL San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4314' GR	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING OTHER

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
 CASING TEST AND CEMENT JOB
 OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Present PBTB @ 4650'.
- Top of cmt behind 4 1/2 prod csg @ approx 3850'. 13 3/8" surf csg set @ 362' w/335 sxs cmt circulated to surface. 8 5/8" intermediate surf csg set @ 4100' w/785 sxs cmt circulated to surface. 4 1/2" prod csg set @ 4680' w/160 sx cmt. Perfs @ 4570-76' and 4600-12'.
- Load hole w/mud.
- Place 25 sxs cmt plug (3350-4650) to cover perfs.
- Cut off 4 1/2" prod csg @ approx 3700'. Pull prod. csg. Keep hole loaded w/mud.
- Place 25 sxs cmt (3680-3740') in & out of 4 1/2" sub.
- Place 10 sxs cmt @ surface.
- Install dryhole marker.
- Remove surface equipment & clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.F. Brawley **B.F. Brawley** TITLE District Engineer DATE 11-17-66

APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: