

N. M. OIL CONS. COMMISSION

F. BOX 1980

UNITED STATES OF NEW MEXICO 88240 IN TRIPLICATE
DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

GEOLOGICAL SURVEY

Form approved
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-082

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rider Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lynch

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 27-T20S-R34E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Temporarily Abandoned

2. NAME OF OPERATOR

Burk Royalty Co.

3. ADDRESS OF OPERATOR

P. O. Box BRC, Wichita Falls, TX 76307

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also Space 17 below.)
At surface

2310' FNL & 467' FEL of Sec. 27

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3695' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETION ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

(Other) ☐

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Purpose to plug and abandon - May 10, 1983

Well data: Casing - 4 1/2" PBTD 3570'.

Original perfs: 3560'-3744'. Squeezed perfs. with 150 sacks and drilled out to 3570'.

Reperforate 3562'-70'. Well T.A.

Proposed Procedure: Set cement retainer with

2" tubing at 3362', squeeze with 100 sacks.

Pull out of retainer. Pump 10 sacks with tubing set at 100'. Circulate cement. Pull tubing out of hole.

additional plug!

* Because this well is in Secretary Potash area you need a 300' cmt. plug (1890'-1590'). P.W.C.

RECEIVED

APR 14 1983

OIL & GAS
MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Fred M. Lynch
Fred M. Lynch

TITLE

Petroleum Engineer

DATE

April 11, 1983

(This space for Federal or State Agency Use)

APPROVED (Or, Sec.) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 22 1983

RECEIVED
APR 25 1983
C.D.O.
HOBBS OFFICE