Submit 3 Copies To Appropriate Di Office	ostrict Sta		
		tte of New Mexico	Form C-
District I	Energy, Mir	nerals and Natural Resources	Revised March 25,
1625 N. French Dr., Hobbs, NM 88 District II	8240		WELL API NO.
1301 W. Grand Ave., Artesia, NM	88210 OIL CONS	SERVATION DIVISION	30-025-03992
District III	1220	South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 8' District IV	1/410		STATE FEE
1220 S. St. Francis Dr., Santa Fe, N	Sai M	nta Fe, NM 87505	6. State Oil & Gas Lease No.
87505			
SUNDRY (DO NOT USE THIS FORM FOR	NOTICES AND REPOR	TS ON WELLS	7. Lease Name or Unit Agreement Na
DILLEKTIAL KESEKAOIK OSE	"APPLICATION FOR PERMIT	O DEEPEN OR PLUG BACK TO A "(FORM C-101) FOR SLICH	
TROTOSALS.)		(- Same O POLITOR BOCH	Northwest Eumont Unit
 Type of Well: Oil Well Gas Well 	1		
2. Name of Operator Rh	Ombus Operating Co.	144	
- rame or Operator Kil	iominus Obetating Co.	, Lta.	8. Well No. #101
3. Address of Operator			0.7
200	0 N. Loraine, Suite 127	70, Midland, Texas 79711	9. Pool name or Wildcat
4. Well Location		-,	Eumont Yates
Unit Letter:	1,980 feet from the	e South line and	660 feet from the East line
Section 11			ine Last line
Section 11		hip 19-S Range 36	-E NMPM County Lea
	10. Elevation (S)	how whether DR, RKB, RT, GR,	etc.)
11. Cho	eck Appropriate Roy t	to Indicate Nature of Notice	Donard as City
NOTICE O	OF INTENTION TO:	O INOTICE OF MOUNT OF	C, REPORT OF Other Data
PERFORM REMEDIAL WOR	RK PLUG AND ABAN	IDON REMEDIAL WO	BSEQUENT REPORT OF:
			DRK ALTERING CASING
EMPORARILY ABANDON	☐ CHANGE PLANS	☐ COMMENCE D	RILLING OPNS. PLUG AND
PULL OR ALTER CASING	☐ MULTIPLE		ABANDONMENT
	COMPLETION	CASING TEST CEMENT JOB	AND
)THFR			
OTHER: Describe proposed or com	pleted operations. (Clearl	OTHER:	give pertinent dates, including estimated dat
. Describe proposed or com	apleted operations. (Clearl k). SEE RULE 1103. For	ly state all pertinent details, and	give pertinent dates, including estimated dat wellbore diagram of proposed completion or
Describe proposed or comstarting any proposed work recompilation. /01/02 Notified OCD, Bude	ldy Hill. MIRU Triple N	y state all pertinent details, and g Multiple Completions: Attach v #25 and plugging equipment.	wellbore diagram of proposed completion or NU BOP, SDFN.
Describe proposed or comstarting any proposed work recompilation. /01/02 Notified OCD, Buddon 102/02 RIH w/ tbg to 3,850 aged cmt @ 3,708'. Pumperson 102/02/02 Pumperson 102/03/03/03/03/03/03/03/03/03/03/03/03/03/	ldy Hill. MIRU Triple N a 0', tagged PBTD. Loade	y state all pertinent details, and g Multiple Completions: Attach v #25 and plugging equipment.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and
Describe proposed or comstarting any proposed work recompilation. /01/02 Notified OCD, Buddon (02/02 RIH w/ tbg to 3,850 aged cmt @ 3,708'. Pumperson (1984).	ldy Hill. MIRU Triple N a 0', tagged PBTD. Loade	y state all pertinent details, and g Multiple Completions: Attach v #25 and plugging equipment.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and
Describe proposed or complete starting any proposed work recompilation. /01/02 Notified OCD, Buddon 1/02/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumper t @ 1,350'. RIH w/ tbg and the management of the managem	ldy Hill. MIRU Triple N a 0', tagged PBTD. Loade ped 25 sx C cmt 2,822 - nd pumped 30 sx C cmt	y state all pertinent details, and y Multiple Completions: Attach versions and plugging equipment. Head hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, pure state of the pumped 2 sx C cmt 407 - 262'.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60 to surface. RDM
Describe proposed or comstarting any proposed work recompilation. 701/02 Notified OCD, Buddon 102/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpet @ 1,350'. RIH w/ tbg and	ldy Hill. MIRU Triple N a 0', tagged PBTD. Loade ped 25 sx C cmt 2,822 - nd pumped 30 sx C cmt	y state all pertinent details, and g Multiple Completions: Attach v #25 and plugging equipment.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60 to surface. RDM
Describe proposed or complete starting any proposed work recompilation. /01/02 Notified OCD, Buddon 1/02/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumper t @ 1,350'. RIH w/ tbg and the management of the managem	ldy Hill. MIRU Triple N a 0', tagged PBTD. Loade ped 25 sx C cmt 2,822 - nd pumped 30 sx C cmt	y state all pertinent details, and y Multiple Completions: Attach versions and plugging equipment. Head hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, pure state of the pumped 2 sx C cmt 407 - 262'.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60 to surface. RDM
Describe proposed or comstarting any proposed work recompilation. 701/02 Notified OCD, Buddon 102/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpet @ 1,350'. RIH w/ tbg and	ldy Hill. MIRU Triple N a 0', tagged PBTD. Loade ped 25 sx C cmt 2,822 - nd pumped 30 sx C cmt	y state all pertinent details, and y Multiple Completions: Attach versions and plugging equipment. Head hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, pure state of the pumped 2 sx C cmt 407 - 262'.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60' to surface. RDM
Describe proposed or comstarting any proposed work recompilation. 701/02 Notified OCD, Buddon 102/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpet @ 1,350'. RIH w/ tbg and	ldy Hill. MIRU Triple N a 0', tagged PBTD. Loade ped 25 sx C cmt 2,822 - nd pumped 30 sx C cmt	y state all pertinent details, and y Multiple Completions: Attach versions and plugging equipment. Head hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, pure state of the pumped 2 sx C cmt 407 - 262'.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60' to surface. RDM
Describe proposed or complication. 701/02 Notified OCD, Budden Complication. 702/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumper t @ 1,350'. RIH w/ tbg and 109/02 Cut off wellhead and 109/02 Cut off wellhead and 109/03 Cut o	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will be a state of the	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and t 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60 to surface. RDM ors.
Describe proposed or comstarting any proposed work recompilation. O1/02 Notified OCD, Buddon 102/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpot @ 1,350'. RIH w/ tbg and 1,350'. RIH w/ tbg and 1,350'. Cut off wellhead and 1,350'.	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and y Multiple Completions: Attach versions and plugging equipment. Head hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, pure state of the pumped 2 sx C cmt 407 - 262'.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60 to surface. RDMc ors.
Describe proposed or comstarting any proposed work recompilation. 01/02 Notified OCD, Buddon Described and Descri	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will also and plugging equipment. ed hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, put pit and cellar, removed anch applete to the best of my knowledge.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60' to surface. RDMc ors.
Describe proposed or comstarting any proposed work recompilation. O1/02 Notified OCD, Buddon O2/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpot @ 1,350'. RIH w/ tbg and 09/02 Cut off wellhead and one of the certify that the information of the certification	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will be a state of the	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60 to surface. RDMc ors.
Describe proposed or comstarting any proposed work recompilation. O1/02 Notified OCD, Buddon O2/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpet @ 1,350'. RIH w/ tbg and O9/02 Cut off wellhead and one of the corprint name.	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will also and plugging equipment. ed hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, put pit and cellar, removed anch applete to the best of my knowledge.	NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60' to surface. RDMc ors. Be and belief. DATE
Describe proposed or complication. /01/02 Notified OCD, Buddy /02/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpert @ 1,350'. RIH w/ tbg and /09/02 Cut off wellhead and reby certify that the information.	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will also and plugging equipment. ed hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, put pit and cellar, removed anch aplete to the best of my knowledge. TITLE Engineer	give pertinent dates, including estimated date wellbore diagram of proposed completion or NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60' to surface. RDMC ors. 26 and belief. DATE 08/10/02 Telephone No. 915-687-19
Describe proposed or complication any proposed work recompilation. /01/02 Notified OCD, Buddon (02/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpert @ 1,350'. RIH w/ tbg and (09/02 Cut off wellhead and (19/04) certify that the information of print name (19/04) James space for State use)	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will be a plugging equipment. 25 and plugging equipment. 26 hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, put pit and cellar, removed anch aplete to the best of my knowledged	give pertinent dates, including estimated date wellbore diagram of proposed completion or NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60' to surface. RDMC ors. DATE 08/10/02 Telephone No. 915-687-19
Describe proposed or complication any proposed work recompilation. /01/02 Notified OCD, Buddon (02/02 RIH w/ tbg to 3,850) Iged cmt @ 3,708'. Pumpert @ 1,350'. RIH w/ tbg and (09/02 Cut off wellhead and (19/04) Exercise certify that the information of the proposed work recompilation.	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will be a plugging equipment. 25 and plugging equipment. 26 hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, put pit and cellar, removed anch aplete to the best of my knowledged	25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60 to surface. RDMC ors. DATE 08/10/02 Telephone No. 915-687-19
Describe proposed or complication any proposed work recompilation. /01/02 Notified OCD, Buddon (02/02 RIH w/ tbg to 3,850 ged cmt @ 3,708'. Pumpert @ 1,350'. RIH w/ tbg and (09/02 Cut off wellhead and (19/04) certify that the information of print name (19/04) James space for State use)	ldy Hill. MIRU Triple N and the state of the	y state all pertinent details, and a Multiple Completions: Attach we will also and plugging equipment. ed hole w/ mud and pumped 2 2,677'. Pumped 25 sx C cmt 407 - 262'. POOH w/ tbg, put pit and cellar, removed anch aplete to the best of my knowledge. TITLE Engineer	give pertinent dates, including estimated date wellbore diagram of proposed completion or NU BOP, SDFN. 25 sx C cmt 3,850 – 3,705'. WOC and 1,550 – 1,288'. WOC 2 hrs and tagged mped 10 sx C cmt 60' to surface. RDMC ors. DATE 08/10/02 Telephone No. 915-687-19