

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>John H. Hendrix</b>	8. Farm or Lease Name <b>Alaska Cooper</b>
3. Address of Operator <b>316 Central Bldg., Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> SECTION <b>12</b> TOWNSHIP <b>20S</b> RANGE <b>36E</b> NMPM.	10. Field and Pool, or Wildcat <b>Monument (G-BA)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3547 (GR estm.)</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Proposed Rework Operations - Alaska Cooper No. 1**

- (1) Cleanout to 3780' and run Gamma Ray-Neutron Log.
- (2) Selectively perforate with 10 holes from approximately 3700' to 3730'.
- (3) Set CIBP at approximately 3735' and acidise perforated interval with 1000 gallons 15% LSTNE acid.
- (4) Swab test for evaluation of work.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John H. Hendrix TITLE Owner-Operator DATE 2/20/69

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: