

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002505655
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1589-1
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 6
8. Well No.	6
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
AMERADA HESS CORPORATION

3. Address of Operator
POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265

4. Well Location
Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST Line
Section 20 Township 19S Range 37 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #606
Plan To
Move in and rig up pulling unit, reverse unit and air unit. TOH with rods and pump. Nipple down wellhead. Nipple up BOP. Shut-in well overnight. TIH w/Amerada Bomb and obtain static bottomhole pressure. TOH w/tubing. TIH w/4-3/4" bit on drill collars and 2-7/8" tubing. Clean out openhole to TD (3,995' MD). Drill out an additional 10'. TOH w/bit and tubing. Rig up Schlumberger. TIH and log openhole with GR/LDT log. TOH w/tools. Rig down Schlumberger. Rig up acid company. TIH w/tubing open ended and spot acid on bottom of openhole. TOH w/tubing. TIH w/packer and tubing to 3,850'. Acidize well with 5,000 gals. 15% NEFE DI HCL. Swab/flow back load. Swab/flow test well. Obtain oil water and gas samples for analysis. TOH w/tubing and packer. TIH w/tubing. Nipple down BOP. Nipple up wellhead. TIH w/rods and pump. Rig down and move out pulling unit. Pump test well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 02-01-94
TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FEB 16 1994