

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

O+2 - NMOC-D-P.O. Box 1980

Hobbs, NM 88240

1 - Engr. DW

1-Laura Richardson-Midland

1 - Foreman

1 - File

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-1330

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name Skelly E State
3. Address of Operator P.O. Box 730 Hobbs, NM 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>19-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Eun-Mon (GB-SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3535' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit. Install BOP.
2. Pull rods, pump, and 2 7/8" tubing.
3. Rig up air and foam unit supplied by Foam Air of Odessa.
4. Clean out open hole section 3809-3970' with air and foam. Attempt to remove all fill (sand) from the wellbore.
5. Rig down air and foam unit.
6. Run tubing, pump, and rods.
7. Put well on production and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett TITLE Area Superintendent DATE September 4, 1980

APPROVED BY Dale R. Crockett

JERRY SEXTON

DISTRICT 1 SUPERVISOR

TITLE _____ DATE OCT 7 1980

CONDITIONS OF APPROVAL, IF ANY: