

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088DISTRICT II
P.O. Drawer DD, Aracata, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-05747
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1533
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 10
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265	4. Well Location Unit Letter <u>E</u> 1980 Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>30</u> Township <u>19S</u> Range <u>37E</u> NMPM <u>LEA</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☒	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in and rig up pulling unit and reverse unit. TOH with rods and pump. ND wellhead. NU BOP. TOH with tubing. RU Schlumberger and perforate with 3 3/8" casing gun from 3,800'-3,850' with 2 SPF 280 deg. phased (50 feet, 101 holes total). RD Schlumberger. RU acid company. Trip in hole with sonic hammer on tubing. Acidize well with 5,000 gals. 15% NEFE DI HCL w/3% DP-77MX Micellar solvent. Move tool across perfs and openhole from 3,800'-3,904' throughout acid job. RD acid co. Trip out of hole with sonic hammer. Trip in hole with tubing and packer. Set packer at ±3,750'. Swab back load. Trip out of hole with tubing and packer. Trip in hole with prod tubing. Nipple down BOP. Trip in hole with rods and pump. Nipple up wellhead. Rig down and move out pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 04-25-95
TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ DATE MAY 01 1995
CONDITIONS OF APPROVAL, IF ANY: _____