

# WORKOVER PROCEDURE

DATE: July 13, 1988

WELL NO. & TYPE OF JOB: BERTHA J. BARBER #20  
Repair Casing Leak

LOCATION: 990' ESL & 660' FEL SEC 7, T20S, R37E

DRILLED & COMPLETED: 04-01-56 LAST WD: 06-01-88

FIELD: Monument Paddock COUNTY: LEA, NM. PREPARED BY: A. E. Burdick

TD: 5,698' PBD: 5200' DATUM: GL= 3548'

## CASING INFORMATION:

	SIZE	WEIGHT	GRADE	SET @	SX CMT	IDC
SURFACE:	13-3/8"	48#	H-40	945'	1000	surface
INTERMEDIATE:	9-5/8"	36#	J-55	2898'	1500	surface
PRODUCTION:	7"	23#	J-55	5697'	300	3690' (temp surv)

Liner: Size \_\_\_\_\_ WT. \_\_\_\_\_ TOP \_\_\_\_\_ BOTTOM \_\_\_\_\_ TOC \_\_\_\_\_

## PRESENT PERFORATIONS & FORMATION:

ACTIVE PERFS: NONE

INACTIVE PERFS: Paddock 5,165' - 5,198' (CIBP SET ABOVE PERFS)

## PROCEDURE

1. Notify NMCCC to witness Remedial work. (Bonnie or Eddy C. @ 505-393-6161)
2. R.U.P.U. ND Wellhead and NU BOP (one joint of tubing in the hole).
3. TIH w/ packer and Test CIBP to 500 psi. Isolate bad casing. Establish injection rate. Attempt to break circulation back to surface. Release packer and POH.
4. If necessary, R.U. Western Atlas and run Vertilog from CIBP above perfs to surface. Consult Midland with results prior to continuing.