

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-12471
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-869-2
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 14
8. Well No.	11
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
AMERADA HESS CORPORATION

3. Address of Operator
POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265

4. Well Location

Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The WEST Line

Section 36 Township 19S Range 36E N-M-P-M LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER: Convert to injection well.

SUBSEQUENT REPORT OF:

- PLUG AND ABANDON
- CHANGE PLANS
- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- OTHER:
- ALTERING CASING
- PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1411

R-9596

Move in and RU pulling unit, reverse unit. ND wellhead. TOH and lay down rods and pump. ND wellhead. NU BOP. TOH w/tubing. TIH w/RBP and set at ±500'. Install new wellhead equipment. Retrieve RBP. TIH w/bit, drill collars and tubing. Clean out to TD at 3,905'. TOH w/bit. TIH w/underreamer, drill collars and tubing and underream openhole. TOH w/underreamer. RD air unit. RU Schlumberger and log the openhole w/Sonic/LDT/CNL/GR tools. Evaluate logs for additional perforations. Perforate as needed. RD Schlumberger. Rig up cementers. TIH w/tbg. open ended and spot cement plug from 3,905' to 3,870'. WOC 24 hours. TIH w/a sonic hammer on tubing to TD. RU acid co. Acidize well w/5,000 gals. NEFE DI HCL w/3% DP-77MX Micellar Solvent. TOH w/sonic hammer. TIH w/tubing and packer. Set packer at ±3,700'. Swab/flow back load. TOH w/tubing & pkr., laying down prod. tbg. Pick up & TIH w/2-3/8" lined inj. tbg. w/inj. pkr. ND BOP. NU inj. wellhead assembly. RD & move out pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 03-22-95

TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 28 1995

CONDITIONS OF APPROVAL, IF ANY: