STATE	ΩF	NEW	MEY	CO
SIMIE	O.	NEM	PIL.A	, 00

ENERGY AND MINERALS DEPARTMENT	Form C-103	
NO. OF COPIES RECEIVED OIL CONSERVATION DIVISION	Revised 10-1-78	
DISTRIBUTION P.O. Box 2088		
SANTA FE, NEW MEXICO 87501	5a. Indicate Type of Lease	
FILE	State Fee X	
U.S.G.S		
LAND OFFICE	5. State Oil & Gas Lease No.	
OPERATOR		
	_	
SUNDRY NOTICES AND REPORTS ON WELLS	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
1. OIL GAS	7. Unit Agreement Name	
WELL X WELL OTHER	7. UNITY Agr COMBIT TUME	
. Name of Operator	8. Farm or Lease Name	
Read & Stevens, Inc.	Snyder	
3. Address of Operator	9. Well No.	
P.O. Box 1518, Roswell, NM 83201		
i. Location of Well	10. Fleid and Poot, or Wildcat	
UNIT LETTER J . 2310 FEET FROM THE East LINE AND 2310 FEET FROM	West Teas Yates	
THE South LINE. SECTION 16 TOWNSHIP 20S RANGE 33E NMPM	 	
<pre><xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx< td=""><td>12. County XXXXXXXXXXXXXXXXX</td></xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx<></pre>	12. County XXXXXXXXXXXXXXXXX	
<pre><xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx< td=""><td>Lea XXXXXXXXXXXXXXXXX</td></xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx<></pre>	Lea XXXXXXXXXXXXXXXXX	
Check Appropriate Box To Indicate Nature of Notice, Report or Ott	ner Data	
NOTICE OF INTENTION TO: SUBSEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING	
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT	
<u> </u>	P	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	P	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB	P	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER OTHER Describe Proposed or Completed Operations(Clearly state all pertinent details, and give	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER OTHER Pescribe Proposed or Completed Operations (Clearly state all pertinent details, and givenated date of starting any proposed work) SEE RULE 1103.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER Describe Proposed or Completed Operations(Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. E) Set CIPB @ 30501. Spot 351 of cmt on top of CIPB w/ a Dump Bailer.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER Describe Proposed or Completed Operations(Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. E) Set CIPB @ 30501. Spot 351 of cmt on top of CIPB w/ a Dump Bailer. C) Circulate hole w/ saitmud.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations(Clearly state all pertinent details, and give mated date of starting any proposed work) SEE RULE 1103. E) Set CIPB @ 30501. Spot 351 of cmt on top of CIPB w/ a Dump Bailer. C) Circulate hole w/ saltmud. E) Spot 35sx plug 25001-27001. (Across top of liner)	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER Describe Proposed or Completed Operations(Clearly state all pertinent details, and give mated date of starting any proposed work) SEE RULE 1103. Set CIPB @ 3050'. Spot 35' of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saitmud. Spot 35sx plug 2500'-2700'. (Across top of liner) Spot 35sx plug 1450'-1350'. (At top of sait)	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations(Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. Set CIPB @ 30501. Spot 351 of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saltmud. Spot 35sx plug 25001-27001. (Across top of liner) Spot 35sx plug 14501-13501. (At top of salt) Spot 10sx surface plug w/ 4"X101 Dryhole Marker.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations(Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. Set CIPB @ 3050'. Spot 35' of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saitmud. Spot 35sx plug 2500'-2700'. (Across top of liner) Spot 35sx plug 1450'-1350'. (At top of sait) Spot 10sx surface plug w/ 4"X10' Dryhole Marker. Clean location and prep for inspection.	PLUG AND ABANDONMENT pertinent dates, including esti-	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations(Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. Set CIPB @ 3050'. Spot 35' of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saltmud. Spot 35sx plug 2500'-2700'. (Across top of liner) Spot 35sx plug 1450'-1350'. (At top of salt) Spot 10sx surface plug w/ 4"X10' Dryhole Marker.	PLUG AND ABANDONMENT pertinent dates, including esti-	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations (Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. Set CIPB @ 3050'. Spot 35' of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saltmud. Spot 35sx plug 2500'-2700'. (Across top of liner) Spot 35sx plug 1450'-1350'. (At top of salt) Spot 10sx surface plug w/ 4"X10' Dryhole Marker. Clean location and prep for inspection.	PLUG AND ABANDONMENT pertinent dates, including esti- wiledge and belief.	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations(Clearly state all pertinent details, and give mated date of starting any proposed work) SEE RULE 1103. Set CIPB @ 3050'. Spot 35' of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saltmud. Spot 35sx plug 2500'-2700'. (Across top of liner) Spot 35sx plug 1450'-1350'. (At top of salt) Spot 10sx surface plug w/ 4"X10' Dryhole Marker. Clean location and prep for inspection.	PLUG AND ABANDONMENT pertinent dates, including esti- where partial particles and belief. properties of the propertie	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations (Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. Set CIPB @ 30501. Spot 351 of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saltmud. Spot 35sx plug 25001-27001. (Across top of liner) Spot 35sx plug 14501-13501. (At top of salt) Spot 10sx surface plug w/ 4"X101 Dryhole Marker. Clean location and prep for inspection. Cipilling & Production Manage OPIGINAL SIGNED AV IERBAY ERVANA	PLUG AND ABANDONMENT pertinent dates, including esti- where partial particles and belief. properties of the propertie	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Pescribe Proposed or Completed Operations(Clearly state all pertinent details, and give nated date of starting any proposed work) SEE RULE 1103. Est CIPB @ 3050'. Spot 35' of cmt on top of CIPB w/ a Dump Bailer. Circulate hole w/ saltmud. Spot 35sx plug 2500'-2700'. (Across top of liner) Spot 35sx plug 1450'-1350'. (At top of salt) Spot 10sx surface plug w/ 4"X10' Dryhole Marker. Clean location and prep for inspection.	PLUG AND ABANDONMENT pertinent dates, including esti- wiledge and belief.	

HE COASM SIGN WOT SE NOTHED 24 HOURS 1000 100 DE BUIENSTIC OF SERVICE OF SERVICE OF SERVICE OF SERVICE.

AUG 30 1983

error and the second of the se

. . .