

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Free ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State H
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 4
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM West 6 TOWNSHIP 19-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Yates Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3650' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon the subject well per the following:

Move in service unit and pull 2-3/8" tubing. RIH with a cast iron bridge plug. Set CIBP at 2750' and cap with 35' of class C neat cement. Spot 55 bbls of 10# brine with 25# gel per bbl. Spot 47 sx class C neat across 8-5/8" casing shoe at 401' to surface. Weld on cap and erect permanent abandonment marker.

* Notify NMOC prior to setting plugs.

0+4-NMOC,H 1-HOU 1-F. J. Nash, HOU 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Herring TITLE Assist. Admin. Analyst DATE 4-19-83

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APR 21 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 20 1983

Q.C.D.
HOBBY OFFICE