

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION DISTRICT I Hobbs PO BOX 1980 Hobbs, NM 88241-1981 (505) 393-6161

Jennifer A. Salisbury

Letter Sent/ 67

December 4, 1997

Keith E. Bucy Division Production Superintendent P.O. Box 2760 Midland, Texas 79702-2760

Dear Mr. Bucy:

In reference to Bass's C-103's intent to plug and abandon Bass State #5 and #6 in UL C 18-20S-33E, according to Rule 111-P (Potash Rules) New Mexico Oil Conservation Division (NMOCD) Rules and Regulations, Bass needs to have a solid cement plug that covers from the base of the salt zone to above the top of the salt. This will keep the wells in compliance with NMOCD rules.

Well #5 the salt plug should be from 1110' to 2690'

Well #6 the salt plug should be from 1104' to 2700'

If you have any questions, please call myself or Paul Kautz-District Geologist at (505)393-6161.

Sincerely,

Chris Williams

District 1 Supervisor

Mris Williams

Submit 3 Copies

to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

811 S. 1st Street, Artesia, NM 88210-2834

DISTRICT III

1000

OIL CONSERVATION DIVISION

P. O. Box 2088 Santa Fe. New Mexico 87504-2088 WELL API NO. 30-025-27903

5. Indicate Type of Lease State X Fee

6. State Oil & Gas Lease No.

1000 Rio Brazos Rd., Aztec, NM 87410								E-5231			
SUNDRY NOTICES AND REPORTS ON WELLS											
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							7. Lease Name or Unit Agreement Name				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)								Bass State			
Type of Well		-					7				
Oil Well X	Gas We		Other								
Name of Opera	itor						8. Well No	5			
Bass	Enterprises Producti	on Company									
3. Address of Operator						Pool Name or Wildcat					
P. O. Box 2760 Midland, Texas 79702-2760						Salt Lake Yates					
4. Well Location						,		-			
Unit	Letter C	:330	Feet From The	<u>North</u>	_ Line and	2310	_Feet From The	West	Line		
Se	ction 18	Township	20S	Range	33E	NMPM		Lea	County		
		10. Elevation	on (Show whether DF	RKB, RT, G	R, etc.)						

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND AB	REMEDIAL WORK ALTERING CASING						
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT						
THE COMMISSION MUST BE NOTIFIED 21 PULL OR ALTER CASHS PRIOR TO THE BUSINESSION OF THE CASHS OTHER: PLUGGING OPERATIONS FOR THE CASHS	CASING TEST AND CEMENT JOB						
OTHER: PLUGGING OFFICATIONS TO BE APPROVED.	OTHER:						

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Bass Enterprises Production Company requests approval to plug and abandon the referenced well. Work will begin soon after approval. Completion of the project should be 3 days after start. The procedure as follows:

- 1) MIRU Plugging Co. equipment. Dig workover pit. Unseat pump and POH with 3/4" rods (2878'), 1" x 1' HF lift sub, 2" x 1-1/2" x 12' RWTC pump #UB-626, 1" x 6" strainer nipple and LD.
- 2) ND wellhead. NU BOP. PU 2-3/8" x 8' sub and RIH with 2-3/8" EUE 4.7#/ft J-55 tubing and tag CIBP at 2890'.
- 3) RU pump truck to tubing and circulate 5-1/2" 15.5#/ft casing with 69 bbls FW. PU off CIBP. Mix and spot 20 sx (Class "C", 14.8 ppg, 1.32 yield + 2% calcium chloride, 2 hours pump time).
- 4) PUH to 2690', LD tubing while POH. Reverse tubing clean using 64 bbls mud laden fluid. PUH ±100' standing back tubing. WOC.
- 5) PU and RBIH with tubing and tag TOC @ 2690' (TOC must be no lower than 2763').
- 6) PUH to 1450'. LD tubing while POH. Mix and spot 45 sx cement (Class "C" Neat, 1.32 yield, 14.8 ppg, 2 hours pump time). Estimated TOC at 1000'.
- 7) PUH to surface. ND BOP. Mix and spot 10 sx surface plug using same cement.
- 8) RDPU and plugging company equipment. Cut off wellhead, remove deadmen and install dry hole marker.
- 9) Contact OCD in Hobbs, NM (505) 393-6161 when well plugging is completely finished, including clean up

	n above is true and complete to the best of my kno	•	LERTIFIED	P 966 241	832 JOL: PG
Thereby certify that the informatio	in above is true and complete to the best of my kno	wiedge and be	ulet.		1 1-
SIGNATURE	will any	TITLE:	Division Production Superintendent	DATE:	11/17/97
TYPE OR PRINT NAME	Keith E. Bucy		TELEPHONE N	IO. (915) 683-227	7
(This space for State Use)					
APPROVED BY:		_ TITLE:		DATE:	

CONDITIONS OF APPROVAL, IF ANY: