

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <u>Injection</u>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
J. P. Cone		Cone Jalmat Yates Pool
3. Address of Operator		9. Well No.
P.O. Box 871, Lubbock, Tx 79408		Tract 5 No. 4
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>M</u> . <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM		Jalmat Yates
THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>22S</u> RANGE <u>35E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3608' GR		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <u>Shut In</u>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 25 SX Plug 3618 to 3518 Tag plug @ 3500'
2. Load & Circulate 7" CSG w/10# Brine & Salt Jel Mud
3. 25 SX Plug 1709 to 1609
4. Perf 4-- $\frac{1}{2}$ Holes @354
5. Run & Set 7" PKR @ 250'. Mix & Pump 50 SX Class "C". Displace to 300'. Tag plug @ 314'
6. 10 SX @ Surf. Install D.H. Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leonard Caffo TITLE Agent DATE 8-1-86

APPROVED BY R. A. Public OIL & GAS INSPECTOR DATE NOV 19 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 6 1986
C.C.S.
HOBBS OFFICE