

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 811 South First, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-025-04761 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name: Harry Leonard (NCT-A) |
| 8. Well No. 8 |
| 9. Pool name or Wildcat <u>22800</u> Eumont, Yates, 7 RVERS, Queen |

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
15 Smith Road, Midland Texas 79705

4. Well Location
 Unit Letter 0 : 660 feet from the south line and 1980 feet from the east line
 Section 22 Township 21-S Range 36-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON

TEMPORARILY ABANDON CHANGE PLANS

PULL OR ALTER CASING MULTIPLE COMPLETION

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING

COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT


CASING TEST AND CEMENT JOB

OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24hrs prior to MI & RU.
2. Set 5 1/2 CIBP @ 3050, spot 30sx plug 3050-2750(Eumont, 7 RVERS, Queen, B-salt)WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25# Gel p/BBL.
4. Spot 25sx plug 1500-1300(T-salt) WOC Tag.
5. Perf 4 holes @ 475, sqz 75sx plug 475-200(8 5/8 shoe) WOC Tag.
6. 10sx surface, Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G.R. Bledsoe TITLE HES Specialist DATE 11/1/2002

Type or print name G.R. Bledsoe Telephone No. 915.687.7153

APPROVED BY [Signature] TITLE MANAGER DATE NOV - 7 2002

Conditions of approval, if any:

[Handwritten mark]