ENERGY AND MINERALS DEPARTMENT

(
DISTRIBUTION .	
SANTA FE	
FILE	
U.S.G.E.	
LANC OFFICE	
OPPRATOR	

JIL CONSERVATION DIVISIC ..

Form	C - 1	03
Revis	e d	19-1-78

	DISTRIBUTION	P. O. BOX 2088	Form C-103 Revised 10-1-78
	SANTA FE	SANTA FE, NEW MEXICO 8750	01
	PILE	<u></u>	Sa. Indicate Type of Lease
	U.3.G.E.		State Fee X
	LANC OFFICE	·	5. State Oil & Gas Lease No.
	OPERATOR		J. State on a sease No.
			· · · · · · · · · · · · · · · · · · ·
	SUNE SUNE THIS FORM FOR TO SUNE TO SUNE TO SUNE TO SUNE THIS SUNE THE SUNE THE SUNE THE SUNE THE SUNE TO SUNE THE SUNE T	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO BRILL ON TO BEEPEN OR PLUG BACK TO A DIFFERENT R ATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	ESTRYOIR.
1.			7. Unit Agreement Name
	WELL WELL	GTHER.	NORTHEAST DRINKARD UNIT
2. N	ame of Operator		8. Fam or Lease Name
	SHELL WESTERN E&P IN	C. (4431 WCK)	NORTHEAST DRINKARD UNIT
	ddiess of Operator	(1102 1000)	9. Well No.
-	P. O. BOX 576, HOUST	ON. TX 77001	303
	scation of Well		
٠. ـ		1980 FEET FROM THE South LINE AND 1980	NORTA EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS
	•	•	(1)////////////////////////////////////
	THELINE, SEC	TION 3 TOWNSHIP 21-S MANGE 37	-E mon. [[]][][][][][][][][][][][][][][][][][]
11		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
///		3435' DF	Lea ()
16.	Charl	Appropriate Box To Indicate Nature of Notice	Parasa or Orban Dava
			•
	- NOTICE OF	INTENTION TO:	SUBSEQUENT REPORT OF:
	FORW REMEDIAL WORK	PLUC AND ABANDON REMEDIAL WORK	ALTERING CASING
	一	COMMENCE DRILLING	
	PORARILY ABANDON		
PUL	L OR ALTER CASING	CHANGE PLANS CASING TEST AND CE	
	OAP, AT / CTI	OTHER	
	OTHER OAT, AT / CIT		
17	Describe Proposed or Completed	Operations (Clearly state all pertinent details, and give pertine	nt dates, including estimated date of starting any proposed
	work) SEE RULE 1103.		
		*.	

- 1) POOH w/ prod equip.
- 2) Perf Blinebry 5725'-5753' and Tubb 6046'-6038' w/ 1 JSPF.
- 3) Selectively ATPB1 nebry 5725'-5753 and Tubb 6046'-6038' w/ 2130 gals 15% NEFE HCl acid, using BP's and pkrs.
- 4) Install injection equip, setting Guiberson Uni-VI pkr @ 5670'.
- 5) Press test to 300 psi for 30 min.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE Orig. Signed by	
\cdot	1 1988
	
	·

RECEIVED

OCT 24 1988 OCD HOBBS OFFICE

STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPPRATOR	

OIL CONSERVATION DIVISION

Form C-103

SANTA FE	SANTA	FE, NEW MEXICO	87501	Revised 10-1-1
FILE]	TI TI MEXICO	67501	Sa. Indicate Type of Lease
U.S.G.S.]			State Fee X
LAND OFFICE	· ·			5. State Oil & Gas Lease No.
	J			
SUNDR	RY NOTICES AND RE	PORTS ON WELLS		
IND MOT USE THIS FORM FOR PRO	CPGSALS TO DRILL OR TO BE	C-101) FOR SUCH PROPOSALS.	PENT RESERVOIR.	
1. 61L V 6AB			•	7. Unit Agreement Name
2. Name of Operator	OTHER-			8. Farm or Lease Name
SHELL WESTERN E&P INC.		•		LIVINGSTON*
3. Address of Operator				9. Well No.
P. O. BOX 576, HOUSTON	N, TX 77001 (WCK 4435)	•	1*
4. Location of Well				10. Field and Pool, or Wildcat
UNIT LETTERS	1980 FEET FROM THE	SOUTH LINE AND	1980 FEET PROM	DRINKARD
	•	010	275	
THE WEST LINE, SECTI	on Town:	SHIP 21S NAMEE	3/E HIMPM.	
mmmmmm	15 Flavotion	(Show whether DF, RT, GR, e	ic.]	12. County
	3435'		,	LEA AIIIIIII
16. Check		Indicate Nature of No	vice Report of Oth	
	NTENTION TO:	Indicate Nature of Ne	SUBSEQUENT	
_ ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
PERPORM REMEDIAL WORK	PLUE AND	ABANDON REMEDIAL WO		ALTERING CASING
TEMPORARILY ABANDON	*	COMMENCE DR	ILLING OFMS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE P	— ;	AND CEMENT JOB	_
OAP &	ACDZ	X OTHER		
OTHER	- 11-7			
17. Describe Proposed or Completed Operal SEE RULE 1103.	perations (Clearly state al	l pertinent details, and give p	ertinent dates, including	estimated date of starting any propose
again, see note those	*NEW	WELL NAME: NORTH	EAST DRINKARD UN	IIT #303
1. POH w/prod equip.				
 Tag PBTD & CO if in the second second		kard perfs 6528' -	66401	•
4. Perf Blinebry 580	0' - 6026' (1 JS	PF).	0040 .	
5. Set RBP @ 6040'.	0 00=0 (= 00	· · / ·		
	- 6026' w/4000 g	als 15% HCl + 750#	rock salt.	
7. POH w/RBP.				•
Install prod equi	p & return well	to prod.		
NOTE: Well will	he on produntil	inj facilities ar	e ready for ini	
MOTE: NCTT WITT	be on prod dirent	my ractificies at	c ready for fina	
		• •		
			. ,	
	-			•
	•			
18. I hereby certify that the information	above is true and comple	te to the best of my knowledg	e and belief.	
			•	
BIGHED Strue	A. J. FORE	SUPERVISOR RE	G. & PERMITTING	DATE 12-28-87
ORIGINAL SIGNED BY				
ORIGINAL SIGNED BY DISTRICT I SUP			•	
Man 12/1/2/11 1 0 01 1				그 그는 그를 가는 사람들이 가장 없었다.

DEC 30 1981