

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instruction  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. <b>LC-032874-1(a)</b>
2. NAME OF OPERATOR <b>TEXACO Inc.</b>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME <b>NONE</b>
3. ADDRESS OF OPERATOR <b>P. O. Box 728 - Hobbs, New Mexico</b>		7. UNIT AGREEMENT NAME <b>NONE</b>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface <b>Well located 990' from the West Line, and 1980' from the South Line of Section 35, T-24-S, R-37-E, Lea County, New Mexico.</b>		8. FARM OR LEASE NAME <b>G. L. Erwin "a"</b>
14. PERMIT NO. <b>Regular</b>		9. WELL NO. <b>4</b>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>3189' (D. F.)</b>		10. FIELD AND POOL, OR WILDCAT <b>Justis Blinebry</b>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 35, T-24-S, R-37-E</b>
		12. COUNTY OR PARISH <b>Lea</b>
		13. STATE <b>N. M.</b>

## 18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We propose to do the following work on subject well:

1. Pull rods and tubing.
2. Perforate 2 7/8" O. D. Casing with one jet shot at 5381', 5388', 5391', 5400', 5412', 5452', 5462', 5470', 5503', 5561', 5608', and 5619'.
3. Acidize with 500 gals acetic acid. Re-acidize with 1100 gals 15% NE acid in 11 stages with one ball sealer between each stage.
4. Frac with 20,000 gals gelled lease crude, carrying one pound of sand per gal.
5. Swab well, recover load oil, test, return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. E. Morgan

TITLE

Assistant to the District Superintendent

DATE

November 30, 1964.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

