



APPROVED

By Olivia Yu at 11:00 am, Oct 22, 2018

*EOG Resources, Inc.
Artesia Division Office
104 S. 4th Street
Artesia, N. M. 88210*

NMOCD grants
closure to incident
nOY1735250845.

October 9, 2018

Ms. Olivia Yu
NMOCD District I
1625 N. French Drive
Hobbs, New Mexico 88240

Re: Waylon BMD State #8
30-025-38256
Section 14, T11S-R34E
Lea County, New Mexico
1RP-

Ms. Yu,

EOG Y Resources, Inc. is submitting the enclosed CLOSURE REPORT and C-141 Final Report for the above captioned location. The report is being submitted in response to the C-141 Initial Report dated 12/18/2017.

Thank you.

EOG Y Resources, Inc.

A handwritten signature in blue ink, appearing to read "Robert Asher", followed by a period.

Robert Asher
Environmental Supervisor

I. Location

From Tatum, NM, travel west on US Highway 380 for approximately 12 miles to Four Lakes Road. Turn right (North) and continue for approximately 2.5 miles, turn right (East), before cattle guard onto Farm Road. Continue approximately 0.5 miles, to a "Y" in the road and turn left, continue through a cattle guard. Curve back West and then and continue North for approximately 1.7 miles to a "T" in the road. Turn right (East) and continue for approximately 0.4 miles to the Southwest corner of the well pad.

II. Background

On December 15, 2017, EOG Y Resources, Inc. submitted to the NMOCD District I Office a Form C-141 for the release of 5 B/O with 4.5 B/O recovered (the remaining 0.5 B/O entrained within the gravel). The affected area is approximately 30' X 30' within the containment of the production facility and was contained within the bermed and lined battery. The release was caused by a production tank, a valve was left open causing the oil to equalize and overflow the tank. A vacuum truck was dispatched and recovered 90% of the released oil. A roustabout crew was dispatched and excavated the visibly impacted gravel. The impacted gravel excavated was hauled to an NMOCD approved disposal facility.

III. Surface and Ground Water

Area surface geology is Paleozoic Permian. Based on information regarding this location (Section 14, T11S-R34E), the New Mexico Office of the State Engineer (NMOSE) database depth to groundwater is follows: (NMOSE-L06372, DTGW @ 80'), the United States Geological Survey National Water Information System, is as follows: (USGS #332301103291301, DTGW @ 18.25', USGS #332230103294501, DTGW @ 19.5', USGS #332118103283901, DTGW @ 25' & USGS #332212103282101, DTGW @ 26.5'). The depth to groundwater is <50', per USGS and NMOSE groundwater level. **Based on this information the Site Ranking is a Twenty (20).**

Watercourses in the area are dry except for infrequent flows in response to major precipitation events, with the nearest body of surface water is House Lake (0.91 miles, SW direction).

IV. NMOCD Ranking Criteria

The ranking for this site is Zero (0) based on the following:

Depth to ground water	>100'
Wellhead Protection Area	> 1000'
Distance to surface water body	> 1000'

V. Liner Integrity

With the battery being bermed and lined with a 20 millimeter liner, Per the Conditions of Approval on the C-141 Initial Report, the NMOCD requested the liner to be inspected and provide a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

Per 19.15.29.11, EOG Y Resources, Inc. has conducted the following actions:

(5) Soil/Waste characteristics.

- (a) If the release occurred within a lined containment area, the responsible party must demonstrate liner integrity after affected material is removed and the affected area of the liner is exposed and provide:
 - (i) certification on form C-141 that the responsible party has visually inspected the liner where the release occurred and the liner remains intact and had the ability to contain the leak in question (Appendix F); and
 - (ii) at least two business days' notice to the appropriate division district office before conducting the liner inspection (Appendix E).

Figure 1

Site Map

Waylon BMD State #8

Section 14, T11S-R34E
Lea County, New Mexico
Site Map

Legend

- Waylon BMD State #8



Google Earth

© 2018 Google

2000 ft



Figure 2

Photos



Appendix A

Water Well Date Site Map

Waylon BMD State #8

Section 14, T11S-R34E

Lea County, New Mexico

Water Well Data: Site Ranking is Twenty (20). Depth to Ground Water: <50'
(Approximately 33.85', per NMOSE & USGS Groundwater Levels).

Legend

-  USGS & NMOSE Water Wells
-  Waylon BMD State #8

USGS 332301103291301 (DTGW @ 18.25')

USGS 332230103294501 (DTGW @ -19.51')

USGS-332212103282401 (DTGW @ 26.5')

Waylon BMD State #8

NMOSE L 06372 (DTGW @ 80')

USGS 332118103283901 (DTGW @ 25')

Google Earth

© 2018 Google

1 mi





New Mexico Office of the State Engineer

Point of Diversion Summary

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

Well Tag	POD Number	Q64 Q16 Q4 Sec Tws Rng	X	Y
L 06372		3 1 16 11S 34E	637458	3693013*

Driller License: 46

Driller Company: ABBOTT BROTHERS COMPANY

Driller Name: MURRELL ABBOTT

Drill Start Date: 08/18/1968

Drill Finish Date: 08/19/1968

Plug Date: 10/31/1968

Log File Date: 10/03/1968

PCW Rcv Date:

Source: Shallow

Pump Type:

Pipe Discharge Size:

Estimated Yield:

Casing Size:

Depth Well: 124 feet

Depth Water: 80 feet

Water Bearing Stratifications:

Top Bottom Description

80 110 Sandstone/Gravel/Conglomerate

112 120 Sandstone/Gravel/Conglomerate

*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

Appendix C

USGS Groundwater Level Information



USGS Home
Contact USGS
Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:

Site Information ▼

Geographic Area:

United States ▼

GO

Click to hideNews Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

USGS 332301103291301 11S.34E.02.33100

Available data for this site

SUMMARY OF ALL AVAILABLE DATA ▼

GO

Well Site

DESCRIPTION:

Latitude 33°23'01", Longitude 103°29'13" NAD27

Lea County, New Mexico

Well depth: not determined.

Land surface altitude: 4,145 feet above NAVD88.

Well completed in "Ogallala Formation" (121OGLL) local aquifer

AVAILABLE DATA:

Data Type	Begin Date	End Date	Count
Field groundwater-level measurements	1981-02-17	1990-11-30	3

OPERATION:

Record for this site is maintained by the USGS New Mexico Water Science Center

Email questions about this site to [New Mexico Water Science Center Water-Data Inquiries](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)

[News](#)

[Accessibility](#)

[Plug-Ins](#)

[FOIA](#)

[Privacy](#)

[Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)

Title: NWIS Site Information for USA: Site Inventory

URL: <https://waterdata.usgs.gov/nwis/inventory?>



Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 08:55:07 EST

0.28 0.26 caww01



USGS Home
Contact USGS
Search USGS

National Water Information System: Web Interface

[USGS Water Resources](#)

Data Category:

Groundwater

Geographic Area:

United States

GO

Click to hideNews Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

Groundwater levels for the Nation

Search Results -- 1 sites found

site_no list =

- 332301103291301

Minimum number of levels = 1

[Save file of selected sites](#) to local disk for future upload

USGS 332301103291301 11S.34E.02.33100

Available data for this site

Groundwater: Field measurements

GO

Lea County, New Mexico

Hydrologic Unit Code --


Latitude 33°23'01", Longitude 103°29'13" NAD27

Land-surface elevation 4,145 feet above NAVD88

This well is completed in the Ogallala Formation (121OGLL) local aquifer.

Output formats

Table of data
Tab-separated data
Graph of data
Reselect period



Breaks in the plot represent a gap of at least one year between field measurements.

[Download a presentation-quality graph](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)

[News](#)

[Accessibility](#)

[Plug-Ins](#)

[FOIA](#)

[Privacy](#)

[Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)

Title: Groundwater for USA: Water Levels

URL: <https://nwis.waterdata.usgs.gov/nwis/gwlevels?>



Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 08:55:18 EST

1.04 0.93 nadww01



USGS Home
Contact USGS
Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:

Site Information ▼

Geographic Area:

United States ▼

GO

Click to hide News Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

USGS 332230103294501 11S.34E.10.413221

Available data for this site

SUMMARY OF ALL AVAILABLE DATA ▼

GO

Well Site

DESCRIPTION:

Latitude 33°22'41", Longitude 103°29'47" NAD27

Lea County, New Mexico , Hydrologic Unit 12080001

Well depth: not determined.

Land surface altitude: 4,144.00 feet above NGVD29.

Well completed in "Ogallala Formation" (121OGLL) local aquifer

AVAILABLE DATA:

Data Type	Begin Date	End Date	Count
<u>Field groundwater-level measurements</u>	1971-03-18	1996-01-24	6

OPERATION:

Record for this site is maintained by the USGS New Mexico Water Science Center

Email questions about this site to [New Mexico Water Science Center Water-Data Inquiries](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)

[News](#)

[Accessibility](#)

[Plug-Ins](#)

[FOIA](#)

[Privacy](#)

[Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)

Title: NWIS Site Information for USA: Site Inventory

URL: <https://waterdata.usgs.gov/nwis/inventory?>



Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 08:45:09 EST

0.28 0.27 caww01



USGS Home
Contact USGS
Search USGS

National Water Information System: Web Interface

[USGS Water Resources](#)

Data Category:

Groundwater ▼

Geographic Area:

United States ▼

GO

Click to hideNews Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

Groundwater levels for the Nation

Search Results -- 1 sites found

site_no list =

- 332230103294501

Minimum number of levels = 1

[Save file of selected sites](#) to local disk for future upload

USGS 332230103294501 11S.34E.10.413221

Available data for this site

Groundwater: Field measurements ▼

GO

Lea County, New Mexico

Hydrologic Unit Code 12080001


Latitude 33°22'41", Longitude 103°29'47" NAD27

Land-surface elevation 4,144.00 feet above NGVD29

This well is completed in the Ogallala Formation (121OGLL) local aquifer.

Output formats

Table of data
Tab-separated data
Graph of data
Reselect period



Breaks in the plot represent a gap of at least one year between field measurements.

[Download a presentation-quality graph](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)

[News](#)

[Accessibility](#)

[Plug-Ins](#)

[FOIA](#)

[Privacy](#)

[Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)

Title: Groundwater for USA: Water Levels

URL: <https://nwis.waterdata.usgs.gov/nwis/gwlevels?>



Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 08:45:27 EST

5.57 0.97 nadww01



USGS Home
Contact USGS
Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:

Site Information ▼

Geographic Area:

United States ▼

GO

Click to hideNews Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

USGS 332118103283901 11S.34E.14.434441

Available data for this site

SUMMARY OF ALL AVAILABLE DATA ▼

GO

Well Site

DESCRIPTION:

Latitude 33°21'31", Longitude 103°28'38" NAD27

Lea County, New Mexico , Hydrologic Unit 12080001

Well depth: not determined.

Land surface altitude: 4,143.50 feet above NGVD29.

Well completed in "Ogallala Formation" (121OGLL) local aquifer

AVAILABLE DATA:

Data Type	Begin Date	End Date	Count
<u>Field groundwater-level measurements</u>	1961-02-15	1981-02-17	5

OPERATION:

Record for this site is maintained by the USGS New Mexico Water Science Center

Email questions about this site to [New Mexico Water Science Center Water-Data Inquiries](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)

[News](#)

[Accessibility](#)

[Plug-Ins](#)

[FOIA](#)

[Privacy](#)

[Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)

Title: NWIS Site Information for USA: Site Inventory

URL: <https://waterdata.usgs.gov/nwis/inventory?>



Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 08:44:47 EST

0.27 0.26 caww01



USGS Home
Contact USGS
Search USGS

National Water Information System: Web Interface

[USGS Water Resources](#)

Data Category:

Groundwater

Geographic Area:

United States

GO

Click to hideNews Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

Groundwater levels for the Nation

Search Results -- 1 sites found

site_no list =

- 332118103283901

Minimum number of levels = 1

[Save file of selected sites](#) to local disk for future upload

USGS 332118103283901 11S.34E.14.434441

Available data for this site

Groundwater: Field measurements

GO

Lea County, New Mexico

Hydrologic Unit Code 12080001

Latitude 33°21'31", Longitude 103°28'38" NAD27

Land-surface elevation 4,143.50 feet above NGVD29

This well is completed in the Ogallala Formation (121OGLL) local aquifer.


Output formats

[Table of data](#)

[Tab-separated data](#)

[Graph of data](#)

[Reselect period](#)



Breaks in the plot represent a gap of at least one year between field measurements.

[Download a presentation-quality graph](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)

[News](#)

[Accessibility](#)

[Plug-Ins](#)

[FOIA](#)

[Privacy](#)

[Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)

Title: Groundwater for USA: Water Levels

URL: <https://nwis.waterdata.usgs.gov/nwis/gwlevels?>



Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 08:41:08 EST

1.01 0.89 nadww01



[USGS Home](#)
[Contact USGS](#)
[Search USGS](#)

National Water Information System: Web Interface

[USGS Water Resources](#)

Data Category:

Site Information ▼

Geographic Area:

United States ▼

GO

Click to hideNews Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

USGS 332212103282101 11S.34E.11.444

Available data for this site

SUMMARY OF ALL AVAILABLE DATA ▼

GO

Well Site

DESCRIPTION:

Latitude 33°22'25", Longitude 103°28'24" NAD27
Lea County, New Mexico , Hydrologic Unit 12080001
Well depth: not determined.
Land surface altitude: 4,138.00 feet above NGVD29.

AVAILABLE DATA:

Data Type	Begin Date	End Date	Count
Field groundwater-level measurements	1961-02-15	1976-04-27	4

OPERATION:

Record for this site is maintained by the USGS New Mexico Water Science Center
Email questions about this site to [New Mexico Water Science Center Water-Data Inquiries](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)
[News](#)

[Accessibility](#) [Plug-Ins](#) [FOIA](#) [Privacy](#) [Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)



Title: NWIS Site Information for USA: Site Inventory

URL: <https://waterdata.usgs.gov/nwis/inventory?>

Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 09:02:50 EST

0.36 0.31 caww01



USGS Home
Contact USGS
Search USGS

National Water Information System: Web Interface

[USGS Water Resources](#)

Data Category:

Groundwater

Geographic Area:

United States

GO

Click to hide News Bulletins

- [Please see news on new formats](#)
- [Full News](#) 

Groundwater levels for the Nation

Search Results -- 1 sites found

site_no list =

- 332212103282101

Minimum number of levels = 1

[Save file of selected sites](#) to local disk for future upload

USGS 332212103282101 11S.34E.11.444

Available data for this site

Groundwater: Field measurements

GO

Lea County, New Mexico


Hydrologic Unit Code 12080001

Latitude 33°22'25", Longitude 103°28'24" NAD27

Land-surface elevation 4,138.00 feet above NGVD29

Output formats

Table of data
Tab-separated data
Graph of data
Reselect period



Breaks in the plot represent a gap of at least one year between field measurements.

[Download a presentation-quality graph](#)

[Questions about sites/data?](#)

[Feedback on this web site](#)

[Automated retrievals](#)

[Help](#)

[Data Tips](#)

[Explanation of terms](#)

[Subscribe for system changes](#)

[News](#)

[Accessibility](#)

[Plug-Ins](#)

[FOIA](#)

[Privacy](#)

[Policies and Notices](#)

[U.S. Department of the Interior](#) | [U.S. Geological Survey](#)

Title: Groundwater for USA: Water Levels

URL: <https://nwis.waterdata.usgs.gov/nwis/gwlevels?>



Page Contact Information: [USGS Water Data Support Team](#)

Page Last Modified: 2017-12-15 09:03:05 EST

1.01 0.9 nadww01

Appendix D

Form C-141 Initial Report

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Waylon BMD State #8	Facility Type Battery	

Surface Owner State	Mineral Owner State	API No. 30-025-38256
------------------------	------------------------	--------------------------------

LOCATION OF RELEASE

Unit Letter C	Section 14	Township 11S	Range 34E	Feet from the 660	North/South Line North	Feet from the 2310	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 33.3712234 Longitude 103.4824219

NATURE OF RELEASE

Type of Release Oil	Volume of Release 5 B/O	Volume Recovered 4.5 B/O
Source of Release Production Tank	Date and Hour of Occurrence 11/25/2017; PM	Date and Hour of Discovery 11/25/2017; PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Pumper drained water from oil tank to water tank. Left valve open to long causing to much fluid to equalize over. Causing water tank to run over. Vacuum truck(s) and roustabout/backhoe crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 10'X 30', this battery is bermed and has a synthetic liner. Vacuum truck recovered 4.5 B/O, remaining 0.5 B/O entrained within gravel material on top of liner. Roustabout crews removed impacted gravel, that gravel was disposed at an NMOCD approved facility. EOG Y will inspect liner and attest to liner integrity. Depth to Ground Water: <50' (approximately 33.85', per NMOSE & USGS Groundwater Levels), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Based off of the liner inspection/enclosed photos, EOG Y requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: Environmental Supervisor	Approval Date: 12/18/2017	Expiration Date:
E-mail Address: Robert_Asher@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 15, 2017 Phone: 575-748-4217	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1735250845

Appendix E

NMOCD I Two Days' Notice

Bob Asher

From: Bob Asher
Sent: Wednesday, October 3, 2018 7:20 AM
To: olivia.yu@state.nm.us; NMSLO (Hobbs/Ryan Mann)
Cc: Katie Jamison (Katie_Jamison@eogresources.com); Chase Settle
Subject: Liner Inspection (Moped BQP State #1 & Waylon BMD State #8)

Tracking:	Recipient	Read
	olivia.yu@state.nm.us	
	NMSLO (Hobbs/Ryan Mann)	
	Katie Jamison (Katie_Jamison@eogresources.com)	Read: 10/3/2018 8:10 AM
	Chase Settle	Read: 10/3/2018 7:22 AM

EOG Resources, Inc. will be conducting a liner inspection at the following locations on October 5, 2018 at 7:00 AM.

Moped BQP State #1
Waylon BMD State #8

EOG FR/PPE Policy is as follows.

All EOG employees, contractors and Regulatory personnel or other Non-EOG personnel are required to wear approved FR clothing and PPE on all EOG locations.

FR Clothing:

Approved FR pants or jeans

Approved FR shirts are to be long sleeves.

PPE includes:

H2S Monitors

Safety Glasses

Hard Hat

Steel toed or closed toe leather shoes.

If Non-EOG personnel do not have these items (excluding footwear), items can be provided by EOG.

Thank you,

Robert C. "Bob" Asher

Environmental Supervisor

Safety & Environmental Department

EOG Resources, Inc.

Artesia Division

Artesia, NM 88210

575-748-4217 (Office)

575-365-4021 (Cell)

EOG Safety Begins With YOUR Safety



Appendix F

Form C-141 Final Report

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street		Telephone No. 575-748-1471
Facility Name Waylon BMD State #8		Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-005-38256
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter C	Section 14	Township 11S	Range 34E	Feet from the 660	North/South Line North	Feet from the 2310	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 33.3712234 Longitude 103.4824219 NAD83

NATURE OF RELEASE

Type of Release Oil	Volume of Release 5 B/O	Volume Recovered 4.5 B/O
Source of Release Production Tank	Date and Hour of Occurrence 11/25/2017; PM	Date and Hour of Discovery 11/25/2017; PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Pumper drained water from oil tank to water tank. Left valve open to long causing to much fluid to equalize over. Causing water tank to run over. Vacuum truck(s) and roustabout/backhoe crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 10'X 30', this battery is bermed and has a synthetic liner. Vacuum truck recovered 4.5 B/O, remaining 0.5 B/O entrained within gravel material on top of liner. Roustabout crews removed impacted gravel, that gravel was disposed at an NMOCD approved facility. EOG Y will inspect liner and attest to liner integrity. **Depth to Ground Water: <50' (approximately 33.85', per NMOSE & USGS Groundwater Levels), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Based on demonstrating liner integrity, EOG Y Resources, Inc. certifies integrity with this C-141 Final Report and requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Robert Asher	Approved by Environmental Specialist:	
Title: Environmental Supervisor	Approval Date:	Expiration Date:
E-mail Address: bob_asher@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 9, 2018 Phone: 575-748-4217	1RP-	

* Attach Additional Sheets If Necessary