Submit 1 Copy To Appropriate District Office	State of New Mexico Rec'd 06/			
$\frac{\text{District I}}{100000000000000000000000000000000000$	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	30-025-47035			
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease STATE X FEE		
<u>District IV</u> - (505) 476-3460		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505		V-2884		
	S AND REPORTS ON WELLS S TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATE		HYPERION STATE		
PROPOSALS.) 1. Type of Well: Oil Well X Gas	Well 🔲 Other	8. Well Number _{208H}		
2. Name of Operator TAP ROCK OPERATING, LLC		9. OGRID Number 372043		
3. Address of Operator	10. Pool name or Wildcat			
602 PARK POINT DR, SUITE 200	WC025 G09 S243310P;UPPER WOLFCAMP			
4. Well Location Unit Letter A :634	feet from theline and	feet from the EAST line		
Section 20	Township 24S Range 33E	NMPM County LEA		
	1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3563 GR			

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	×	COMMENCE DRILLING OPNS.	P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB		
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM]				
OTHER:			OTHER:		
12 Describe managed on some	alatad amounting (Classify	state all m	artiment details, and size martiment dat	an including actimated data	

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Request to change Casing Plan.

Casing information with detailed intermediate casing procedure is attached.

Updated Casing Information:

Туре	Hole Size	Casing Size	Casing Weight/ft	Setting Depth	Sacks of Cement	Estimated TOC	Mud
Surf	17.5	13.375	54.5	1250	1280	0	Fresh Water
Int 1	9.875	7.625	29.7	9500	1310	0	Direct Emulsion
⊐nt 2 Int1	8.75	7.625	29.7	11900	776	5050	Direct Emulsion
Prod	6.75	5.5	20	11700	0	11200	OBM
Prod	6.75	5.5	20	17550	700	11200	OBM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Regulatory Manager

DATE 6/11/2020

Type or print name Christian Combs

E-mail address: ccombs@taprk.com

PHONE: (720)360-4028

For State Use Only

APPROVED BY: Conditions of Approval (if any

TITLE

DATE 07/07/2020

Drill Plan for Hyperion 4 Well Pad

Hyperion State #204H

Hyperion state #203H

Hyperion state #208H

Hyperion state #206H

Procedure for Intermediate:

- 1. P/U 9-7/8" tools and swap over mud system to Diesel Emulsion Mud (fully saturated diesel/brine).
- 2. Drill out float equipment and begin drilling into new formation. 9-7/8" hole will be drilled until the first pull point roughly at 9,700'.
- 3. 8-3/4" BHA will be picked up and drilled to the planned TD ~11,900'.
- 4. TOH and run casing
- 5. Casing schematic will be as follows:
 - a. 7-5/8" 29.7# P110 BTC will be ran to 9,500'
 - b. 7-5/8" 29.7# P110 W513 will be ran to 11,900'
 - c. DVT will be planned at 5,050' to perform a two-stage cement job
- 6. Cement job will be performed as follows:
 - a. Pump first stage cement job with 13.2 Primary (tail) to a planned TOC 300' above the DVT with 50% excess. Bump plug and test floats.
 - b. Shut down and drop opening bomb
 - c. Open DVT and begin circulating, take DEM mud back to tank farm, swap over to open top when cement is circulated to surface.
 - d. Begin pumping second stage
 - i. 11.5 lead with 100% excess will be pumped to surface with a 200' tail covering the DVT
 - ii. Bump plug verify sleeve has been closed.
 - e. Set pack-off and move off the well
 - f. Ensure valid casing tests are performed prior to drilling out equipment.

