Submit 1 Copy To Appropriate Di	istrict Office	State of N	ew Mexico			г	C 102	
District I - (575) 393-6161	Engray		nd Natural Resources				orm C-103 d July 18,2013	
1625 N. French Dr., Hobbs, NM 8	8240 Energy,	Willerais al	iu Naturai Resources	WELL A			<u> </u>	
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 8821	OIL C	CONSERVA	ATION DIVISION 30.025.39748 5. Indicate Type of Lease					
Disrtict III - (505) 334-6178		1220 South S	St. Francis Dr.				er	
1000 Rio Brazos Rd. Aztec, NM 8	87410				ATE 🗸		EE	
<u>District IV - (505) 476-3460</u>	NM 97505	Santa Fe,	NM 87505	6. State O	il & Gas Leas			
	1220 S. St. Francis Dr., Santa Fe, NM 87505 BO-0158-0019							
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT					7. Lease Name or Unit Agreement Name			
RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						NC1-8		
1. Type of Well: Oil Well 🗸 Gas Well 🗌 Other					8. Well Number #017			
2. Name of Operator	v ous wen outer			9. OGRIE				
Apache Corporation					873			
3. Address of Operator					10. Pool Name or Wildcat			
	ans Airpark Lane, Ste. 300	0, Midland,	TX 79705		mperial Tul	ob-Drink	ard	
4. Well Location Unit Letter	I : 1930	feet from the	S line and	660	feet from t	E	line	
Section	16 Township	23S	Range 37E	NMPM		County	LEA	
Section			OR, RKB,RT, GR, etc.)	1 (1/11 1/1		ounty	BEIT	
			300' GL					
	12. Check Appropriate Bo	ox To Indica	te Nature of Notice, Re	eport, or O	ther Data			
NOTIC	E OF INTENTION TO:			•	Γ REPORT (SE.		
PERFORM REMEDIAL WO		ANDON 🗸	REMEDIAL WORK	SEQUENT	ALTERING		<u>.</u>	
TEMPORARILY ABANDON		=	COMMENCE DRILLING	OPNS.	PANDA	5 07 (01110		
PULL OR ALTER CASING	MULTIPLE COM	_	CASING/CEMENT JOB		Ī			
DOWNHOLE COMMINGLE								
CLOSED-LOOP SYSTEM								
OTHER:	1 1		OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated								
date of starting any proposed work.) SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram or								
proposed completion or	recompletion.							
Anache Cornoration r	proposes to P&A the abov	e mentioned	well by the attached	l nrocedur	e Aclosed	l loon sy	stem will	
	all fluids from this wellbo			-			Stelli Will	
De useu ioi	all fluids from this welloc	ore and disp	osed of required by C	JOD Kule	13.13.17.14	INIAC.		
g 1D /			D' D 1 D	₋ S	ee Attach	ed		
Spud Date:			Rig Release Date:	Condi	tions of A	VOIDE	al	
				001141				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
Thereby certify that the i	information above is true at	ia compiete i	o the dest of my know.	ieuge and i	bellel.			
SIGNATURE	Guinn Burks	TITLE	Sr. Reclamation F	oromon	DATE	10	/2/20	
SIGNATURE	- Gunur Dur Ns	–	Si. Recialitation F	Oreman	DATE -	12	12120	
T	Cuine Durke	D 11	والمراجع والمراجع والمراجع والمراجع		DUONE	400.5	EC 04 40	
Type or print name	Guinn Burks	_E-mail add.	guinn.burks@apache	ecorp.com	PHONE: _	432-5	56-9143	
For State Use Only	A							
APPROVED BY:	Kerry Fortner	TITLE	Compliance Officer	Α	DATE 1	12/9/20		
Conditions of Approval (if	any): d							



 LEASE NAME
 NM BZ State NCT-8

 WELL #
 #017

 API #
 30.025.39748

 COUNTY
 LEA, NM

	WELL BORE INFO.
0	Cmt fell 10' on 5 1/2" by CBL
691	
	12 1/4' Hole 8 5/8" 24# @ 1089' w/750 sx CIRC to surf
1383	W/130 3x GING to 3dil
2074	
2766	
3457	
4148	

4840

5531

6223

6914

TD @ 6914'

Perfs @ 6059' - 6182'

Perfs @ 6478'-6607'

Prod equipment still in hole.

8 7/8" Hole 5 1/2" 17# @ 6914' w/ 1225 sx to surf



LEASE NAME	NM BZ State NCT-8
WELL#	#017
API#	30.025.39748
COUNTY	LEA, NM

PROPOSED PROCEDURE

Cmt fell 10' on 5 1/2" by CBL 0 691 12 1/4' Hole 8 5/8" 24# @ 1089' w/750 sx CIRC to surf 1383 2074 2766 3457 4148 4840 NOTE: Prior to MIRU P&A rig, a WO rig will MIRU & pull prod equip & set two CIBP's @ 6400' w/ 35' cmt & @ 6000' w/ no cmt CIBP @ 6000' w/ no cmt

CIBP @ 6400' w/ 35' cmt

8 7/8" Hole 5 1/2" 17# @ 6914'

w/ 1225 sx to surf

6223

6914

TD @ 6914

 PUH & spot 120 sx Class "C" cmt from 1139' to surf, fill up. (Surf Shoe, Rustler, Water Board, & Surf Plug)

3. PUH & spot 55 sx Class "C" cmt from 2887'-2370', WOC/TAG (Tansill, Yates, & 7 Rvrs)

2. PUH & spot 40 sx Class "C" cmt frm 3960'-3565', WOC/TAG (San Andres & Grayburg)

1. MIRU P&A rig, RIH w/ tbg & verify CIBP @ 6000', CIRC w/ MLF & spot 25 sx Class "C" cmt from 6000'-5800'. (Tubb)

Perfs @ 6059' - 6182'

Perfs @ 6478'-6607'

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- **19.** No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)