
		Rec	ceived NMOCD 11/30/20		
Submit 1 Copy To Appropriate District	State of New Me	xico			C-103
Office District 1 – (575) 393-6161	Energy, Minerals and Natur	ral Resources		Revised Augus	st 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
District II - (575) 748-1283	OIL CONSERVATION	DIVISION	30-041-20410		
811 S. First St., Artesia, NM 88210OIL CONSERVATION DIVISIONDistrict III - (505) 334-61781220 South St. Francis Dr.		5. Indicate Type of L			
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		6. State Oil & Gas Le	FEE	
$\frac{\text{District IV}}{\text{District IV}} - (505) 476-3460$	Salita Fe, Nivi 87	505	6. State Off & Gas Le 27116	ease no.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			27110		
SUNDRY NOT	ICES AND REPORTS ON WELLS		7. Lease Name or Un		Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLU	UG BACK TO A	SWEARINGEN I)	
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FC	JK SUCH			
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other			8. Well Number	1	
2. Name of Operator			9. OGRID Number		
ENDER VORENERGT RESOURCES; EI				190595	
3. Address of Operator			PETERSON PE		ATED)
4. Well Location	2006) Conference COUTU	line and	554 feet from the	WEST	line
Unit LetterL:					County
Section 20	Township 5S	Range 33E		CHAVES	County
	11. Elevation (Show whether DR, 4409' GL	, KKB, KI, GK, elc.)	,		Contraction of the
	4407 GE				
12 Check	Appropriate Box to Indicate N	ature of Notice	Report or Other Da	ita	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF I	NTENTION TO:		SEQUENT REPC		
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛	REMEDIAL WOR		TERING CAS	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	Т ЈОВ		
DOWNHOLE COMMINGLE					
071150	_	OTHER:			
OTHER:	pleted operations. (Clearly state all j	pertinent details, and	d give pertinent dates, i	including estir	nated date
of starting any proposed w	ork). SEE RULE 19.15.7.14 NMAG	C. For Multiple Con	mpletions: Attach well	bore diagram	of
proposed completion or re	completion.				
 NOTIFY NMOCD 24 HR 			See Attached		
2. MIRU. ND WH, NU BOPE.					
 CIRCULATE 9.5 PPG MLF AND TEST CASING. SPOT XXX OF CLASS "C" CEMENT FROM 5425'-5325'. WOC&TAG. (FISH) 					
THE AND CONFERE FORM OF OF A CONCENTER ON 4407' 4210' WOCKTAG (VESO/GLORIETA)					
 PERF AND SQUEEZE 30SX OF CLASS "C" CEMENT FROM 4497 -4319 . WOC&TAG. (FESO/GLOKIETA) PERF AND SQUEEZE 30SX OF CLASS "C" CEMENT FROM 2096'-1096'. WOC&TAG. (SHOE) 					
8 DERE AND SOLIFEZE 30SX OF CLASS "C" CEMENT FROM 475'-375', WOC&TAG, (FW)					
 9. STOTATES OF CLASS "C" CEMENT FROM 30X SURFACE. VERIFY CEMENT TO SURFACE. (SURFACE). 150 circ 10. CUTOFF WELLHEAD, ANCHORS 3' BELOW SURFACE AND INSTALL DRYHOLE MARKER. TURN OVER FOR 					S 50 sx Class ()' circ to surfac
10. CUTOFF WELLHEAD, A	ANCHORS 3' BELOW SURFACE	AND INSTALL DR	RYHOLE MARKER. T	URN OVER	FOR
RECLAMATION. 4" diar	neter 4' tall above ground marker				
	INMENT SYSTEM WILL BE USE	D FOR FLUIDS			
CLOSED LOOF CONTA	INVIENT STSTEM WILL DE OSE	DIORIECIDO.			
			5	1	
Spud Date:	Rig Release D	ate:			
				-	
×					
I hereby certify that the informatio	n above is true and complete to the b	best of my knowledg	ge and beller.		
	Korti				
SIGNATURE		SR REGULATORY	, ,		
ANALYSTDATE01/31/1	911/25/20				
		EEPONI INE CON	PHONE: (122)	687-1575	
Type or print name <u>JAN SOUTH</u> For State Use Only	E-mail address: <u>JSOUTH@</u>	LENONLINE.COM	I HORE(452)		
	A				
APPROVED BY: Xence Forther TITLE Compliance Officer A DATE 12/3/20					

WELLBORE DIAGRAM SWEARINGEN D #1



CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¹/₄" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)