| Submit 1 Copy To Appropriate District | | 09/17/2020 - NMOCD |
|--|---|--|
| Office | State of New Mexico | Form C-103 |
| District I - (575) 393-6161 | Energy, Minerals and Natural Resources | Revised July 18, 2013 |
| 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 | | WELL API NO. 30-025-04532 |
| 811 S. First St., Artesia, NM 88210 | OIL CONSERVATION DIVISION | 5. Indicate Type of Lease |
| District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 | 1220 South St. Francis Dr. | STATE 🗹 FEE 🗌 |
| $\frac{\text{District IV}}{1220 \text{ S}} = (505) 476-3460$ | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | |
| | TICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| | POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LICATION FOR PERMIT" (FORM C-101) FOR SUCH | Eunice Monument South Unit |
| PROPOSALS.) | | 8. Well Number 195 |
| Type of Well: Oil Well Name of Operator | Gas Well Other Injector | 9. OGRID Number |
| XTO Energy, Inc. | | 005380 |
| 3. Address of Operator | | 10. Pool name or Wildcat |
| 6401 Holiday Hill Road, Bldg 5 | Midland, Texas 79707 | Eunice Monument; Grayburg-San Andres |
| 4. Well Location | 1000 | |
| Unit Letter H | : 1965 feet from the North line and | |
| Section 6 | Township 21S Range 36E | NMPM County Lea |
| | 11. Elevation (Show whether DR, RKB, RT, GR, | etc.) |
| | | |
| 12. Check | Appropriate Box to Indicate Nature of Notice | ce. Report or Other Data |
| | | |
| | | JBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK | | |
| PULL OR ALTER CASING | | |
| DOWNHOLE COMMINGLE | | |
| CLOSED-LOOP SYSTEM | | |
| OTHER: | OTHER: | |
| | pleted operations. (Clearly state all pertinent details, | and give pertinent dates including estimated date |
| | | |
| of starting any proposed v | work). SEE RULE 19.15.7.14 NMAC. For Multiple | |
| of starting any proposed v proposed completion or re | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. | Completions: Attach wellbore diagram of |
| of starting any proposed v proposed completion or re | work). SEE RULE 19.15.7.14 NMAC. For Multiple | Completions: Attach wellbore diagram of |
| of starting any proposed w proposed completion or re XTO Energy, Inc. respectfully | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. | Completions: Attach wellbore diagram of |
| of starting any proposed w proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. | Completions: Attach wellbore diagram of |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. | Completions: Attach wellbore diagram of |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. | Completions: Attach wellbore diagram of |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. | Completions: Attach wellbore diagram of dure: |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. | Completions: Attach wellbore diagram of dure: ndition of Approval: notify |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process Co | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process Co | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process Co | Completions: Attach wellbore diagram of dure: ndition of Approval: notify |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following proced Co O prior | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours |
| of starting any proposed w proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process Co | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following proced Co O prior | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. | vork). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following proced Co O prior | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. | work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process Co O prior Rig Release Date: | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart |
| of starting any proposed w proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. 5. Return well to inj. | work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process Co O prior Rig Release Date: | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart edge and belief. |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. 5. Return well to inj. | work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process requests to reset the packer with the following process Rig Release Date: Rig Release Date: Rig Release Date: TITLE Supervisor, Regulato | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart edge and belief. |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. 5. Return well to inj. | work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process requests to reset the packer with the following process Rig Release Date: Rig Release Date: Rig Release Date: TITLE Supervisor, Regulato | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart edge and belief. |
| of starting any proposed v proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. 5. Return well to inj. | work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process requests to reset the packer with the following process Rig Release Date: Rig Release Date: Rig Release Date: TITLE Supervisor, Regulato | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart edge and belief. TyDATE_09/16/2020 |
| of starting any proposed w proposed completion or re XTO Energy, Inc. respectfully 1. MIRU 2. POOH w/tbg & pkr. 3. Reset pkr. 4. Run good MIT. 5. Return well to inj. 5. Return well to inj. | work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. requests to reset the packer with the following process requests to reset the packer with the following process Rig Release Date: Rig Release Date: Rig Release Date: TITLE Supervisor, Regulato | Completions: Attach wellbore diagram of dure: ndition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart edge and belief. ry DATE 09/16/2020 abadue@xtoener PHONE: 432-620-6714 |