Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

R	UREAU OF LAND MANA	GEMENT		·	5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WI Do not use this form for proposals to drill or to re					L NIME COOFTE OA		
Do not use thi abandoned wel	D) for such prop	r an		6. If Indian, Allottee	or Tribe Name		
			- 14	N 0 9 2010			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. NMNM94514X		
Type of Well		RECEIVED 8. Well Name and No. LUSK WEST DELAWARE UNIT 001			001		
Oil Well Gas Well Other: INJECTION 2. Name of Operator Contact: TRACIE CHE			_		9. API Well No.		
CIMAREX ENERGY COMPANY E-Mail: tcherry@cimarex.com			30-025-30518				
3a. Address 600 NORTH MARIENFELD S MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-620-1959			10. Field and Pool, or Exploratory LUSK DELAWARE, WEST			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 20 T19S R32E 330FNL 330FEL					LEA COUNTY,	NM	
12. CHECK APPR	ROPRIATE BOX(ES) TO	O INDICATE NA	TURE OF N	NOTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
	☐ Acidize	☐ Deepen		Production	on (Start/Resume)	☐ Water Shu	t-Off
Notice of Intent	Alter Casing	☐ Fracture	Ггеаt	☐ Reclama		☐ Well Integ	
☐ Subsequent Report	nt Report Casing Repair				ete .	Other	
Final Abandonment Notice	Change Plans	Plug and	Abandon	☐ Tempora	rily Abandon	_	
_	Convert to Injection	Plug Bac	· ·	□ Water Di	sposal		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Attach the site is ready for final attached that the site is ready for final attached the site is ready for final attached that the site is ready for final attached the site is ready for final attached the site is ready for final attached that the site is ready for final attached the site is ready for final attach	rk will be performed or provide operations. If the operation recond on the pandonment Notices shall be final inspection.) mission to recomplete the life recompletion is successful. If the particular is successful. I	The Bond No. on file sults in a multiple con led only after all requirements of the control of t	with BLM/BIA pletion or reccements, include Cherry Ca Record Capeta TEST OK, I FELL HEAD POH ANE SURE CAS	A. Required sub completion in a n ling reclamation anyon format b Lusk Deep " C(MIRU WSU 12NU 3K BOF D RUN CIBP ING TO 500	sequent reports shall be we interval, a Form 310, have been completed. ATTACHE ONDITIONS P, RELEASE INJECTION ON WIRELINE TO	e filed within 30 de 60-4 shall be filed and the operator hand the operator had been considered by the operator had been	ays once nas
14. Thereby certify that the foregoing is Name(Printed/Typed) TRACIE C	Electronic Submission # For CIMAREX Committed to AFMSS 1	(ENERGY COMPĂI	NY, sent to t URT SIMMO	the Hobbs	2012 ()		
Signature (Electronic S	Submission)	Date	: 10/23/2	012			
Signature (Electronic Submission) Dat THIS SPACE FOR FEDERAL O						ROVED	$\overline{}$
	HIIO SPACE P						
Approved By		Titi	petroleum	n Engineer	AN JAN	7 2013	

BUREAU OF LAND MANAGEMENT Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any definition states any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

Additional data for EC transaction #156001 that would not fit on the form

32. Additional remarks, continued

4. IF BOND LOG IS GOOD AND TOC IS ABOVE 4500?, PERFORATE CHERRY CANYON AS FOLLOWS:

? 4960'?4974?

- ? 4984'-5000'
- 5. PU TREATING PACKER ON 2-7/8? TUBING SPOT 500 GALS 7-1/2% DI NEFe ACID. PU WITH PACKER AT ~4850? AND CIRCULATE ACID INTO TUBING. SET PACKER AND BREAK DOWN PERFS WITH SPOT ACID. IMMEDIATELY FOLLOW WITH 2500 GALS 7-1/2% NEFe ACID.

6. SWAB BACK LOAD AND EVALUATE INTERVAL FOR PRODUCTIVE POTENTIAL. RELEASE PACKER AND POH WITH

7. PU 3-1/2? L-80 FRAC STRING TUBING AND PACKER. SET PACKER @ ~4850?. FRAC CHERRY CANYON AS PER DESIGN BASED ON RATES AND PRESSURES OF ACID STIMULATION.

8. FLOW AND SWAB BACK FRAC LOAD UNTIL SAND CLEARS UP. KILL WELL IF NECESSARY, RELEASE PACKER & POH, LD FRAC STRING AND BHA.

- 9. TIH WITH 2-7/8? TUBING OF TO ~5200? TO CHECK FOR FILL, CIRCULATE WELL CLEAN WITH 2% KCI FW.
- 10. PU PUMPING BHA ON 2-7/8? J-55 TUBING AND TIH. ND BOP, SET TAC, NU WELL HEAD & PUMPING TEE.

11. RUN RODS AND PUMP, SOHO.

- **12. RD WSU**
- 13. MI & SET PUMPING UNIT and production equipment.



Original Operator: Phillips Petroleum

Spud Date:

KB = 14' AGL

Original Well Name: Lusk Deep Unit #17


13:3/8" 54.5#355:@ 882'-w/1000sx C

DV Tool @ 2795!

8.5/8" 24#K-55 \$T&C @4510 1st Stage 500 \$X"C" Circulated 2nd Stage 850 \$X"C" thru DV Tool @ 2795' Circulated to surface

TOC Unknown

5-1/2ⁱⁱ 15:5# J55 @ 7220' -500 sc.Howco Litë & 300 sx "C" Neat



TD @ 7500'

Cimarex Energy Co. of Colorado Lusk Deep Unit "A" #17 FKA Lusk West Delaware Unit #001 API# 30-025-30518 330" FNL 330! FEL, Sec. 20 T-19-S, R-32-E

J Piwetz


9/5/2012

Current Conditions WIW

Packer @ 6373' w/on-off tool (8/27/2009)

6974'-90' (5/17/1991)

6468'-76' (Delaware, Brushy Canyon) (8/15/91)



Conditions of Approval

Cimarex Energy Company Lusk West Delaware Unit 001 API 30-025-30518 T19S-R32E, Sec 20

January 07, 2013

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work to be completed by April 07, 2013.

- 1. CIBP to be set at 6418' (50' above the top perforation). A minimum of 35' of Class C cement shall be bailed on top of the CIBP.
- 2. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp <i hep-qichopp@blm.gov> 575.234.2227 or Bob Ballard <b style="color: blue;">bballard@blm.gov> 575.234.5973.
- 3. Functional H₂S monitoring equipment shall be on location.
- 4. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record attached to an email to pswartz@blm.gov
- 5. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. Subject to like approval by the New Mexico Oil Conservation Division.
- 7. Notify BLM 575-200-7902 before plug back procedures. The procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. If there is no response, 575-361-2822. Note the contact, time, & date in your subsequent report.
- 8. Surface disturbance beyond the originally approved pad must have prior approval.
- 9. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 10. A minimum of 3,000 (3M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 11. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 12. Class H > 7,500' & Class C < 7,500') cement plugs(s) will be necessary. The minimum pumped volume of 25 sacks of cement slurry is to exceed a 100' cement plug across the drilled wellbore. Add 10% to the 100' slurry volume for each 1,000' of plug depth when calculations indicate the need. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.
- 13. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 14. File intermediate **subsequent sundry** Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- 15. Submit the BLM Form 3160-4 Completion Report within 30 days of the date all BLM approved procedures are complete. Include all formation tops.
- 16. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.
- 17. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies) before 05/10/2013.
- 18. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

Submit NOI for name change after "beneficial use" is determined. Proposed perfs are not in unitized formation.

JAM 010713