Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
<u>District II</u> – (575) 748-1283	OUL CONCERNATION DIVISION	30-025-06443
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 APR 2620	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505)	6. State Oil & Gas Lease No.
SUNDRY NOTICES	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATIO PROPOSALS.)	TO DRILL OR TO DEEPEN OR PLUG BACK TO A N FOR PERMIT" (FORM C-101) FOR SUCH	West Blinebry Drinkard Unit (WBDU) / 37346
	Well 🔽 Other Injection	8. Well Number 006
2. Name of Operator Apache Corporation		9. OGRID Number 873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 3000 M	lidland, TX 79705	Eunice; B-T-D, North (22900)
4. Well Location		
Unit Letter <u>B</u> :660	feet from the North line and 19	
Section 9 Township 21S Range 37E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	2' GL	
12 Charle Army	muista Davi ta Indianta Natura of Nation	Report or Other Date
**	opriate Box to Indicate Nature of Notice	•
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK I PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
		Formal Injection Control Program Manual
DOWNHOLE COMMINGLE		•
OTHER:		acker shall be set within or less than 100
13. Describe proposed or completed	operations. (Clearly state all pertinent details, a	Republic person and the second s
of starting any proposed work).	SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
proposed completion or recomple	tion.	
Anache would like to perform the attach	ed workover to return this well to injection.	
Apache would like to perform the attach		
The Oil Conservation D		ndition of Approval: notify
MUST BE NOTIFIED 24	Hours O	CD Hobbs office 24 hours
Prior to the beginning of o	perations prior	of running MIT Test & Chart
Spud Date: 10/12/1962	Rig Release Date:	
I hereby certify that the information above	is true and complete to the best of my knowled	ge and belief.
SIGNATURE Relso Holland	fisher TITLE Sr. Staff Reg Tech	DATE 4/24/2012
+9		DATE <u>4/24/2013</u>
Type or print name <u>Reesa Holland Eisher</u> For State Use Only	E-mail address: Reesa Holland@ap	achecorp.com PHONE: 432/818-1062
THE I NET MAS 120 7.10		
APPROVED BY: Angeline TITLE DIST. MALE DATE = 50-2013		
Conditions of Approval (if any);		. •*
		APR 30 2013
÷		ALLA

.

WBDU #6W Proposed Procedure

- **Day 1:** MIRU. Install BOP. RIH w/ 6-1/8" washover shoe w/ internal cut-rite, washover pipe w/ grapple, and string mill on 2-7/8" ws
- Day 2: Work through tight spots in casing, circulate clean. Attempt to washover and retrieve fish
- Day 3: Cont. to attempt to retrieve fish. POOH
- Day 4: RIH, cut over and remove CIBP and Model D packer pushed to 6702'
- **Day 5:** Continue to cut over and remove CIBP and Model D packer pushed to 6702'. Clean well out to original PBTD at +/-6740'
- **Day 6:** RU wireline unit. RIH w/GR/CNL/CCL/CBL. Log well from TD to surface. POOH. (Drinkard perfs to be determined from log evaluation)
- **Day 7:** RU csg crew & equipment. RIH 4-1/2" 11.6# J-55 csg C/W centralizers, float equipment, marker joint, and stage tool to +/- 6735'
- Day 8: Perform two stage cement job to surface. WOC
- **Day 9:** RIH w/ 3-3/4" bit on 2-3/8" ws. Drill out stage tool, float collar, and cement to +/- 6720'. Clean well out to PBTD. POOH
- **Day 10:** RU wireline unit. Perforate the Drinkard as per the log evaluation above @ 4 SPF, 90 Deg phasing
- Day 11: RIH w/4-1/2" treating packer on 2-3/8" tbg. Set pkr @ +/-6400'. Acidize the Drinkard w/10,000 gals 15% HCI-NE-FE BXDX acid and rock salt in 3 equal stages. Release pkr. Wash out salt. POOH
- **Day 12:** RIH w/4-1/2" injection packer, on-off tool and 2-3/8" tbg. Set pkr @ +/- 6400'. P/T backside to 500 psi. Rel. on/off tool and POOH LD ws
- Day 13: RIH w/2-3/8" IPC inj tbg. Latch on to packer @ +/- 6400'. RO

Day 14: Run MIT for NMOCD

i

Allow injection rates to stabilize, run injection profile and temperature survey

Return well to injection, and at a later date, shut well in to perform fall-off test or static gradient



