Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM01218

SUNDRY NOTICES AND REPORTS ON WELLS.

Do not use the	ie form for proposals to dri	ill or to re- Mily 2 Q 2	012		
Do not use this form for proposals to drill or to re-enter an 6 2013 abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian. Allottee of	or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side VED				7. If Unit or CA/Agre SW72	ement, Name and/or No.
1. Type of Well ☐ Gas Well ☐ Other				8. Well Name and No. ELLIOTT-A 01	
2. Name of Operator Contact: JENNIFER A DUARTE YATES DRILLING COMPANY E-Mail: jennifer_duarte@oxy.com				9. API Well No. 30-025-20104-00-S1	
3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	b. Phone No. (include area co h: 713-513-6640	ie)	10. Field and Pool, or Exploratory LUSK		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State	
Sec 30 T19S R32E NENE 660FNL 660FEL				LEA COUNTY, NM 🗸	
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	NDICATE NATURE OF	FNOTICE, R	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION		ТҮРЕ			
■ Notice of Intent	□ Acidize	□ Deepen	☑ Produc	tion (Start/Resume)	■ Water Shut-Off
	Alter Casing	☐ Fracture Treat	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recom	plete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Tempo	rarily Abandon	
	Convert to Injection	☐ Plug Back	☐ Water I	Disposal	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) The Elliott Hall A-1 is currently down with a tubing leak. This is the last well on the subject lease. Partner approval is required before repair work can begin based on the Joint Operating Agreement, and Single Expenditure Limits. Oxy has balloted partners and expects to receive full partner approval by 6/3/13 for this repair. Work is expected to begin on or before 6/7/13. Duration for this repair should be no more than (3) working days from date work is initiated. Oxy respectfully submits this sundry for approval. 1. MIRU Co-Rod Unit and WO Rig. 2. Hold PJSM, check well pressure(s). 3. Load and test tubing to verify tubing leak. 4. Unseat pump. 5. POH w/ Co-Rod and pump. Visually inspect equipment for signs of wear, corrosion, pitting and					
Соп	Electronic Submission #208	LING COMPÁNY, sent to ing by KURT SIMMONS o	the Hobbs n 05/23/2013 (1	3KMS22033E) ARLS	ANPIELUE
Name(17mea/1ypea) JENNIFER	ADUANIE	Title REGO	JLATORY SP	ECIALIST	
Signature (Electronic S	ubmission)	Date 05/22	/2013		
	THIS SPACE FOR	FEDERAL OR STATI	OFFICE U	SE	
Approved By EDWARD FERNAN Conditions of approval, if any, are attaches certify that the applicant holds legal or equaliches would entitle the applicant to condu	warrant or oject lease	TitlePETROLEUM ENGINEER Date 05/23/2013 Office Hobbs			
Fitle 18 U.S.C. Section 1001 and Title 43	S.C. Section 1219, make it scrin	ne for any person knowingly a	nd willfully to m	ake to any department or	agency of the United

Additional data for EC transaction #208342 that would not fit on the form

32. Additional remarks, continued

damage. Send in pump for inspection. Collect solids/paraffin samples and provide to chemical company for analysis.

6. ND WH & NU BOPE.

şì

b. ND WH & NU BOPE.
7. RU scan loggers, release TAC & POH w/ 2-7/8? L-80 tubing. Scan tubing out of hole, LD bad joints and replace. RD scan loggers.
8. RIH w/ new BHA & 2-7/8? L-80 tubing.
9. ND BOPE, set TAC, NU WH.
10. RIH w/ new or rebuilt pump and Co-Rod.
11. RU surface equipment, space out & install polished rod. Load and pressure test tubing to 500 per Check pump action.

psi. Check pump action.

12. Nalco to provide wellbore cleanup recommendation to be performed before well hung on and returned to production.