Submit 1 Copy To Appropriate District Office	State of New Me	exico		Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-025-36149	/
811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate Type of Le	2956
District III - (505) 334-6178 1220 South St. Francis Dr.		STATE STEE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	7505	6. State Oil & Gas Le	
1220 S. St. Francis Dr., Santa Fe, NM				
87505	CES AND REPORTS ON WELLS		7 Loosa Nama or Uni	it Agreement Name
(DO NOT USE THIS FORM FOR PROPOS			7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Section 32	51III	
PROPOSALS.) 1. Type of Well: Oil Well as Well Other		8. Well Number 537		
2. Name of Operator		9. OGRID Number: 157984		
Oxy USA Inc		9. OGRID Nulliber: 137984		
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)		
2611 Plains Hwy Denver City, TX 79323				
4. Well Location	,,	-	<u></u>	
	6feet from theNorth line	e and 1403	feet from the East	line
Section 32	Township 18S			ea County
Section 32	11. Elevation (Show whether DR			Ca
	3641' GR	, KKD, KI, GK, cic.		
12 Check A	appropriate Box to Indicate N	ature of Notice	Report or Other Dat	·a
12. Check A	appropriate Box to maleate is		report of Other Dat	·u
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPO	RT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR			K 🗌 ALT	TERING CASING 🔲
TEMPORARILY ABANDON 🛛	CHANGE PLANS	COMMENCE DR	ILLING OPNS.□ PA	ND A
PULL OR ALTER CASING	MULTIPLE COMPL '	CASING/CEMEN	Т ЈОВ	
DOWNHOLE COMMINGLE				
OTLIEB				
OTHER:	Clearly state all	OTHER:	d aiva mantinant datas in	oludina astimatad data
13. Describe proposed or compl	eted operations. (Clearly state all	pertinent details, an		
13. Describe proposed or compl of starting any proposed wo	rk). SEE RULE 19.15.7.14 NMA	pertinent details, an		
13. Describe proposed or compl	rk). SEE RULE 19.15.7.14 NMA	pertinent details, an	mpletions: Attach wellb	ore diagram of
13. Describe proposed or compl of starting any proposed wo	rk). SEE RULE 19.15.7.14 NMA	pertinent details, an	mpletions: Attach wellb	
Describe proposed or complete of starting any proposed wo proposed completion or recomplete. POOH with prod equipment.	rk). SEE RULE 19.15.7.14 NMACompletion.	pertinent details, an	mpletions: Attach wellb	ore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.1) POOH with prod equipment 2) Clean out to 4000'.	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb	ore diagram of
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980'. 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb	ore diagram of
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980' RUN MIT 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980'. 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb	ore diagram of SS OCD 3 2013
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980' RUN MIT 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980' RUN MIT 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980' RUN MIT 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980' RUN MIT 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980' RUN MIT 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA	rk). SEE RULE 19.15.7.14 NMACOMPletion. Cap with 35' of cmt.	pertinent details, an C. For Multiple Con	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
 Describe proposed or complete of starting any proposed wo proposed completion or reconstruction. POOH with prod equipment 2. Clean out to 4000'. RIH with CIBP set at 3980' RUN MIT 	rk). SEE RULE 19.15.7.14 NMACOMPletion.	pertinent details, an C. For Multiple Con	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA	rk). SEE RULE 19.15.7.14 NMACOMPletion. Cap with 35' of cmt.	pertinent details, an C. For Multiple Con	mpletions: Attach wellb HOB: JUL 2	ore diagram of SS OCD 3 2013
13. Describe proposed or compl of starting any proposed wo proposed completion or reco 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date:	rk). SEE RULE 19.15.7.14 NMACOMPletion. Cap with 35' of cmt. Rig Release Da	pertinent details, an C. For Multiple Con	MOBS JUL 2 RECE	ore diagram of SS OCD 3 2013
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA	rk). SEE RULE 19.15.7.14 NMACOMPletion. Cap with 35' of cmt. Rig Release Da	pertinent details, an C. For Multiple Con	MOBS JUL 2 RECE	ore diagram of SS OCD 3 2013
13. Describe proposed or compl of starting any proposed wo proposed completion or reco 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date:	rk). SEE RULE 19.15.7.14 NMACOMPletion. Cap with 35' of cmt. Rig Release Da	pertinent details, an C. For Multiple Con	MOBS JUL 2 RECE	ore diagram of SS OCD 3 2013
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA	Rig Release Date of the brown o	pertinent details, an C. For Multiple Con ate:	HOB: JUL 2 RECE	ore diagram of SS OCD 3 2013
13. Describe proposed or compl of starting any proposed wo proposed completion or reco 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date:	Rig Release Date of the brown o	pertinent details, an C. For Multiple Con	HOB: JUL 2 RECE	ore diagram of SS OCD 3 2013
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date:	Rig Release Date of the bound o	pertinent details, an C. For Multiple Contact ate: est of my knowledge pecialist	mpletions: Attach wellb HOB: JUL 2 RECE	ore diagram of BS OCD 3 2013 EIVED
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date: I hereby certify that the information at SIGNATURE Steve Snead	Rig Release Date of the bound o	pertinent details, an C. For Multiple Contact ate: est of my knowledge pecialist	HOB: JUL 2 RECE	ore diagram of BS OCD 3 2013 EIVED
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date:	Rig Release Date of the bound o	pertinent details, an C. For Multiple Con ate: est of my knowledg becialist steve_snead@ox	THE TOTAL STATE OF THE STATE AND THE STATE A	ore diagram of BS OCD 3 2013 EIVED 6-592-6312
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date: I hereby certify that the information at SIGNATURE Steve Snead	Rig Release Date of the bound o	pertinent details, an C. For Multiple Contact ate: est of my knowledge pecialist	THE TOTAL STATE OF THE STATE AND THE STATE A	ore diagram of BS OCD 3 2013 EIVED 6-592-6312
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date: I hereby certify that the information at SIGNATURE Steve Snead For State Use Only APPROVED BY:	Rig Release Date of the beautiful address: See RULE 19.15.7.14 NMAC completion. Rig Release Date of the beautiful address: See E-mail address: See TITLE County TITLE	est of my knowledg becialist steve_snead@ox	THE TOTAL STATE OF THE STATE AND THE STATE A	ore diagram of BS OCD 3 2013 EIVED 6-592-6312
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date: I hereby certify that the information at the start of the	Rig Release Da TITLE_Lift Sp. E-mail address: St. National Right Control of the beauty	est of my knowledg becialist steve_snead@ox	RECE DATE 7/22/13 LY.com PHONE:806	ore diagram of BS OCD 3 2013 EIVED 6-592-6312 7-26-2013
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. 1) POOH with prod equipment 2) Clean out to 4000'. 3) RIH with CIBP set at 3980' 4) RUN MIT 5) Well is TA Spud Date: I hereby certify that the information at SIGNATURE Steve Snead For State Use Only APPROVED BY:	Rig Release Da TITLE_Lift Sp. E-mail address: St. National Right Control of the beauty	est of my knowledg becialist steve_snead@ox	THE TOTAL STATE OF THE STATE AND THE STATE A	ore diagram of BS OCD 3 2013 EIVED 6-592-6312 7-26-2013