Office'	State of New Me		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	HOBBS OCD	WELL API NO.	
District II ~ (575) 748-1283	TOTAL CONFEDERATIONS	DIVISION 30-025-39808	
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178	1 S. First St., Artesia, NM 88210 strict III – (505) 334-6178 00 Rio Brazos Rd., Aztec, NM 87410 AUG 29 2020 South St. Francis Dr. Sonto Fo. NIM 87505		of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87	STATE	FEE _
<u>District IV</u> – (505) 476-3460	Santa Fe, INIVI 67	6. State Oil & Ga	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	RECEIVED		ļ
	ICES AND REPORTS ON WELLS	7 Lease Name o	r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			· Cint / ig/Coment / june
	ICATION FOR PERMIT" (FORM C-101) FO		A 15 STAZÉ
PROPOSALS.)		8. Well Number	
1. Type of Well: Oil Well	Gas Well 🛛 Other		
2. Name of Operator		9. OGRID Numb	per /
Devon Energy Production Company, LP		6137	
3. Address of Operator		10. Pool name or	
333 W. Sheridan Avenue, Oklahoma City, OK 73102		WILDCAT; WO	LFCAMP GAS
4. Well Location			
Unit Letter J:	1700 feet from the South	line and 1840 feet from th	e East line
Section 15			
Section 13			ty, NM
	11. Elevation (Show whether DR,	RKB, R1, GR, etc.)	
	3716' GL		The state of the s
12. Check	Appropriate Box to Indicate N	ature of Notice, Report or Other	Data
	NTENTION TO:	SUBSEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛	REMEDIAL WORK	ALTERING CASING 🗌
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.□	P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE			
			
OTHER:		OTHER:	
	pleted operations. (Clearly state all p		es, including estimated date
13. Describe proposed or com		pertinent details, and give pertinent dat	
13. Describe proposed or com	ork). SEE RULE 19.15.7.14 NMAC		
13. Describe proposed or com- of starting any proposed w	ork). SEE RULE 19.15.7.14 NMAC	pertinent details, and give pertinent dat	
13. Describe proposed or com of starting any proposed w proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC	ertinent details, and give pertinent dat E. For Multiple Completions: Attach v	
13. Describe proposed or com of starting any proposed w proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC completion.	ertinent details, and give pertinent dat E. For Multiple Completions: Attach v	
13. Describe proposed or com of starting any proposed w proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole Se	ertinent details, and give pertinent dat E. For Multiple Completions: Attach v	
13. Describe proposed or com of starting any proposed w proposed completion or re Plug and abandon 104' hole drilled	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom.	ertinent details, and give pertinent dat E. For Multiple Completions: Attach v	
 13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom.	pertinent details, and give pertinent dat E. For Multiple Completions: Attach vervices)	
 13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface.	pertinent details, and give pertinent dat E. For Multiple Completions: Attach vervices)	
 13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface.	pertinent details, and give pertinent dat E. For Multiple Completions: Attach vervices)	
 13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface.	pertinent details, and give pertinent dat E. For Multiple Completions: Attach vervices)	
 13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole Seng and tag bottom. surface.	pertinent details, and give pertinent dat E. For Multiple Completions: Attach vervices)	
13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grant from 104' to 3.	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole Seng and tag bottom. surface.	pertinent details, and give pertinent dat E. For Multiple Completions: Attach vervices)	
 13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole Seng and tag bottom. surface.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker.	
13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grant from 104' to 3.	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface. ound level. Top out with cement & s	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker.	
13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grant from 104' to 3.	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface. ound level. Top out with cement & s	ertinent details, and give pertinent dat E. For Multiple Completions: Attach v ervices) et dry hole marker.	
13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grows and the starting of th	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface. ound level. Top out with cement & see and level. Top out with cement & see and level.	ertinent details, and give pertinent dat For Multiple Completions: Attach vervices) et dry hole marker. te:	
13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grows and the starting of th	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface. ound level. Top out with cement & s	ertinent details, and give pertinent dat For Multiple Completions: Attach vervices) et dry hole marker. te:	
13. Describe proposed or comof starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grant from 104' to 3'	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and tag bottom. surface. ound level. Top out with cement & see and level. Top out with cement & see and level.	ertinent details, and give pertinent dat For Multiple Completions: Attach vervices) et dry hole marker. te:	
13. Describe proposed or comof starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grant from 104' to 3'	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best above is true and complete to the best above.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker. te: est of my knowledge and belief.	wellbore diagram of
13. Describe proposed or composed of starting any proposed was proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grows and the starting of th	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best above is true and complete to the best above.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker. te: est of my knowledge and belief.	
13. Describe proposed or come of starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below grant from 104'. Spot Completion of the proposed or complete to the proposed of the proposed we proposed to the proposed of the proposed we proposed to the proposed of the proposed or complete the proposed or complete the proposed or complete the proposed or proposed	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best see above. TITLE_Operation.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker. te: est of my knowledge and belief.	ATE 8/28/13
13. Describe proposed or comof starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below growing and Date: Spud Date: Thereby certify that the information and Signature S	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best see above. TITLE_Operation.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker. te: est of my knowledge and belief.	wellbore diagram of
13. Describe proposed or comof starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below growing and Date: Spud Date: Thereby certify that the information and Signature S	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best see above. TITLE_Operation.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker. te: est of my knowledge and belief. ations Technician	ATE 8/28/13 =_405-552-4615
13. Describe proposed or come of starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below growing and below growing that the information of the state	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best see above. TITLE_Operation.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker. te: est of my knowledge and belief. ations Technician	ATE 8/28/13 =_405-552-4615
13. Describe proposed or come of starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below growing and below growing the start of the star	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best see above. TITLE_Operation.	ertinent details, and give pertinent date. For Multiple Completions: Attach vervices) et dry hole marker. te: est of my knowledge and belief. ations Technician	ATE 8/28/13
13. Describe proposed or comof starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below growing and Date: Spud Date: Thereby certify that the information and Signature S	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best above is true above is true above is true above is true above is	te: te: te: te: tof my knowledge and belief. tonnie.Slack@dvn.com PHONE.	ATE 8/28/13 =_405-552-4615
13. Describe proposed or come of starting any proposed we proposed completion or responsed and abandon 104' hole drilled 1. MIRU. TIH w/2-7/8" tubing 2. Spot cement from 104' to 3. Cut conductor 3' below growing and below growing the start of the star	ork). SEE RULE 19.15.7.14 NMAC completion. by spudder rig (Butches Rat Hole See and and tag bottom. surface. ound level. Top out with cement & see above is true and complete to the best see above. TITLE_Operation.	te: St of my knowledge and belief. Stonnie.Slack@dvn.comPHONE. Plance Office Must Ro Notified.	ATE 8/28/13 =_405-552-4615

SEP 0 3 2018

DEVON ENERGY	PRODUCTION COMPANY LP	
Well Name: BLACK MAMBA 15 STATE 1	Field: WILDCAT; WOLFCAMP GAS	
ocation: 1700 FSL & 1840' FEL; SEC 15-T23S-R33E	County: LEA State: NM	
Elevation: 3716' GL	Spud Date: 7/26/10 Compl Date: Not completed	
API#: 30-025-39808 Prepared by: Ronnie Slack	Date: 8/27/13 Rev:	
48" Hole 30" conductor w/locking lid @ 6' Cmt'd back to 3', fill dirt from 3' to surface	Proposed: 1. Cut conductor 3' BGL, top out w/cmt. 2. Set dry hole marker Proposed: 1. Spot cmt from 104' to surface (Approx 190 sx cmt. 1.32 cu ft / sx	

