


Office District 1 – (575) 393-6161 HOEBS Decay, Minerals and Natural Resources Revise	Form C-103 d August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 WELL API NO	
811 S. First St., Artesia, NM 88210 SEP 1 9 2013 1220 South St. Francis Dr. 5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM RECEIVED 87505	<i>.</i> .
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 7. Lease Name or Unit Agree Linam AGI	eement Name
PROPOSALS.) 1. Type of Well: Oil Well, Gas Well Other 8. Well Number 1	
2. Name of Operator 9. OGRID Number 36785 DCP Midstream LP	
3. Address of Operator 370 17 th Street, Suite 2500, Denver CO 80202 10. Pool name or Wildcat Wildcat	
4. Well Location	
Unit Letter K; 1980 feet from the South line and 1980 feet from the West line Section 30 Township 18S Range 37E NMPM Count	y Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3736 GR	
TANK TO THE PARTY OF THE PARTY	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING COMMENCE DRILLING OPNS. P AND A DOWNHOLE COMMINGLE CASING/CEMENT JOB CASING/CEMENT JOB P AND A DOWNHOLE COMMINGLE P AND A DOWNHOLE COMMINGLE P AND A CASING/CEMENT JOB P AND A DOWNHOLE COMMINGLE P A	OF: G CASING
OTHER: OTHER: Monthly Report pursuant to Workover (
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, includin of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore dia proposed completion or recompletion.	
Monthly Report for the Month ending August 31, 2013 (8/1/13-9/1/13) Pursuant to Workover C-103 for Linam AG This is the sixteenth monthly submittal of data as agreed to between DCP and OCD relative to injection pressure, TAG ter casing annulus pressure. As shown on the attached graphs, there has continued to be some fluctuation in the data due to flows due to power failures from lightning. DCP continues to implement modified operational procedures to better maintained to the procedure of the pr	mperature and luctuating gas ain the pressure
and temperature conditions in the well in order to minimize the opportunity for corrosion in the tubing. Average tempera pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Tempand Pressure Differential: 1472 psig.	
pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Temp	orrature: 121°F, arly that the onth of August emperature and continue to
pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Temp and Pressure Differential: 1472 psig. The data clearly show the effect of the changing temperature and pressure in the annulus and continue to demonstrate clear workover successfully eliminated all connection between the tubing and the annular space. At several times during the method facility had some power outages due to lightning which caused brief shutdowns and corresponding variations in the pressure. See attached graphs containing explanation of observed trends and excel spreadsheet for raw data. All the data confirm the integrity of the tubing which was replaced last year and the well continues to serve as a safe, effective and environments.	orrature: 121°F, arly that the onth of August emperature and continue to
pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Temp and Pressure Differential: 1472 psig. The data clearly show the effect of the changing temperature and pressure in the annulus and continue to demonstrate clear workover successfully eliminated all connection between the tubing and the annular space. At several times during the method facility had some power outages due to lightning which caused brief shutdowns and corresponding variations in the pressure. See attached graphs containing explanation of observed trends and excel spreadsheet for raw data. All the data confirm the integrity of the tubing which was replaced last year and the well continues to serve as a safe, effective and environments of the continue of Class II wastes consisting of H ₂ S and CO ₂ . I hereby certify that the information above is true and complete to the best of my knowledge and belief.	orrature: 121°F, arly that the onth of August emperature and continue to vironmentally-
pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Temp and Pressure Differential: 1472 psig. The data clearly show the effect of the changing temperature and pressure in the annulus and continue to demonstrate clear workover successfully eliminated all connection between the tubing and the annular space. At several times during the method facility had some power outages due to lightning which caused brief shutdowns and corresponding variations in the pressure. See attached graphs containing explanation of observed trends and excel spreadsheet for raw data. All the data confirm the integrity of the tubing which was replaced last year and the well continues to serve as a safe, effective and environments of the system to dispose of Class II wastes consisting of H ₂ S and CO ₂ . I hereby certify that the information above is true and complete to the best of my knowledge and belief.	orrature: 121°F, arly that the onth of August emperature and continue to vironmentally-
pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Tempand Pressure Differential: 1472 psig. The data clearly show the effect of the changing temperature and pressure in the annulus and continue to demonstrate clea workover successfully eliminated all connection between the tubing and the annular space. At several times during the method facility had some power outages due to lightning which caused brief shutdowns and corresponding variations in the pressure. See attached graphs containing explanation of observed trends and excel spreadsheet for raw data. All the data confirm the integrity of the tubing which was replaced last year and the well continues to serve as a safe, effective and environment of the serve of the dispose of Class II wastes consisting of H ₂ S and CO ₂ . I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Consultant to DCP Midstream/ Geolex, Inc. DATE 9/9/20	arly that the onth of August emperature and continue to vironmentally-
pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Temp and Pressure Differential: 1472 psig. The data clearly show the effect of the changing temperature and pressure in the annulus and continue to demonstrate clear workover successfully eliminated all connection between the tubing and the annular space. At several times during the method facility had some power outages due to lightning which caused brief shutdowns and corresponding variations in the pressure. See attached graphs containing explanation of observed trends and excel spreadsheet for raw data. All the data confirm the integrity of the tubing which was replaced last year and the well continues to serve as a safe, effective and environments of the system to dispose of Class II wastes consisting of H ₂ S and CO ₂ . I hereby certify that the information above is true and complete to the best of my knowledge and belief.	arly that the onth of August emperature and continue to vironmentally-
pressures for the report period are as follows: TAG Injection Pressure: 1565 psig, Annulus Pressure: 94 psig, TAG Temp and Pressure Differential: 1472 psig. The data clearly show the effect of the changing temperature and pressure in the annulus and continue to demonstrate clear workover successfully eliminated all connection between the tubing and the annular space. At several times during the method facility had some power outages due to lightning which caused brief shutdowns and corresponding variations in the pressure. See attached graphs containing explanation of observed trends and excel spreadsheet for raw data. All the data confirm the integrity of the tubing which was replaced last year and the well continues to serve as a safe, effective and environment of the data confirm that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Consultant to DCP Midstream/ Geolex, Inc. DATE 9/9/20 Type or print name Alberto A. Gutierrez, RG E-mail address: aag@geolex.com PHONE: 505-842-800	arly that the onth of August emperature and continue to vironmentally-

Fluctuations in annular pressure observed during the month of August 2013 primarily represent the correlative behavior of the annular pressure with the flowrate and injection pressure. There were several temporary shutdowns of the plant during the month of August due to power failures at the AGI facility. These issues were generally corrected within hours. On A/13 a lightning strike resultated in a power outage at the AGI facility which was resolved within even hours. At these times the annular pressure drops significantly when injection rates are reduced, as can be seen on the graph. The effect in also visible on the pressure/temperature graphs during the same period as the flow drops and temperature varies. These drops are also associated with decreased annular pressure, as demonstrated on the graph. The significant spread between TAG injection pressure (inside tubing) and the annular pressure proves the continuing integrity of the well and the tubing.

TAG injection Flowrate (scf/h) —TAG injection Pressure (psig) —Casing Annulus Pressure (psig)









DCP Midstream EIVED OCD 1625 West Marland St Ofc. (575) 397-5552 Fax (575) 397-5598

RECEIVED 9-25-2013

HOBBS OCD

SEP 1 9 2013

Electronic MAIL:

September 11, 2013

Mr. Elidio Gonzales
District Supervisor
New Mexico Oil Conservation Division
Hobbs Office – District 1
1625 North French Dr.
Hobbs, NM 88240

Re: August C-103 monthly report, Linam AGI #1

Dear Mr. Gonzales:

This letter serves as DCP Midstream, LP's (DCPM) response to file a monthly C-103 report with the OCD. DCPM will continue to operate as per our original approved injection order as modified by the C-103 approved on 5/3/2012 which requires monthly reporting and MIT every 6 months.

If you have any questions about the information included in this submittal, please feel free to contact me at 575-397-5505 or via email at SJHarless@dcpmidstream.com.

Sincerely,

Steve Harless

General Manager of Operations, SENM

SH; de

cc: Will Jones, New Mexico OCD

Steve Boatenhamer, DCPM - Hobbs

Russ Ortega, DCPM - Hobbs

Quentin Mendenhall, DCPM – Midland Paul Tourangeau, DCPM – Denver Jonas Figueroa, DCPM – Midland

Chris Root, DCPM - Denver

Alberto Gutierrez, Geolex – Albuquerque