Form 3160-5 (August 2007)	UNITED STAT DEPARTMENT OF THE BUREAU OF LAND MAN	ES EINTERIOR	CD HODDS HOBBS OCD	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No.		
Do not	NDRY NOTICES AND REP use this form for proposals	55 2 5 20	015 Lease Serial NO. NMNM0556297 6. If Indian, Allottee or Tribe Name			
abando	ned well. Use form 3160-3 (A	PD) for such proposa				
SUBMI	IN TRIPLICATE - Other instr	uctions on reverse sid	le. RECEIV	7. If Unit or CA/Agre	ement, Name and/or No.	
<ol> <li>Type of Well</li> <li>Oil Well Gas We</li> </ol>	II 🔲 Other			8. Well Name and No. WILDCAT 21 LI F	ED COM 1H	
2. Name of Operator MEWBOURNE OIL C	Contact OMPANY E-Mail: jlathan@	JACKIE LATHAN	AN 9. API Well No 30-025-41 26 41261			
3a. Address PO BOX 5270 HOBBS, NM 88241		3b. Phone No. (include Ph: 575-393-5905 Fx: 575-397-6252	area code)	10. Field and Pool, or BONE SPRING		
	ge, Sec., T., R., M., or Survey Descript		······································	11. County or Parish,	11. County or Parish, and State	
Sec 21 T23S R34E N	WSW 2310FSL 150FWL			LEA COUNTY,	LEA COUNTY, NM	
	K APPROPRIATE BOX(ES)	TO INDICATE NATU	RE OF NOTICE, I	L REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSIC	ON	,	FYPE OF ACTION	<u></u>		
□ Notice of Intent	🗖 Acidize	🗖 Deepen	🗖 Produ	ction (Start/Resume)	U Water Shut-Off	
	Alter Casing	Fracture Trea	t 🗖 Reclai	nation	Well Integrity	
Subsequent Report	Casing Repair	New Constru	—	1	☑ Other Drilling Operations	
🗖 Final Abandonment N	Iotice         Image         Change         Plans           Image         Convert to Injection         Injection <td>Plug and Aba n D Plug Back</td> <td>ndon 🔲 Tempo</td> <td>orarily Abandon Disposal</td> <td>2 milling operations</td>	Plug and Aba n D Plug Back	ndon 🔲 Tempo	orarily Abandon Disposal	2 milling operations	
Attach the Bond under whi following completion of the testing has been completed determined that the site is r 08/30/13 TD 8 3/4" ho Class H Lite (50:50:10 w/additives. Mixed @ rate lift pressure @ 23	directionally or recomplete horizontal the work will be performed or provi- involved operations. If the operation Final Abandonment Notices shall be eady for final inspection.) le @ 11780'. Ran 11780' of 7" ) w/additives. Mixed @ 11.9 #/ 15.6 #/g w/1.18 yd. Plug down 40# @ 3 BPM. Ran temp surv t 3:00 PM 09/02/13, tested csg	ide the Bond No. on file with results in a multiple completi filed only after all requirement 26# P110 BT&C & LT&C g w/2.47 yd. Tail w/400 @ 2:45 PM 08/30/13. D ey indicating TOC @ 41	BLM/BIA. Required s on or recompletion in a tts, including reclamati C csg. Cemented v sks Class H id not circ.cmt. WC 50'. Tested BOPE	ubsequent reports shall be a new interval, a Form 316 on, have been completed, vith 600 sks DC, Slow E to 3000#	filed within 30 days 60-4 shall be filed once	
Chart & schematic atta	ached.					
Bond on file: NM1693	nationwide & NMB000919					
14. I hereby certify that the for	Electronic Submission For MEWB	#219591 verified by the I OURNE OIL COMPANY, r processing by JOHNN)	sent to the Hobbs	-		
Name(Printed/Typed) JA		· • 1	AUTHORIZED RE	0		
Signature (El	ectronic Submission)	Date	09/10/2013	ACCEPTED I	OR RECORD	
	THIS SPACE I	FOR FEDERAL OR S	TATE OFFICE U	JSE		
Approved By		Title		SEP 2	1 Die hoad	
Conditions of approval, if any, and	e attached. Approval of this notice do gal or equitable title to those rights in to conduct operations thereon.		-, -, -, -, -, -, -, -, -, -, -, -, -, -	BUEZAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE		
Title 18 U.S.C. Section 1001 and	Title 43 S.C. Section 1212, more in autulen samments or representations	a crime for any person know as to any nearer within its jur	ingly and willfully to n isdiction.	/		
** 0	PERATOR-SUBMITTED **	OPERATOR-SUBMI	TED ** OPERA	TOR-SUBMITTED	**	

•

۰.

SEP 26 20131

US d	WELDING • BOP TESTING WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS Lovington, NM • 575-398-4540 Pg of						
	ase: Wildrat ZIL						
					tor: Trinidad Rig # 110 Tester: Ulisr's Marlinir		
	equired BOP: 36						
	ppropriate Casing Valve Must Be Open Dur				Check Valve Must Be Open/Disabled To Test Kill Line Valve	ves *	
0	Annular #15 Pipe Rams #12 Blind Rams #13 H11 #10 #9 #7 Pipe Rams #14 Casing	#26 #2 #4 #4 #3 #3 #3 #1 #25 Super C	#5 #5 #88 Mud Gaug Valve		(BOP 2 Valve		
	TEST # ITEMS TESTE	D TEST LENGTH	LOW PSI	HIGH PSI	SI REMARKS	٦	
	1 Unit Pumps	#119 10/10	250	3000	c good.		
	2 Pipettn, 9	7 101-	250	3000	C Pipe Ram door leaked reads gas	set	
	3 13,9,4,5	3 10/10	250	3000	a good		
	4 13, 10, 2, 1,	5 10/10	2.50	3000	c 2000		
	\$ 13, 10, 26,5	-,25 Buing TEst		3000	good Manualchokes	_	
	6 13, 11, 28, 5	-, 27 10/10	250	3000	0000	4	
ļ	7 12, 11, 7	10/14		3000	9000	-	
ļ	8 12, 11, 8	10/10	750	3000		4	
ļ	9 Hydrill #K,		250	1500		Close	
ŀ	10 Hydrill#15,	11,8 10/10	210	1500	3000	4	
ł						-	
ŀ						-	
ŀ						-	
ŀ						4	
ł						-	
1				1			
ŀ						-	
ŀ						-	
1		1				1	

MAN WELDING "SERVICES, INC						
	MAR	ANC.				
Compa	my Mewbourne Oil Company	Date9-1/3				
Lease_	Wildeat 71 LI Fed Com 111	County Lea, NM				
Drillin	g Contractor Trinidad 110	Plug & Drill Pipe Size// <sup>#</sup> 3//z T F				
To Ch o o	eck - USABLE FLUID IN THE NITRO Make sure all rams and annular are open a Ensure accumulator is pumped up to work	and if applicable HCR is closed.				
	<b>Record remaining pressure</b> $1/3\infty$ <b>4 (950</b> psi for a 1500 psi system) 7. If annular is closed open it at this time	<ul> <li>chieve the 50+ % safety factor. (5M and greater systems).</li> <li>psi. Test Fails if pressure is lower than required.</li> <li>b. {1200 psi for a 2000 &amp; 3000 psi system }</li> </ul>				
To Che	ck - PRECHARGE ON BOTTLES OR	SPHERICAL (III.A.2.d.)				

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure: a. (800 psi for a 1500, psi system) b. (1100 psi for 2000 and 3000 psi system)
- 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)


ŝ

- 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
- 3. Record pressure drop <u>1/00</u> psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}

## To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
  - 1. Open the HCR valve, {if applicable}
  - 2. Close annular
  - 3. With **pumps** only, time how long it takes to regain the required manifold pressure.
  - 4. Record elapsed time 1.0F. 22. Test fails if it takes over 2 minutes.
    - a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system)
- 0

6



.

